Date: October 21, 2015

To: Senator Kay Wolf and members of the Joint Committee on State Building Construction

From: Lori Hart, Interim General Manager, Kansas State Fair

Re: Kansas State Fair - Capital Improvement Projects and Priorities

Overview: The Kansas State Fair employs 25 full-time year round staff and approximately 550 temporary, part-time employees during the annual Kansas State Fair. Throughout the year the staff is charged with hosting over 500 non-fair events, maintaining 280 acres with over 70 structures. We are funded through the fees our agency generates with a majority of those revenues received during the Fair. The Kansas State Fair maintains a preventative maintenance plan that evaluates each building in regards to general upkeep, major improvements and future uses. The State's match to the capital improvement fund is vital to the continued success of the Kansas State Fair. Attached is the history of the State Fair and Funds from the State to the Capital Improvements Fund.

To assist us with our planning, the Kansas State Fair has hired a consulting firm, Keefer/Overton to assist with the development of a facilities master plan, scheduled to be presented in spring of 2016.

Current and Completed Projects from the Capital Improvements Fund:

- 1. Refurbished outside of the Eisenhower Building
- 2. Refurbished the exterior of the Boy and Girl Scout Buildings at Lake Talbott
- 3. Fans added to the 4-H Centennial Hall
- 4. Continue much needed asphalt repairs
- 5. Improved parking lot security lighting
- 6. Landscape development and beautification of the grounds
- 7. Enlarged the drive through gate at entrance 10.
- 8. Domestic Arts outside brick tuck pointing

Buildings renovated or constructed during the Master Plan in the early 2000's are now at an age when repairs and upkeep are essential.

Priorities:

Expo Center (1964) Horse/Equine

The Expo Center has hosted an average of 38 non-fair events resulting in 150 days of usage above and beyond the ten days of the Kansas State Fair.

- 1. Roof replacement
- 2. Moisture and corrosion issues related to anchor bolts, baseplates, columns, wall girts and roof purlins.
- 3. Restrooms

Attached is the Structural Review provided by Engineering Consultants in 2013 and provided to this committee last October

Recommended Action: Replacement of structure. Attached are project quotes from Wiens & Company for replacement of the Expo Center dated 2013 and provided to this committee in 2014.

Attachment 36 TCSBC 10-21-15





Recommended Action: Replacement of structure. Attached are project quotes from Wiens & Company for replacement of the Expo Center dated 2013 and provided to this committee in 2014.

Bison Arena: (1937) 4-H Dog show/Miniature Horse/Sheep Dog Trials/Antique Tractor Pull Also known in the early days as the 4-H Livestock Arena, Grand building.

- 1. Fire Marshall requests Emergency Exit Doors: Currently utilizing overhead doors in Bison Arena and are not approved emergency exits.
- 2. Fire Sprinkling and Fire Alarm System
- 3. New Roof

Recommended Action: Kansas State Fair to work with the Fire Marshall to review timeline as it relates to the Master Plan recommendation and future use of the facility. Otherwise we will need to make the emergency exit door improvements by the 2016 Fair at an estimated cost of \$116,060 or find alternative locations or cancel the activities held in Bison Arena.





State Fair Capital Improvement Fund Matching History

The State Fair Capital Improvements and Maintenance Fund was authorized by K.S.A. 2-223 in 1988.

On June 30, 1989, and each year succeeding June 30, the Fair is to contribute at least (5) percent from its qualified receipts to maintain and generate further balances in the Fund. On July 1, 1989, and each succeeding July 1, the State of Kansas will transfer an amount equal to that contributed by the Fair, but not to exceed \$300,00 in any one annual, single fiscal year.

Fiscal Year	State Fair Contribution	State Contribution	Amount State Yet to Match
1989	\$87,551	N/A	
1990	Exempt	\$87,551	
1991	\$149,779	Exempt	
1992	\$107,927	\$149,779	
1993	\$117,016	\$107,927	
1994	\$145,657	\$117,016	
1995	\$153,164	\$145,657	
1996	\$196,882	\$153,164	
1997	\$113,168	\$196,882	
1998	\$260,000	\$113,168	
1999	\$300,000	\$260,000	
2000	\$300,000	\$300,000	
2001	\$300,000	\$300,000	
2002	\$158,000	No Match Made	\$300,000
2003	\$243,000	\$294,000 (\$158,000 to	\$300,000
		match: additional for	
		storm damage repair)	
2004	\$300,000	No Match Made	\$543,000
2005	\$200,000	No Match Made	\$843,000
2006	\$25,000	\$200,000	\$843,000
2007	\$300,000	\$25,000	\$843,000
2008	\$300,000	\$300,000	\$843,000
2009	\$200,000	\$300,000	\$843,000
2010	\$300,000	No Match Made	\$1,043,000
2011	\$350,000 - \$300,000 budgeted by KSF; \$50,000 added from Fee Fund by the Division of Budget	No Match Made	\$1,343,000
2012	\$350,000 - \$300,000 budgeted by KSF; \$50,000 added from Fee Fund by the Division of Budget	\$159,207\$	\$1,483,793
2013	\$250,000	\$400,000	\$1,383,793
2014	\$300,000	\$250,000	\$1,383,793
2015	\$300,000	\$400,000	\$1,283,793
2016	\$300,000 budgeted	\$100,000	\$1,483,793



May 30, 2013

Mr. Keith Schroeder Physical Plant Manager Kansas State Fair 2000 North Poplar Hutchinson, KS 67502

Re:

Kansas State Fair Expo Center - Structural Review

2000 North Poplar - Hutchinson, KS

EC Project Number: 13-069

Dear Mr. Schroeder.

On April 23rd, 2013, Engineering Consultants, PA reviewed the structural condition of the Expo Center building on the Kansas State Fairgrounds at 2000 North Poplar Street in Hutchinson, KS. This evaluation, sought by the Kansas State Fair, was intended to evaluate the condition of the pre-engineered metal building (PEMB) structure, in particular the corrosion that is visible in the PEMB components, and to render an opinion on the condition of the building and whether it is prudent to invest significant money into building renovations. Brent L. Engelland, P.E., S.E., LEED® AP, along with D. Kelly McMurphy of Landmark Architects and Engineers performed the evaluation. The structure was viewed from the interior and exterior and digital photographs were taken. No materials testing or evaluation, nor structural analysis, was completed as part of this scope of work.

KSF Expo Building - Observations:

- The structure is a three bay PEMB with primary frames running east-west. The center bay is a clear-span over the livestock arena and there are two small "leanto" bays east and west of the clear-span. The east and west bays have concrete slab flooring while the majority of the arena is a dirt floor. Per KSF personnel, the majority of the building previously had a dirt floor and livestock pens along the east and west sides.
- The building has a history of corrosion at the baseplate level due to the moisture and manure associated with livestock. There are a number of main frames which have repaired baseplates due to an apparent near failure of a primary frame that had released from its anchor bolts due to corrosion.
- Moisture and corrosion continue to be an issue in the building as anchor bolts, baseplates, columns, and secondary PEMB framing (light gauge wall girts and roof purlins) continue to show signs of corrosion.
- The primary focus of the structural review was the condition of the baseplates and anchor bolts for the PEMB structure. All of the baseplates and anchor bolts were reviewed and their condition was documented (a plan of the anchor bolts and notes regarding their condition are attached). The vast majority of these anchor bolt/baseplate conditions are showing rust of some degree.
- One of the most prevalent and most concerning aspects of the corrosion at the base of the structure is the corrosion of the anchor bolt nuts. In some of the

514 West First Avenue, P.O. 932 Hutchinson, KS – 67501 620-665-6394 (ph) 620-665-0218 (fax)



cases the nuts have rusted completely off and in a majority of the cases the nuts are showing rust and severe corrosion. For the main frame baseplates (column lines B and C on the attached diagram) over ½ of the locations have rusted off anchor bolts. When heavy rust of the baseplate is included, the number of severely corroded anchor bolt/baseplates on the primary frame columns jumps to 65%.

- The outer bays of the structure (column lines A to B and C to D on the attached diagram) still have dirt floors in most locations. A majority of these column bases have heavy rust on the structural steel column and baseplate or on the anchor bolts.
- In addition to the base conditions of the frames, a number of areas of roof purlins were spot-checked via a man-lift to verify the condition of the roof purlins. It was discovered during this review that there are a number of areas of roof leaks. In these areas the insulation was soaked and the leaks have lead to corrosion of the light-gauge roof purlins.
- The dimensions and gauge of the purlins was verified so that the capacity of the purlins could be determined. Through the structural calculations using the field collected data, it was determined that the live load capacity of the roof purlins is 20 psf if the purlins are made from at least 55 ksi yield strength material. If the purlins are made from only 33 ksi yield strength material then the allowable live load drops to 14 psf. The building code required minimum roof live load is 20 psf. This means that the purlins are either designed right at the allowable load, or are below the required Code loading, depending on the material used. Since materials testing was outside of the scope of this investigation no further conclusions can be drawn.

KSF Expo Building - Conclusions:

- The condition of the existing baseplates, anchor bolts, and anchor bolt nuts is a serious concern on this building. The numerous locations where the anchor bolt nuts have rusted away completely impacts the structural integrity of the building. Without the anchor bolt nuts in place and tight, the structure has no ability to resist uplift loads in a high wind event.
- Additionally, the corrosion at the anchor bolts and baseplates also impacts the structural integrity of the building, in particular the ability of the foundations to resist the outward thrust that results from the clearspan center section. The center arches must be adequately connected to a foundation that is capable of resisting the arch thrust and the connection of the baseplate and anchor bolts is how the structure achieves this.
- The condition of the roof purlins is also a concern for the building structure. The
 wet insulation is likely leading to additional corrosion on the top flange of the
 purlins that is currently not visible.

KSF Expo Building – Recommendations:

 All of the corroded anchor bolts, baseplates, and anchor bolt nuts need to be repaired or replaced. The process to achieve this will be challenging as the corrosion of the anchor bolt nuts is likely to have left many of the anchor bolt

514 West First Avenue, P.O. 932 Hutchinson, KS – 67501 620-665-6394 (ph) 620-665-0218 (fax)



threads in a condition that will not accept a new nut without extensive cleaning and possibly chasing the threads with a thread cutting tool to re-form them (this may not even be possible given the limited clearances).

- If the anchor bolt threads will not accept new nuts, or if the anchor bolts are
 corroded and have lost cross-sectional area, then new adhesive anchor bolts will
 need to be installed. If the baseplates are not corroded then the new anchor
 bolts may be able to be installed adjacent to the existing anchor bolts. However,
 many of the frames also have corroded baseplates that will require replacement.
- The corroded roof purlins should be replaced with new members. During this process the remainder of the roof purlins should be reviewed to locate additional areas of corrosion. We estimate that a minimum of 10% of the roof purlins in the structure will need to be replaced as a result of corrosion. If the structure is desired to be saved and renovated, the purlin replacement would be most easily accomplished when the roofing panels and insulation are removed.
- As a result of this study, we recommend that any plans to renovate and/or improve the existing structure should first include a fiscal analysis that takes into account the necessary repairs of the existing structure. This fiscal study should be completed prior to any other planning work to determine the costeffectiveness of keeping, repairing, and renovating the existing structure, versus demolition and constructing a new structure. As a point of reference for that study, we estimate that the repair costs for a single location of anchor bolt cleaning, re-threading, and repair would be around \$3,500. The more simple clearing and minor repairs of baseplates could be around \$1,000 each. If it is assumed that 20 locations require the full cleaning or repair, and 25 more require just the simple level of repair, the costs for just the anchor bolts and baseplates could easily exceed \$95,000 to \$100,000. We also estimate that at least 10% of the roof purlins will need to be replaced and that number could easily climb to 30% or more once the saturated insulation is removed and the corrosion on top of the purlins is visible. When the costs for a new roof are estimated these purlin costs should also be included to get an accurate estimate.

We have been pleased to be of service to you in this matter. Please do not hesitate to call with questions or comments.

Sincerely,

ENGINEERING CONSULTANTS, P.A.

Brent L. Engelland, P.E., S.E., LEED® AP

Attachments


Photos

Structural Review Diagram


514 West First Avenue, P.O. 932 Hutchinson, KS – 67501 620-665-6394 (ph) 620-665-0218 (fax)



Typical view of corroded base condition




Detail view of corroded anchor bolt nuts




514 West First Avenue, P.O. 932 Hutchinson, KS – 67501 620-665-6394 (ph) 620-665-0218 (fax)



Typical view of saturated insulation and corroded roof purlin



Detail view of corroded roof purlin




514 West First Avenue, P.O. 932 Hutchinson, KS – 67501


620-665-6394 (ph) 620-665-0218 (fax)




Detail of roof leak and corroded roof purlin



View of Previously Repaired Baseplate



514 West First Avenue, P.O. 932 Hutchinson, KS – 67501 620-665-6394 (ph) 620-665-0218 (fax)



Mr. Keith Schroeder Director of Maintenance Kansas State Fair 2000 N. Poplar Hutchinson, KS 67502 WIENS & COMPANY

219 N. Whiteside, P. O. Box 490 Hufchinson, K\$ 67504-0490 620-665-1155 / Fax 620-665-0911

Re; Kansas State Fair Expo Building
Budget for Replacement of the Expo Building

Dear Keith,

After my submission of our budget for the foundation repair at the Expo Building, you requested that I do a work-up of a budget to replace the building. Accordingly, I am suggesting a budget that includes work described below.

Please note that a budget projection based on my assumptions, multiplied by many variables, can only produce a number that is imprecise, ambiguous, nebulous, and vague at best!

Project Description:

The project would include demolition of the existing Expo Building, replacement with a building of similar size (65,000 SF), but improved features. The description below is a skeletal in nature, with many details to be determined.

General Conditions

Supervision; Temporary connections & services; Equipment & Vehicles

Site Work

- Complete demolition & removal of the Existing Building
- · Site preparation for the new structure
- Site utilities; Temporary protections; Site improvements

Concrete

- · Footings as required, with reinforcement
- Stem-walls & piers to provide a building bearing elevation raised 4' above grade
- Floors: 5" floors at approximately ½ of the building; Remainder to be dirt floor in arena
- Miscellaneous site paving & walks

Masonry

- CMU walls at restrooms & kitchen area with pre-cast structure above for storm protection
- Minimal brick accents

Steel

Misc. Steel fabrications allowed

Pre-Engineered Metal Building

Clear-span structure; Standing seam roof; Insulated roof

Carpentry

Misc. Cabinetry & counters

Openings

- Storefront at main entries
- Steel doors elsewhere
- · Overhead doors allowed
- Basic louvers

Finishes

- · Misc. Drywall assemblies allowed
- Misc. Painting allowed
- Misc. Ceiling allowed
- Allowance for tile at restrooms

Specialties

· Toilet partitions allowed

Equipment

· Budget for Kitchen Exhaust Hood packages

Plumbing

- Approximately 50 toilets / urinals
- · "Gang" wash stations at restrooms
- · Fixtures at kitchen, utility, etc.
- · Water sources throughout building

HVAC

- · Heating & A/C at restrooms, kitchen, eating area
- Exhaust systems at main area
- Space heaters or radiant heaters at main area
- Air movers

Electrical

Service, Power & Lighting

Take Vim

Not Included

- Utility charges
- Furnishings; Loose fixtures; Signage
- · Equipment: bleachers; stalls; arena fencing; etc.
- Sales Taxes

I projected a budget range \$4,750,000 to \$5,550,000. See the attached worksheets for further reference. Again, please understand that these figures are very loose and subject to many variables, including Architectural & Engineering considerations that I may not have anticipated.

Thank you for the opportunity to be of service. If I can answer any questions, please call.

Yours Truly,

Sid Wiens

36-12

KS Stat	te Fair - Expo Building Replac	ement			65,000	SF		
			Formula	as		\$ / Line	<u>%</u>	\$/SF
1110	Administration	65000	\$0.50	1	1	32,500	0.6%	0.50
1200	Supervision	65000	\$0.75	1	1	48,750	0.9%	0.75
1140	Temporary Services	65000	\$0.30	1	1	19,500	0.4%	0.30
1410	Fuel / Milage	65000	\$0.30	1	1	19,500	0.4%	0.30
	Equipment Rental	65000	\$1.75	1	1	113,750	2.0%	1.75
	Dumpster & Cleanup	65000	\$0.30	1	1			
	Warrantee	65000	\$0.30	1	1	19,500 9,750	0.4% 0.2%	0.30
			(B)(F)(C)(B)			0,1.00	0.270	0.10
	Survey / Layout	65000	\$0.30	1	1	19,500	0.4%	0.30
	Demolition	65000	\$3.00	1	1	195,000	3.5%	3.00
2310	Site Prep	65000	\$5.00	1	1	325,000	5.9%	5.00
	Temporary Protections	65000	\$0.15	1	1	9,750	0.2%	0.15
	Site Utilities	65000	\$0.75	1	1	48,750	0.9%	0.75
2510	Permanent Site Improvements	65000	\$0.20	1	1	13,000	0.2%	0.20
3110	Footings	65000	\$3.50	1	1	227,500	4.1%	3.50
	Concrete Walls & Peirs	65000	\$3.50	1	1	227,500		
	Precast Concrete	65000	\$0.50	1	1		4.1%	3.50
	Floors					32,500	0.6%	0.50
100000000000000000000000000000000000000	Paving	65000	\$4.00	0.5	1	130,000	2.3%	2.00
	0	65000	\$0.50	1	1	32,500	0.6%	0.50
	Curb & Gutter	65000	\$0.25	1	1	16,250	0.3%	0.25
	Sidewalks	65000	\$0.35	1	1	22,750	0.4%	0.35
3610	Stairs & Odd Construction	65000	\$0.25	1	1	16,250	0.3%	0.25
4110	Masonry	65000	\$1.50	1	1	97,500	1.8%	1.50
5110	Rebar	65000	\$1.25	1	1	04.050	4.50/	4.05
	Structural Steel					81,250	1.5%	1.25
		65000	\$0.75	1	1	48,750	0.9%	0.75
	Pre-Engineered Metal Buildings		\$17.50	1	1	1,137,500	20.5%	17.50
5/10	Metal Specialties	65000	\$0.25	1	1	16,250	0.3%	0.25
6100	Rough Wood Carpentry	65000	\$0.10	1	1	6,500	0.1%	0.10
	Finish Carpentry	65000	\$0.15	1	1	9,750	0.1%	0.10
	5. * New Architecture & Carry & Charles & Ch.					0,700	0.270	0.15
7910	Caulking & Firesafing	65000	\$0.15	1	1	9,750	0.2%	0.15
	Storefront	65000	\$0.60	1	1	39,000	0.7%	0.60
	Overhead Doors	65000	\$0.50	1	1	32,500	0.6%	0.50
8310	Doors & Hardware	65000	\$0.75	1	1	48,750	0.9%	0.75
0105	Metal Stud Framing	65000	60.40			6.500	0.404	0.40
	Drywall		\$0.10	1	1	6,500	0.1%	0.10
		65000	\$0.15	1	1	9,750	0.2%	0.15
	Painting	65000	\$0.30	1	1	19,500	0.4%	0.30
	Ceilings	65000	\$0.25	1	1	16,250	0.3%	0.25
9510	Flooring	65000	\$1.25	1	1	81,250	1.5%	1.25
10110	Specialties	65000	\$0.75	1	1	48,750	0.9%	0.75
11210	Equipment: Kitchen, Bank, etc	65000	\$1.00	1	1	65,000	1.2%	1.00
15100	Plumbing	65000	\$4.00	1	1	200,000	4 70/	4.00
	Fire Sprinklers		\$4.00		1	260,000	4.7%	4.00
		65000	\$2.00	1	1	130,000	2.3%	2.00
15500	HVAC	65000	\$4.00	1	1	260,000	4.7%	4.00
16100	Electrical	65000	\$7.50	1	1	487,500	8.8%	7.50
	Subtotal					4,491,500		
	Contractor's Fee				5.0%	224,575	4.0%	2 46
	Budget Contingency Allowance				10.0%	449,150		3.46
	badget Contingency Allowance				10.076	449,150	8.1%	6.91
	Subtotal					p .a		
	Subtotal				2 525	5,165,225	le lattare	
	Bonds & Insurance				1.5%	77,478	1.4%	1.19
	Architect / Engineering Fee				6.0%	309,914	5.6%	4.77
	Total Budget estimate	Cost Per Foo	otprint SF		85.42	5,552,617		

KS State Fair - Expo Building Replaceme	nt			65,000	SF		
		Formulas			\$ / Line	<u>%</u>	\$/SF
1110 Administration	65000	\$0.50	1	1	22 500	0.7%	0.50
1200 Supervision	65000	\$0.75	1	1	32,500 48,750	1.0%	0.50
1140 Temporary Services	65000	\$0.70	1	1	19,500	0.4%	0.73
1410 Fuel / Milage	65000	\$0.30	1	1	19,500	0.4%	0.30
1510 Equipment Rental	65000	\$1.75	1	1	113,750	2.4%	1.75
1610 Dumpster & Cleanup	65000	\$0.30	1	1	19,500	0.4%	0.30
1630 Warrantee	65000	\$0.15	1	1	9,750	0.2%	0.15
2210 Survey / Layout	65000	\$0.30	1	1	19,500	0.4%	0.30
2220 Demolition	65000	\$3.00	1	1	195,000	4.1%	3.00
2310 Site Prep	65000	\$5.00	1	1	325,000	6.8%	5.00
2410 Temporary Protections	65000	\$0.15	1	1	9,750	0.2%	0.15
2420 Site Utilities	65000	\$0.75	1	1	48,750	1.0%	0.75
2510 Permanent Site Improvements	65000	\$0.20	1	1	13,000	0.3%	0.20
3110 Footings	65000	\$3.50	1	1	227,500	4.8%	3.50
3210 Concrete Walls & Peirs	65000	\$3.50	1	0.43	97,825	2.1%	1.51
3310 Precast Concrete	65000	\$0.50	1	0	01,020	2	
3510 Floors	65000	\$4.00	0.5	1	130,000	2.7%	2.00
3520 Paving	65000	\$0.50	1	1	32,500	0.7%	0.50
3530 Curb & Gutter	65000	\$0.25	1	1	16,250	0.3%	0.25
3540 Sidewalks	65000	\$0.35	1	1	22,750	0.5%	0.35
3610 Stairs & Odd Construction	65000	\$0.25	1	1	16,250	0.3%	0.25
4110 Masonry	65000	\$1.50	1	0.5	48,750	1.0%	0.75
5140 B. I	05000	04.05		4	04.050	4 70/	4.05
5110 Rebar	65000	\$1.25	1	1	81,250	1.7%	1.25
5210 Structural Steel	65000	\$0.75	1	1	48,750	1.0%	0.75
5250 Pre-Engineered Metal Buildings 5710 Metal Specialties	65000 65000	\$17.50 \$0.25	1 1	0.8571 1	975,000 16,250	20.5% 0.3%	15.00 0.25
0400 D 10	05000	00.40			0.500	0.404	0.40
6100 Rough Wood Carpentry 6510 Finish Carpentry	65000 65000	\$0.10 \$0.15	1	1 1	6,500 9,750	0.1%	0.10 0.15
7910 Caulking & Firesafing	65000	\$0.15	1	1	9,750	0.2%	0.15
8130 Storefront	65000	\$0.60	1	1	39,000	0.8%	0.60
8210 Overhead Doors	65000	\$0.50	1	1	32,500	0.7%	0.50
8310 Doors & Hardware	65000	\$0.75	1	1	48,750	1.0%	0.75
9105 Metal Stud Framing	65000	\$0.10	1	1	6,500	0.1%	0.10
9110 Drywall	65000	\$0.15	1	1	9,750	0.2%	0.15
9210 Painting	65000	\$0.30	1	1	19,500	0.4%	0.30
9410 Ceilings	65000	\$0.25	1	1	16,250	0.3%	0.25
9510 Flooring	65000	\$1.25	1	0.6	48,750	1.0%	0.75
10110 Specialties	65000	\$0.75	1	1	48,750	1.0%	0.75
11210 Equipment: Kitchen, Bank, etc	65000	\$0.75	1	0			
15100 Plumbing	65000	\$4.00	1	0.875	227,500	4.8%	3.50
15300 Fire Sprinklers	65000	\$2.00	1	1	130,000	2.7%	2.00
15500 HVAC	65000	\$4.00	1	0.8125	211,250	4.4%	3.25
16100 Electrical	65000	\$7.50	1	0.8	390,000	8.2%	6.00
16100 Electrical	65000	\$7.50	1	0.8	390,000	8.2%	6.00
Subtotal					3,841,825	-85-65992	(2002)20
Contractor's Fee				5.0%	192,091	4.0%	2.96
Budget Contingency Allowance				10.0%	384,183	8.1%	5.91
Subtotal					4,418,099		
Bonds & Insurance				1.5%	66,271	1.4%	1.02
Architect / Engineering Fee				6.0%	265,086	5.6%	4.08
Total Budget estimate Co	st Per Foo	otprint SF		73.07	4,749,456		

Five-Year Capital Budget Plan--DA 418A Division of the Budget State of Kansas

Agency Name Kansas State Fair

*	Estimated		Current Year			100 May			Subsequent
Project Title	Project Cost	Prior Years	FY 2016	FY 2017	FY 2018	FY 2019	FY 2020	FY 2021	Years
State Fair Capital Improvement Fund 1. Capital Maintenance & Repair	2,005,000	125,000	200,000 50,430	280,000	280,000	280,000	280,000	280,000	280,000
Master Plan Study Bison Arena Emergency Exit Doors Eisenhower Building Exterior Replacement	50,430 116,060		100,000	116,060	7				
Asphalt Repairs Bison Arena Sprinkler/Alarm/Re-roof/Windows	300,000 1,381,555	20,000	40,000	40,000	40,000	40,000 1,381,555	40,000	40,000	40,000
7. Expo Center Replacement 8. Pride of Kansas Building Roof Replacement 9. Bison Arena Renovation	5,552,617 216,000 7,004,000				216,000		5,552,617	7,004,000	
9. DISOTI ATERIA RERIOVATION	,,,,,,,,,,,,	1	4						
Bond Payments 1. Bond Payment - State General Fund	35,498,783	9,435,250	845,950	848,550	850,150	855,750	848,750	850,500	
State Appropriations 1. EDIF 2. SGF Appropriation to the SFCIF	2,100,000	400,000	100,000	100,000	300,000	300,000	300,000	300,000	300,000
2. Sal Appropriation to the siles.			, ,						
*		0 000 050	1 226 200	1 204 610	1 606 150	2,857,305	7,021,367	8,474,500	620,000
Total	54,224,445	9,980,250	1,336,380	1,384,610	1,686,150	2,637,303	7,021,307	3,474,500	020,000

1. Project Title:	Capital Maintenanc	e & Repair			2. Project Priority:	SFCIF #1		
Agency:	Kansas State Fair							
3. Project Description								
	These projects are n	s are funded by the Sta ecessary to maintain th						
1. Maintenance	Contract Expenditure	S						
annual cost is us to utilize a	approximately \$55,0	rical company for election of the contracting through the limited time p	gh the Division of Pu	urchasing is cost effe	ctive for this agency	as it allows		
2. Misc & Cont	ingency Repairs							
accommodate a) F b) F	e Fair patrons, or a not raint, lumber, concrete IVAC repair and/or re	nnually for repairs and n-fair event. Some of e, and steel for repair o eplacement. Parts are to the Fair is replacing so	the items include: f structures 10 longer available f	or some of the units	in the buildings that			
4. Estimated Project	Cost			5. Project Phasing:				
1. Construction (ir				Preliminary pl	ans (including			
equipment and	A STATE OF THE STA			misc. costs)				
2. Architect or eng				2. Final plans (in	cluding misc.			
3. Moveable equip	oment			and other cost	ts)			
4. Project conting	ency		2,005,000	3. Construction	including misc.		*	
5. Miscellaneous	costs			and other cos	ts)			
		Total	\$ 2,005,000		Tota	ı ş		
6. Amount by Source	of Financing			<u> </u>				
and and and and	1				l .	1		
Fiscal Years	1. SGF	2. SFCIF Fund	3. Fund	4.	5.	Total		
Prior Years		125,000			-	125,000	1	-
FY 2016		200,000				200,000		
FY 2017		280,000				280,000]	
FY 2018		280,000				280,000]	
FY 2019		280,000				280,000),430
FY 2020		280,000				280,000]	
FY 2021		280,000				280,000	1	
Subsequent Years		280,000				280,000		
Total	\$	2,005,000	\$	\$	\$	2,005,000]	
),430

17

1. Project Title	Bison Arena Emerg	gency Exits			2. Project Priority:	SGF #3
Agency:	Kansas State Fair					
3. Project Desc	cription and Justific	ation:				
	to install emergen	om the Office of the cy exit doors in Bisc hich are not appro	on Arena. Current	entrance/exiting is		
	Bison Arena has se Fair's campus.	erved a variety of pu	urposes over its life	e and is still an imp	ortant part of the	
						1
						Ì
						* .
		3				1
						98KK W
4. Estimated Pro	piect Cost:			5. Project Phasing:		
	on (including fixed		96,660	1. Preliminary pla	ins (including	
	t and sitework)			misc. costs)		
20, 20	or engineer fee		9,700	2. Final plans (inc	luding misc.	
3. Moveable				and other costs		-
4. Project co			9,700	3. Construction (i	75	
5. Miscellane			0	and other costs		
					35.	
		Total	\$ 116,060		Total	\$
6. Amount by S	ource of Financing:					
Fiscal Years	1. SGF	2. SFCIFund	3. Federal Funds	4.	5.	Total
Prior Years						
FY 2016						
FY 2017		116,060	6, 1			116,060
FY 2018						
FY 2019						
FY 2020			and the second second	incerior and a second	8	
FY 2021						
Subsequent Ye	ars Le	116.060	ć	è	è	116.060

1. Project Title:	Eisenhower Building Exteriors 2. Project Priority: SFCIF #4							
Agency:	Kansas State Fai	r			120			
	on and Justification							
s. Project Descripti	The Eisenhov Kansas Depa This building replacement	ver Building is used to rtment of Wildlife, Pa was constructed in 1	arks and Tourism. 980 and has not b some exterior wor	oeen renova	nercial exhibits as well ted since other than a tion of the building oc	roof		
		is located in the hear d of an upgrade.	t of the Fairgrour	nds and is hig	ghly visible. The exter	ior is dated		
		of the submission of t lans and a cost estim		air's on-call a	architect is in the proc	cess of		
			8			e.		
4. Estimated Proje	ct Cost:	# - 12		5. Project I	Phasing:			
1. Construction	(including fixed			1. Prelir	minary plans (including			
equipment ar	nd sitework)			misc.	costs)			
2. Architect or e	engineer fee			2. Final	plans (including misc.			
3. Moveable eq	uipment			and o	ther costs)			
4. Project conti	ngency			3. Cons	onstruction (including misc.			
5. Miscellaneou	s costs			and o	ther costs)			
		То	tal \$	177		Total \$		
6. Amount by Sour	rce of Financing:							
Fiscal Years	1. SGF	2. SFCIF Fund	3 Fund	4.	5.	Total		
Prior Years								
FY 2016								
FY 2017								
FY 2018								
FY 2019								
FY 2020								
FY 2021								
Subsequent Years						1000		
Total	\$	\$	\$	\$	\$	\$		

Project Title:	Asphalt Repairs	5			2. Project Priority:	SFCIF #5		
	AND NEW W. NE	w.					1	
Agency:	Kansas State Fa		90					
3. Project Description	n and Justification	n:						
			540					
		×		*				
The V	ancac Stata Fa	irarounde hoe o cian	ificant number of	fueede.e end	onbalt areas			
		irgrounds has a sign ous. Ongoing mainte			•			
	T//:	n for vehicle traffic a			1070			
accep	table conditio	ii ioi veilicle traffic a	iliu to avoiu trip	nazarus for peut	estrian trainc.		* 1	
					*0			
						iš		
4. Estimated Project	Cost			5. Project Phasing:				
1. Construction (i			40,000	Preliminary pl	ans lincluding			
equipment and			40,000	misc. costs)	ans (meraanig			
2. Architect or en				2. Final plans (including misc.				
3. Moveable equi				and other costs)				
4. Project conting				3. Construction			1	
5. Miscellaneous				and other cos			1	
		Tota	\$ 40,000		Tota			
		Tota	3 40,000		TOTA	9		
6. Amount by Source	e of Financing:			L				
	1					T		
Fiscal Years	1. SGF	2. SFCIF	3. Federal Funds	4.	5.	Total		
Prior Years		20,000		1023	-	20,0	000	
FY 2016		40,000				40,0		
FY 2017		40,000				40,0	-	
FY 2018		40,000				40,0		
FY 2019		40,000				40,0	000	
FY 2020		40,000				40,	000	
FY 2021		40,000				40,	000	
Subsequent Years		40,000				40,	000	
Total	\$	300,000	\$	\$	\$	300,	000	

 Project Tit 	tle Bison Arena Emergency Exits	2. Project Priority: SGF #6
	0-11-7	
Agency:	Kansas State Fair	

3. Project Description and Justification:

Under direction from the Office of the State Fire Marshal, the Kansas State Fair is exploring the installation of a fire sprinkler system and fire alarm system.

To ensure a properly functioning fire alarm and sprinkler system, the Agency would first need to address issues related to leaks with Bison Arena's roof and upper-story windows. Without addressing these first, there is the possibility of water damage and impacting the functionality of the alarm and sprinkler systems.

Bison Arena has served a variety of purposes over its life and is still an important part of the Fair's campus.

4. Estimated F	Project Cost:			5. Project Phasing:			
1. Construc	ction (including fixed ent and sitework)		96,660	1. Preliminary pla misc. costs)	ns (including		
	t or engineer fee		9,700	2. Final plans (inc	luding misc.		
3. Moveab	le equipment			and other costs	5)		
4. Project o	contingency		9,700	3. Construction (i	ncluding misc.		
5. Miscella	neous costs		0	and other costs	5)		
		Total	\$ 116,060			Total	\$
6. Amount by	Source of Financing:	T	T				
Fiscal Years	1. SGF	2. SFCIFund	3. Federal Funds	4.	5.	1	Γotal
Prior Years							
FY 2016							
FY 2017		116,060	1000 CO				116,060
FY 2018		3				7	
FY 2019							
FY 2020							
FY 2021							
Subsequent Y	'ears						
Total	\$	116,060	\$	\$	\$		116,060

1. Project Title:	Expo Center			Ŧ	2. Project Priority	SFCIF #7	
Agency:	Kansas State Fair		2017				
3. Project Descript	ion and Justificatior	ι.,					
9.							
	The Expo Center i						
					ne annual State Fair,		
	it was utilized for	37 events over 13	35 event days in F	Y 2014.			
	Built in 1964, the	Expo Center is fac	cing the need for s	ignificant renairs	and improvements.		
					replacement. Cost		
	to replace the roo		10	Salie of Mi Systemen			
					xture count also doe	25	
	not meet code re	quirements. Estir	mated cost for the	needed upgrades	is \$349,650.		
	We also employe	d the services of a	structural engine	er to review the r	oof, structural colun	one and	
					erm viability of sust		
						670	
	the existing structure. We have asked a local general contractor to review the engineer's report and provide us an estimate to complete the recommended improvements.						
				THE RESERVE AND CONCUMENTS			
	Based on the exte	ensive repairs req	uired, it is felt a be	etter alternative w	vill be replacement o	of the facility	
	instead of renova	tion of the existin	ng structure. Cons	truction estimate	is based on 2014 do	llars.	
				Ħ		ii ii	
4. Estimated Project	Costs			E Project Phasing		alim una constitution of the constitution of t	
1. Construction (i			4,793,553	5. Project Phasing:			
equipment and		10	4,733,333	Preliminary plans (including misc. costs)			
Architect or en			309,914	2. Final plans (ir	ocluding misc		
3. Moveable equi	7. Table 1981		505,514	and other cos	NAME OF THE OWNER OWNER OF THE OWNER		
4. Project conting			449,150	3. Construction			
5. Miscellaneous	S 25		443,130	and other cos	18 18 18 18 18 18 18 18 18 18 18 18 18 1		
J. Misserianceas					****		
TREE.		Total	\$ 5,552,617		Total	- \$	
6. Amount by Source	e of Financing:	J. Dávis producti a com		Law example of the second			
Fiscal Years	1. SGF	2. SFCIF Fund	3 Fund	4.	5.	Total	
Prior Years							
FY 2016						-	
FY 2017						-	
FY 2018						-	
FY 2019	1000000						
FY 2020	5,552,617					5,552,617	
FY 2021						<u> </u>	
Subsequent Years				 	1	-	

1. Project Title:	Pride of Kansa	s Building Roof	E		2. Project Pric	ority: SFCIF #8	
Agonew	Kansas State F	air					
Agency: 3. Project Descripti							
s. r roject bescripti	on and sustinuatio						
		a					
		*					
he Pride of Kans 314,750.00. The While this repair	sas Building. En work was comp work was satisf	unday, May 24, 2008, mergency repairs were eleted in time for the 2 factory, it addressed or ructed in 1970, and is	e granted by the D 008 State Fair. nly a small portion	ivision of Purch	nases in the an	nount of	
Estimated Proje Construction			216,000	5. Project Phasing			
equipment ar			210,000	1. Preliminary plans (including misc. costs)			
2. Architect or e				15	including misc.		
3. Moveable eq	CO-BONNESS CONTRACTOR	*		and other co			
4. Project conti					n (including misc	2.	
5. Miscellaneou				and other co			
		T-1-	¢ 216 000			T-4-1	
		Tota	\$ 216,000			Total \$	
-	8						
6. Amount by Sou	rce of Financing:						
6. Amount by Sou	rce of Financing:		1				
		2. SECIF Fund	3. Fund	4.	5.	Total	
Fiscal Years	ce of Financing:	2. SFCIF Fund	3 Fund	4.	5.	Total	
Fiscal Years Prior Years		2. SFCIF Fund	3 Fund	4.	5.		
Fiscal Years Prior Years FY 2016		2. SFCIF Fund	3 Fund	4.	5.		
Fiscal Years Prior Years FY 2016 FY 2017				4.	5.		
Fiscal Years Prior Years FY 2016 FY 2017 FY 2018		2. SFCIF Fund 216,000		4.	5.		
Fiscal Years Prior Years FY 2016 FY 2017 FY 2018 FY 2019				4.	5.	216,000	
Fiscal Years Prior Years FY 2016 FY 2017 FY 2018 FY 2019 FY 2020				4.	5.	216,000 	
Fiscal Years Prior Years FY 2016 FY 2017 FY 2018 FY 2019	1. SGF			4.	5.	216,000	

1. Project Tit	le Bison Arena Renovation	2. Project Priority: SGF #9
Agency:	Kansas State Fair	36
2 Decided De	saviation and tratifications	

3. Project Description and Justification:

In partnership with the Kansas Department of Agriculture, the Fair is exploring the renovation of Bison Arena (originally constructed in the 1930's as the 4-H/FFA livestock building).

Bison Arena has served a variety of purposes over its life and is still an important part of the Fair's campus.

Working with the KDA, we envision the development of a facility focusing on the promotion of Kansas agriculture and expanding the already strong presence Kansas agriculture has at the Fair. The renovated facility would enhance agrcultural educational programming and entertainment along with opportunities for the Kansas agriculture community. The building would provide opportunity for an updated and remodeled Agriland, booth space for Kansas agriculture commodity groups and a From the Land of Kansas (state trademark program) pavilion and store.

This renovation would also provide opportunity for year-around use of the facility, a benefit currently not available.

1 Fatimated F	Valuat Coats	_		-		E Droinet Dhasings				
4. Estimated Project Cost:				F 7F4 000	5. Project Phasing:	(;) ();				
1. Construction (including fixed			5,754,000			1. Preliminary plans (including				
equipment and sitework) 2. Architect or engineer fee 3. Moveable equipment 4. Project contingency 5. Miscellaneous costs						misc. costs)				
					575,000	2. Final plans (inc	2. Final plans (including misc.			
						and other cost				
			575,000 3. Construction (including misc. 100,000 and other costs)							
	*									
×				Total	\$ 7,004,000	1		Total	\$	
					de veste d'union					
6. Amount by	Source of Financing:									
Fiscal Years	1. SGF	2	Fund		3. Federal Funds	4.	5.		Total	
Prior Years										
FY 2016										
FY 2017										
FY 2018				S						
FY 2019	v									
FY 2020										
FY 2021	7,004,000								7,004,000	
Subsequent Y	'ears									
Total	7,004,000	\$			\$	\$	\$		7,004,000	

36-24