GEOTECHNICAL ENGINEERING REPORT

Proposed Kansas Energy and Service Center SW 7th Street and SW Van Buren Street Topeka, Kansas

Project No. D14G1399

December 31, 2014

Prepared for:

Kansas Department of Administration HTK Architects, PA

Prepared by:





December 31, 2014

Ms. Ramona A. Flower State of Kansas Office of Facilities & Procurement Management 800 SW Jackson Street, Suite 600 Topeka, Kansas 66612-1216

Subject: Geotechnical Engineering Report

Proposed Kansas Energy and Service Center SW 7th Street and SW Van Buren Street

Topeka, Kansas Project No. D14G1399

Dear Ms. Flower:

We have completed the subsurface exploration and geotechnical engineering evaluation for the above referenced project. The purpose of the exploration was to obtain information on the subsurface conditions within the building site and, based on this information to provide geotechnical engineering recommendations for design and construction of foundations for the proposed structures.

In summary, the borings encountered existing fill and naturally deposited soils underlain by shale and limestone bedrock that continued to the depths explored. The existing fill was quite variable and contained some rubble. Because of this, we have recommended that the proposed building be supported on drilled pier foundations that extend through the fill to the underlying limestone bedrock.

This report completes our current scope of services for this project. The enclosed report describes our exploration procedures and presents the results of the testing and evaluation along with design and construction recommendations for this project. We appreciate the opportunity to work with you on this project and are prepared to provide the recommended construction services.

Respectfully submitted,

GeoSource, LLC

257/

John J. Zey, P.E.

Kansas: 8574

Axel S. Novion, P.E.

Kansas: 15390

Cc: Mr. Dennis A. Haugh, AIA - HTK Architects, PA

Mr. Clark Basinjer, PE – Bob D. Campbell & Company



TABLE OF CONTENTS

<u>SECTION</u>	PAGE
INTRODUCTION	1
PROJECT DESCRIPTION	1
DRILLING AND SAMPLING PROCEDURES	2
LABORATORY TESTING PROGRAM	4
SITE CONDITIONS	5
SUBSURFACE CONDITIONS	6
GROUNDWATER OBSERVATIONS	8
CONCLUSIONS AND RECOMMENDATIONS	9
SITE PREPARATION	11
CLIMATE CONDITIONS	13
EXCAVATIONS	13
STRUCTURAL FILL	14
FOUNDATIONS	15
DRILLED PIER FOUNDATIONS	15
GEOPIER FOUNDATION SYSTEM	18
SEISMIC HAZARDS DETERMINATION	19
BUILDING FLOOR SLABS	20
LATERAL EARTH PRESSURES	22
PAVEMENTS	23
PLANS AND SPECIFICATIONS REVIEW	24
CONSTRUCTION OBSERVATION AND TESTING	25
LIMITATIONS	25

APPENDIX

Figure 1: Boring Location Sketch Figure 2: Generalized Subsurface Profile Boring Logs

General Notes and Terms

Boring Log Symbol

GEOTECHNICAL ENGINEERING REPORT

PROPOSED ENERGY AND SERVICE CENTER

SW 7TH STREET AND SW VAN BUREN STREET

TOPEKA, KANSAS

Project No. D14G1399 December 31, 2014

INTRODUCTION

GeoSource has completed the subsurface exploration and geotechnical engineering evaluation of the

site for the proposed Kansas Energy and Service Center building, which is located southeast of the

intersection of SW 7th Street and SW Van Buren Street in Topeka, Kansas. Our services for this

project were provided in general accordance with our November 26, 2014 proposal. The

exploration work was authorized on December 4, 2014 with the issuance of Purchase Order No.

17300-000017324 by the Kansas Department of Administration.

PROJECT DESCRIPTION

We understand that the proposed building will be a two story, steel frame structure, with metal stud

infill walls and brick veneer or stone panel exterior facing. The new building will have overall plan

dimensions of approximately 120 by 160 feet. Maximum column loads for the new building were

estimated by the Structural Engineer to be less than 260 kips. The finished floor elevation of the

new building has tentatively been set at elevation 928.76 feet, USGS datum. The floor for the

service base on the east side of the building will be stepped to follow the grade of the existing alley.

The floor slab elevation at the northeast corner of the building will be at elevation 925.54 feet, the

floor slab elevation at the southeast corner will be at 928.76 feet, and the intermediate floor slab

elevation will be at 927.04 feet. The bottom of the elevator pit has tentatively been set at elevation

924.76 feet. At this proposed floor elevation up to 6 feet of new fill will be required to establish

grades for the proposed building area.

Light duty parking lots are planned for the areas on the north and south sides of the new building.

The parking lots will provide space for about 40 automobiles and other light personnel vehicles.



Drives will connect the parking lots to SW 7th Street and/or to the existing alley. No other specific information was provided regarding the design life of the pavement section.

A new utility tunnel will extend from the proposed Energy and Service Center building to the Kansas Statehouse along SW Van Buren Street. The plan and profile drawing of the tunnel that was provided to GeoSource indicated that the bottom of the tunnel will extend to about elevation $912 \pm$ feet at the proposed building site and will be at about elevation $915 \pm$ feet at the Statehouse parking garage. The tunnel will have a height of about $8 \pm$ feet and will be constructed of reinforced concrete.

The scope of the exploration and engineering evaluation for this study, as well as the conclusions and recommendations in this report, were based on our understanding of the project as described above. If pertinent details of the project have changed or otherwise differ from our descriptions, we must be notified and engaged to review the changes and modify our recommendations, if needed.

DRILLING AND SAMPLING PROCEDURES

The field work for this project was performed between December 17 and 19 of 2014. A total of sixteen exploratory test borings were drilled for this project. Figure 1 in the Appendix shows the approximate locations of the borings with reference to the proposed building lines and other site features. The boring locations were established by GeoSource personnel. Distances from the existing city streets and other reference features to the boring locations were measured using a calibrated wheel. Right angles for locating the borings were estimated. The ground surface elevations shown on the boring logs are approximate and were determined using an engineer's level and rod. The elevations were referenced to the rim of the existing storm water manhole (SWMH), located on the west side of SW Van Buren Street about 165 feet south of SW 7th Street. The elevation of the manhole was given as 924.49 feet, USGS datum, on the site plan that was provided to GeoSource. The locations and elevations of the borings should be considered accurate only to the degree implied by the methods used to make these measurements.



The borings were performed with a truck-mounted, rotary drill rig using 4-inch diameter flight augers to advance the boreholes. Representative samples of the overburden soils and bedrock units were obtained at selected intervals using the Shelby tube and split-barrel sampling procedures as outlined in ASTM Specifications D-1587 and D-1586, respectively. The Shelby tube sampling procedure utilizes a thin-walled, steel tube with a sharp cutting edge that is pushed hydraulically into the bottom of the boring to obtain relatively undisturbed samples of cohesive or moderately cohesive soils. The samples were sealed and returned to our laboratory for further examination, classification and testing.

The split-barrel sampling procedure utilizes a standard 2-inch O.D. split-barrel sampler that is driven into the bottom of the boring with an automatic hammer. The number of blows required to advance the sampler the last 12 inches of a normal 18-inch penetration is recorded as the Standard Penetration Resistance Value (N). These "N" values are indicated on the boring logs at their depth of occurrence and provide an indication of the consistency of clays and the relative hardness of weathered bedrock units. A higher efficiency is achieved with the automatic hammer compared to the conventional safety hammer operated with a cathead and rope. This higher efficiency has an appreciable effect on the Standard Penetration Resistance Values (N). The effect of the automatic hammer's efficiency has been considered in the interpretation and analysis of the subsurface information for this report.

Borings B-2 and B-4 were continued below the point of auger refusal through use of NQ3-diamond bit coring procedures. This diameter core barrel provides a sample having a diameter that is slightly smaller than 2 inches. Descriptions of the rock core are presented on the respective boring logs in addition to recovery and Rock Quality Designation (RQD) for the core recovered. Recovery is defined as the length of core obtained expressed as a percentage of the total length cored. Rock Quality Designation is defined as the total length of core pieces, 4 inches or greater in length, expressed as a percentage of the total length cored. Rock Quality Designation provides an indication of the integrity of the rock mass and relative extent of seams and bedding planes.



Boring logs are included in the Appendix of this report and present such data as soil and bedrock descriptions, consistency and relative hardness evaluations, depths, sampling intervals and observed groundwater conditions. Conditions encountered in each of the borings were monitored and recorded by the drill crew. Field logs were prepared by the drill crew that included visual classification of the materials encountered during drilling, as well as drilling characteristics. Our final boring logs represent the geotechnical engineer's interpretation of the field logs combined with laboratory observation and testing of the samples. Stratification boundaries indicated on the boring logs were based on observations during our field work, an extrapolation of information obtained by examining samples from the borings and comparisons of soils and/or bedrock types with similar engineering characteristics. Locations of these boundaries are approximate, and the transitions between soil and bedrock types may be more gradational in nature rather than clearly defined.

LABORATORY TESTING PROGRAM

The laboratory testing program consisted of performing water content, dry unit weight and unconfined compression tests on representative portions of undisturbed samples obtained with the Shelby tube sampler. A calibrated hand penetrometer was used to determine the approximate unconfined compressive strength of samples that were deformed or otherwise unsuitable for unconfined compression testing. The hand penetrometer has been correlated with unconfined compression tests, and provides a better estimate of the consistency and strength than visual observation alone. Moisture content determinations were also performed on samples obtained using the split-barrel sampler. The results of the laboratory tests are presented on the respective boring logs.

Atterberg Limits tests were conducted on representative samples of the onsite soils. These tests provide information on the plasticity of the soil, which is a basis for soil classification and for estimating the potential of subgrade soils to change volume with variations in moisture content. Results of these tests are also indicated on the respective boring logs.

In addition, unconfined compression tests were performed on selected rock cores to evaluate the compressive strength of the bedrock units encountered in the borings. The results of the unconfined



compression tests are shown on the respective boring logs in the Appendix of this report. The unconfined compressive strengths are in psi (pounds per square inch).

As part of the testing program, the soil samples were classified by a geotechnical engineer using visual and manual procedures outlined in ASTM D-2487 and D-2488. The descriptions of the soils indicated on the boring logs are in accordance with the enclosed General Notes and the Unified Soil Classification System. Estimated group symbols according to the Unified Soil Classification System are shown on the boring logs. A brief description of this classification system is included in the Appendix of this report.

The bedrock units encountered in the borings were described in accordance with the enclosed General Notes for Bedrock on the basis of visual classification of disturbed auger cuttings and drilling characteristics. Core samples may reveal other rock types.

SITE CONDITIONS

The proposed building site is located southeast of the intersection of SW 7th Street and SW Van Buren Street in Topeka, Kansas. The site was bounded on the north by SW 7th Street, on the west by SW Van Buren Street and on the east by an existing alley. At the time the borings were performed, the site was a paved parking lot. Historical photographs indicated that the site was previously occupied by a power plant and several other buildings in the past. The borings encountered undocumented clay fill, most of which contained variable amounts of bricks, cinders, gravel and other miscellaneous construction debris from the former buildings. Auger refusal was encountered on rubble at boring locations B-8 and B-15, suggesting that buried foundations or basement walls and slabs or large concrete or limestone fragments are buried beneath portions of the proposed building site. At Boring B-2, a strong fuel odor was detected in the undocumented fill encountered between depths of about 5 to 10.3 feet.



SUBSURFACE CONDITIONS

The following presents a general summary of the major strata encountered during our subsurface exploration and includes a discussion of the results of field and laboratory tests conducted. Specific subsurface conditions encountered at the boring locations are presented on the individual boring logs in the Appendix of this report. Figure 2 in the Appendix shows a Generalized Subsurface Profile, based on the information obtained from the borings. The stratification lines shown on the boring logs and profile represent the approximate boundaries between soil and bedrock types; insitu, the transition between materials may be more gradational in nature rather than clearly defined.

All of the borings were drilled in paved areas and encountered about 3 to 5 inches of asphaltic concrete pavement at the surface. Borings B-10 through B-13 were drilled on SW Van Buren Street along the alignment of the proposed utility tunnel and encountered brick pavers below the asphalt pavement.

The pavement section was underlain by undocumented fill that continued to depths of about 5.5 to 14.3 feet below the existing ground surface at the boring locations. The upper 2-½ to 3 feet of the fill was generally comprised of medium stiff to very stiff, light brown lean clay (CL), with a trace of fine sand. Laboratory tests performed on samples of this lean clay fill indicated moisture contents in the range of 13.4 to 25.6 percent, with dry densities of 102 to 115 pcf and unconfined compressive strengths of 1,450 to 5,990 psf. Atterberg Limits performed on this material indicated Liquid Limits in the range of 34 to 39, with Plasticity Indices of 15 to 20.

Beneath the upper fill layer, the borings encountered moderate to high plasticity fill that contained variable amounts of brick, cinders, gravel and other miscellaneous construction debris. No significant amounts of wood, trash or other unsuitable materials were encountered at the boring locations. As previously discussed, fuel contaminated soils were encountered in Boring B-2 below a depth of about 5 feet. In addition, significant amounts of rubble, including large size debris were encountered in Borings B-7, B-8 and B-15. Buried obstructions within the rubble fill were encountered in Borings B-8 and B-15. These obstructions could be buried foundation or large size



fragments of concrete or limestone. Laboratory tests performed on samples of the undocumented fill indicated moisture contents in the range of 11.4 to 55.7 percent, with dry densities of 97 to 106 pcf and unconfined compressive strengths of 1,420 to 5,300 psf. Standard Penetration Tests performed in the existing fill yielded "N" values ranging from 4 to 76 blows for one foot of penetration or less.

The undocumented fill was underlain by naturally deposited clay soils at 9 of the 16 boring locations. The natural clay soils were deposited by glacial ice that covered northeast Kansas in the Pleistocene Period. The glacial soils were visually classified as stiff to very stiff, lean clays (CL) and fat clays (CH). Laboratory tests performed on samples of the natural clay soils indicated moisture contents in the range of 17.1 to 28.0 percent, with dry densities of 102 to 107 pcf and unconfined compressive strengths of 2,050 to 4,440 psf. Soil colors varied from brown to light brown to reddish brown, with light gray and rust mottling. Standard Penetration Tests performed in the natural clay soils yielded "N" values in the range of 7 to 12 blows for one foot of penetration or less.

The undocumented fill and naturally deposited glacial clay soils were underlain by interbedded layers of shale and limestone bedrock that are part of the Topeka Limestone Formation of the Pennsylvanian Age Shawnee Group. The bedrock was encountered in the borings at depths ranging from about 10.3 to 14.3 feet across the proposed building site. The uppermost bedrock unit encountered was the weathered remnants of the Turner Creek Shale Member. The Turner Creek Shale is typically 2 to 5 feet thick and consists of weathered, olive tan to gray brown, clayey to silty shale. The Turner Creek Shale was underlain by the Sheldon Limestone Member. The Sheldon Limestone was described as a buff to light gray, fossiliferous limestone. The thickness of this limestone unit varied from about 1.5 feet to 2.8 feet across the site. The Jones Point Shale Member was encountered below the Sheldon Limestone and this bedrock unit typically consists of gray, silty to clayey shale that was about 1.8 to 2.2 feet thick at the boring locations where it was encountered.

The Jones Point Shale was underlain by the Curzon Limestone, which is the thickest limestone unit of the Topeka Formation. The Curzon Member is typically comprised of two or more beds of medium to thick-bedded, buff to light gray, fossiliferous limestone. The thickness of the Curzon



Limestone ranged from about 5.9 to 6.3 feet at the boring locations where it was encountered. The Curzon Member was underlain by the Iowa Point Shale Member. The Iowa Point Member is typically a hard, gray, clayey to silty shale that locally contains sandstone layers. At the proposed building site, the Iowa Point Shale had a thickness of only about 1 to 2 feet. The Iowa Point Shale was underlain by the Hartford Limestone Member, which is the basal member of the Topeka Limestone Formation. The Hartford Member typically has a total thickness of about 5 to 6 feet and consisted of massive, gray to bluish gray, fossiliferous limestone. Core samples of the bedrock from Borings B-2 and B-4 had recovery rates of 78 to 100 percent, with Rock Quality Designation (RQD) values in the range of 56 to 100 percent, indicating fair to good quality rock. The unconfined strength of the limestone units ranged from about 1,970 to 9,520 psi.

GROUNDWATER OBSERVATIONS

Groundwater observations were made in the boreholes both during and following completion of the drilling operations. Groundwater was encountered in Borings B-1, B-5, B-9 and B-15 at depths ranging from about 0.5 to 12.0 feet below the existing ground surface. At Boring B-15, groundwater was encountered very near the existing ground surface. The other borings remained, dry prior to coring, and no visible groundwater seepage was observed at the time the borings were performed. The materials encountered in the test borings have relatively low permeabilities and observations over an extended period of time through use of piezometers or cased borings would be required to better define current groundwater conditions.

Coring of the bedrock at boring locations B-2 and B-4 required the introduction of water into the borehole as a drilling fluid to cool the bit and to flush the cuttings from the hole. No noticeable loss of drilling fluid was noted. The water levels indicated on the boring logs where coring procedures were used represent the water level in the borings after removal of casing and drill tools and is generally not an indicated of a true water table.

Page 9

GEOSOURCE

Groundwater in the underlying bedrock typically flows through joints and fissures in the limestone

bedrock units. The shale bedrock units are generally less permeable and do not transmit significant

amounts of groundwater seepage.

The composition of the glacial soils is often erratic due to the random nature of its deposition. Glacial

deposits frequently contain isolated pockets of water bearing sands and gravel, as well as cobbles and

large boulder size materials. Water bearing lenses within natural glacial deposits are generally limited

in extent. Excavations encountering such lenses typically experience a sudden influx of groundwater

due to the high permeability of the materials within the lens. Foundation and other excavations that

encounter trapped water within the glacial soils can normally be dewatered using conventional sump

pumps.

Fluctuations of groundwater levels can occur due to seasonal variations in the amount of rainfall,

runoff, and other factors not evident at the time the borings were performed. The possibility of

groundwater level fluctuations should be considered when developing the design and construction

plans for the project.

CONCLUSIONS AND RECOMMENDATIONS

Based on the results of our evaluation, it is our professional opinion that the proposed project site

can be developed for the proposed building and utility tunnel using conventional grading and

foundation construction techniques. The existing undocumented fill was quite variable across the

site and contained significant amounts of rubble and construction debris at some of the boring

locations. Because of this, the undocumented fill is not suitable for support of shallow spread

footings.

We have recommended that the proposed building be supported on drilled pier foundations that

extend through the undocumented fill and naturally deposited glacial clay soils and are founded in

the Curzon Limestone Member that underlies the proposed building site. Recommendations for

02-02-2016

Att.9E.--012



design and construction of drilled pier foundations are presented in the follow sections of this report.

As an alternative to supporting the proposed building on drilled pier foundations, shallow foundation support bearing on a *Geopier*[®] reinforced subgrade would appear to be a viable foundation option for this project that may potentially provide an economic benefit to this project. Geopiers are rammed aggregate piers that are installed by a specialty contractor using a proprietary method. Recommendations for design and construction of geopiers is normally provided by Geopier US, the company that developed this method of ground improvement and foundation support.

The major concern, from a geotechnical engineering standpoint, is the presence of undocumented fill and the potential for encountering old foundations, walls and other buried structures, as well as large concentrations of rubble from the former buildings that previously occupied the site. If buried structures and/or large concentration rubble are encountered, they could hamper the installation of the drilled pier foundations and/or the drilling of the boreholes for the Geopiers. Removal and replacement of the existing undocumented fill does not appear to be an economical option for this project. One way to deal with the uncertainty, would be to establish a contingency fund for removal of old buried structures and/or rubble in areas affected by the new construction.

The construction of the proposed utility tunnel between the proposed building and Statehouse Parking Garage should be relatively straight forward. The borings indicated that some rock excavation will likely be required to install the tunnel at the currently proposed bottom elevations. Removal of the rock will likely require the use of pneumatic breakers, rock teeth or some other method of hard rock removal. Groundwater was not encountered in the borings that were drilled along the proposed tunnel alignment. However, it would be prudent to include underdrains below the floor slab of the tunnel and adjacent to the tunnel walls to prevent hydrostatic loading of the walls and seepage into the tunnel, should groundwater levels change in the future.



To reduce the potential for subgrade volume change and floor slab movement, we have recommended that a minimum of 24 inches of select, low volume change material be placed below building floor slabs. Thorough site preparation will be required to correct areas that were disturbed by previous construction activity at the proposed building site. The recommendations given in the following sections of this report describe subgrade preparation for building foundations, floor slabs and pavements, as well as undercutting procedures to remove existing fill, soft soils, expansive clays and other unsuitable materials. Proper fill placement techniques are also discussed and include: recommended types of fill materials, maximum lift thickness, as well as soil moisture content and compaction criteria for structural fill sections.

The recommendations submitted herein are based, in part, upon data obtained from our subsurface exploration. It should be recognized that subsurface conditions may vary between the exploration points and that the nature and extent of any subsurface variations that may exist at the proposed site will not become evident until exposed during construction. If variations appear evident, then the recommendations presented in this report should be reevaluated. In the event that any changes in the nature, design, location or floor slab elevations of the proposed building are planned, the conclusions and recommendations contained in this report should not be considered valid unless the changes are reviewed by the geotechnical engineer and our recommendations modified in writing, if necessary.

SITE PREPARATION

Initial site preparation for the proposed project should commence with the removal of the existing pavement section and the demolition of any existing structures that are located within proposed construction areas. Demolition should include complete removal of all grade supported slabs, pavements, sidewalks and shallow spread footings. All broken concrete, asphalt and other debris from demolition of these structures should be removed from the site. Areas disturbed during demolition of the existing structures should be thoroughly evaluated by the geotechnical engineer prior to placement of structural fill. All disturbed soils should be undercut prior to placement of structural fill.



Relocation of any existing utility lines within the zone of influence of proposed construction areas should also be completed as part of the site preparation. The lines should be relocated to areas outside of the proposed construction. Excavations created during the removal of the existing lines should be cut wide enough to allow for use of heavy construction equipment to recompact the fill. In addition, the base of the excavations should be thoroughly evaluated by a geotechnical engineer or engineering technician prior to placement of fill. All fill should be placed in accordance with the recommendations presented in the Structural Fill section of this report.

Following completion of the demolition work, it is recommended that the exposed grade be scarified to a minimum depth of 8 inches and be moisture conditioned to bring the moisture content of the soils into the range recommended for structural fill. Moisture conditioning is the process of adjusting the moisture content of the scarified materials to a moisture content that is within a range of 0 to 4 percent above the optimum moisture content as determined by the Standard Proctor (ASTM D-698) compaction procedure. Following moisture conditioning, the scarified materials should be recompacted to a minimum of 95 percent of Standard Proctor (ASTM D-698) maximum dry density. Soft or unstable areas that hamper compaction of the subgrade should be undercut and replaced with structural fill.

Following moisture conditioning and prior to placement of any new fill, it is recommended that the exposed grade be proofrolled. Proofrolling of the subgrade provides a more stable base for placement of structural fill and aids in identifying soft or disturbed areas. Unsuitable areas identified by the proofrolling operation should be undercut and replaced with structural fill. Proofrolling can be accomplished through use of a fully-loaded, tandem-axle dump truck or similar equipment providing an equivalent subgrade loading. Suitable structural fill should then be placed to design grades as soon as practical after reworking the subgrade to avoid moisture changes in the underlying soils.

If soft or unstable conditions are encountered during the proofrolling operation, stabilization of the soils may be required. Clean crushed rock having a particle diameter of 3 to 6 inches could be used to stabilize the subgrade prior to placement of structural fill. After initial undercutting, the large rock would be spread over the unstable subgrade and worked into the soft soils by close tracking with a

Page 13

GEOSOURCE

bulldozer or other suitable construction equipment. Additional rock would be added until the subgrade becomes firm enough to support construction equipment. The use of a geotextile fabric, in conjunction with crushed rock, could also be considered as a means of stabilizing the exposed grade.

CLIMATIC CONDITIONS

Weather conditions will influence the site preparation required. In spring and late fall, following periods of rainfall, the moisture content of the near surface soils may be significantly above the optimum moisture content. Additionally, it is common to encounter wet, unstable soils upon removal of the site pavements or flatwork as a result of moisture becoming trapped beneath relatively impervious concrete or asphalt pavements. These conditions could seriously impede grading by causing an unstable subgrade condition. Typical remedial measures include aerating the wet subgrade, removal of the wet materials and replacing them with dry materials or treating the wet material with fly ash.

If site grading commences during summer months, the moisture contents of the onsite soils may be abnormally low, which can significantly increase the swell potential of the clay soils. Typically, discing and moisture conditioning of the exposed subgrade materials to the moisture content criteria outlined in the Structural Fill section will reduce this swell potential of the dry materials. As an alternative, the dry materials could be undercut and replaced with structural fill.

EXCAVATIONS

Excavations will be required for foundations, underground utilities and a utility tunnel for this project. It is anticipated that the foundation excavations will be in undocumented fill and naturally deposited clay soils above the water table. These materials can generally be excavated with conventional earthmoving equipment such as backhoes and large track hoes. Rubble fill and buried structures within the undocumented fill could hamper excavations in some areas of the site. Utility excavations that extend into the underlying weathered shale bedrock with a Standard Penetration Resistance (N) value of less than 25 blows per foot can generally be excavated with conventional earthmoving

GEO**S**OURCE

equipment such as backhoes, large track hoes, loaders, etc. The borings indicated that the proposed utility tunnel excavation along SW Van Buren Street will extend into harder, less weathered shale and/or limestone bedrock units. Removal of the hard shale and limestone will be more difficult and will probably require the use of rock teeth, pneumatic breakers, or some other method of hard rock removal to complete the excavation for the utility tunnel.

Temporary construction slopes should be designed in strict compliance with the most recent governing regulations. The naturally deposited clay soils encountered in the borings would generally be classified as Type B soils, under Part 1926 of the OSHA regulations pertaining to open excavations. For these soils, it is recommended that temporary construction slopes be no steeper than 1(H) to 1(V). Construction slopes should be closely observed for signs of mass movement: tension cracks near the crest, bulging at the toe, etc. If potential stability problems are observed, the geotechnical engineer should be immediately contacted. The responsibility for excavation safety and stability of temporary construction slopes should lie solely with the contractor.

STRUCTURAL FILL

All structural fill should consist of approved materials, free of organic matter and debris. Fill placed within 24 inches below the building floor slab and leveling course materials should consist of a lower plasticity cohesive soil having a liquid limit less than 45. Higher plasticity soils could be used as structural fill in the lower portion of deep fill sections in the building area and/or as structural fill in pavement areas where more movement can generally be tolerated. Fill should be placed in lifts having a maximum loose lift thickness of 9 inches. All fill should be compacted to a minimum of 95 percent of the material's maximum dry density as determined by ASTM D-698 (standard Proctor compaction). The moisture content of the fill at time of compaction should be within a range of 0 to 4 percent above optimum moisture content as defined by the standard Proctor compaction procedure. Moisture contents should be maintained within this range until completion of the building floor slab.

Granular materials that do not have a well-defined moisture-density relationship that are placed below foundations and other structures should be compacted to a minimum of 70 percent of the materials

Page 15

GEOSOURCE

maximum relative density as determined by ASTM Specifications D-4253 and 4254. Granular backfill materials placed next to structures should be compacted to a minimum of 65 percent of the materials maximum relative density. There is no specific moisture content requirement for compaction of sands and sandy soils and the moisture content of these soils should be maintained in a suitable range that facilitates the compaction of the sand.

Based on the proposed floor slab elevations, it appears that it will be necessary to import fill material to the site. It is recommended the low volume change material be imported to complete the required fill sections.

FOUNDATIONS

The borings encountered undocumented fill with variable amounts of rubble and construction debris. The undocumented fill is not considered suitable for support of shallow spread footings. Because of this, we have recommended that the proposed building be supported on drilled pier foundations that extend through the undocumented fill and naturally deposited glacial clay soils and are founded in the Curzon Limestone that underlies the proposed building site. As an alternate to supporting the proposed building on drilled pier foundations, shallow foundation support bearing on a *Geopier*® reinforced subgrade would appear to be a viable foundation option for this project. As previously discussed, Geopiers are rammed aggregate piers that are installed by a specialty contractor using a proprietary method. Recommendations for design and construction of geopiers is normally provided by Geopier US, the company that developed this method of ground improvement and foundation support.

DRILLED PIER FOUNDATIONS

Based on the subsurface conditions encountered at the site, it recommended that the proposed building be supported by a drilled pier and grade beam foundation system. It is recommended that all drilled piers be founded in the Curzon Limestone. Based on the borings, it is anticipated that the bearing elevations of the drilled piers will range from about 908 to 913 feet, across the proposed



building site. Greater penetration into the bedrock may be required at some locations depending on the extent and severity of bedrock weathering. Drilled piers that are founded in suitable limestone may be designed and proportioned using an allowable end bearing pressure of 60,000 psf.

Any uplift loads acting on the foundations can be resisted by the effective dead weight of the piers plus an allowable side friction value of 250 psf for the portion of the shaft in soils and 2,000 psf for the portion of the shaft in weathered shale and/or limestone bedrock.

Properly reinforced drilled piers are also capable of resisting transient lateral loads from wind and/or earthquakes. It has been our experience that drilled piers with a minimum shaft diameter of 30 inches and an embedment length of at least 10 feet are capable of resisting lateral loads of 25 kips or more, with maximum top of pier deflections of ½ inch or less. If desired, GeoSource can perform a more comprehensive lateral load analysis and provide additional recommendations, when final loads become available. All piers subject to lateral loads should be properly reinforced.

All piers should have a minimum shaft diameter of 36-inches in order to accommodate dewatering equipment and/or to permit access for proper hand cleaning and observation of the base. Some groundwater seepage should be anticipated during the installation of drilled piers and use of temporary casing and dewatering techniques may be required. Temporary casing may also be required in areas where significant amounts of debris and/or rubble are present in the undocumented fill. To minimize disturbance to the bearing surfaces caused by ponding of water, it is recommended that concrete be placed the same day that the piers are drilled. It is also recommended that temporary casing be installed when personnel are required to enter a drilled pier excavation to clean or observe the bearing surface.

To minimize disturbance to the bearing surfaces caused by ponding of water, it is recommended that concrete be placed the same day that the drilled shafts are completed. The bottom of the pier excavation should be clean and free of water and loose materials prior to placement of the reinforcing steel and concrete. Concrete placement should be continuous from the bottom to the top elevation of the shaft. For dry excavations, concrete may be placed by the free fall method,

Kansas Energy & Service Center

Page 17

Project No. D14G1399

GEOSOURCE

provided that it can be directed down the center of the shaft without hitting the reinforcing steel or

sides of the excavation. Wet excavated shafts will require that the concrete either be pumped from

the bottom up or placed using a tremie. The tremie pipe should be clean and have a sufficient inside

diameter for use with the specific concrete mix, but not less than 10 inches. The discharge end of

the tremie should allow free radial flow of the concrete and be immersed at least 5 feet in concrete

and maintain a positive pressure differential during placement to prevent water or spoil intrusion.

It is anticipated that the drilled piers can be installed with conventional drilling equipment. It is

possible that obstructions, such as rubble fill or old buried foundations, walls and other structures from

the former buildings may be encountered during the installation of the drilled piers. Core barrels, rock

augers or special construction methods may be required to remove obstructions and/or to remove loose

rock and other materials to properly prepare the foundation bearing surface for the drilled piers.

Temporary steel casing and dewatering procedures may be required for proper installation of the

drilled piers. If concrete will be placed in conjunction with the use of temporary casing, there must

be a sufficient head of concrete inside the casing to prevent soil and water from entering the pier

excavation as the temporary casing is pulled. It is recommend that concrete be designed to have a

minimum slump in the range of 6 to 8 inches to reduce the potential for arching as the casing is

removed.

It is recommended that all drilled pier and/or footing excavations be observed and evaluated by the

geotechnical engineer or his representative immediately prior to placement of foundation concrete.

Unsuitable areas identified at this time should be corrected. Corrective procedures would be

dependent upon conditions encountered and will most probably include deepening of the drilled

piers.

Long-term structural settlement of drilled piers designed and constructed as outlined above should

be minor; i.e., ½ inch or less.

02-02-2016

Att.9E.--020



GEOPIER FOUNDATION SYSTEM

As an alternate to supporting the proposed building on drilled pier foundations, shallow foundation support bearing on a *Geopier*[®] reinforced subgrade appears to be a viable option for this project and may potentially provide an economic benefit to this project. Based on our experience with the *Geopier* soil reinforcement system, we anticipate that a *Geopier* reinforced subgrade could be designed to increase the net allowable soil bearing pressure at this site while limiting foundation settlement.

The *Geopier* soil reinforcement system has been used for a number of years to support structures as an alternative to deep foundations and/or to the removal and replacement of soft or unsuitable soils. The system allows the use of conventional spread footings and floor slabs cast on-grade, and reliably controls settlement to within design tolerances.

The *Geopier* soil reinforcement system consists of highly densified aggregate piers. The *Geopier* elements are installed by drilling 30-inch diameter holes, and ramming thin lifts of well-graded aggregate within the holes to form very stiff, high-density aggregate piers. The drilled holes for this project should extend through the undocumented fill to the underlying bedrock, a depth of about 13 to 19 feet below the finished floor elevation of the existing building. Following drilling of the geopier hole, well graded aggregate is compacted in 12-inch loose lifts in the drill hole. Ramming takes place with a high-energy beveled tamper that both densifies the aggregate and forces the aggregate laterally into the sidewalls of the hole. This action increases the lateral stress in surrounding soils, thereby further stiffening the reinforced composite soil mass. The result of *Geopier* installation is a significant strengthening and stiffening of subsurface soils that then support floor slabs and high-capacity footings.

Geopier designs are based on a two-layer settlement analysis as described by Lawton et al. (1994) and in the Geopier Reference Manual. Settlements within the "upper zone" (zone of soil that is reinforced with Geopier elements) are computed using a weighted modulus method that accounts for the stiffness of the Geopier elements, the stiffness of the matrix soil, and the area coverage of Geopier elements below supported footings. Settlements within the "lower zone" (zone of soils beneath the upper zone

Page 19

GEOSOURCE

which receives lower intensity footing stresses) are computed using conventional geotechnical

settlement methods.

The Geopier soil reinforcement system is a design-build system and Geopier US should be

contacted to provide engineering analyses and project specific design information for this project.

Please contact Mr. Aaron J. Gaul, of *Geopier Foundation Company – Midwest at (816) 531-6026*

regarding the final system design, including the allowable foundation bearing pressure, Geopier

shaft lengths and spacing, anticipated floor slab thickness, and a cost to support the proposed

building.

If the Geopier system is selected, Quality Assurance testing should be performed during installation,

including documentation of the soil conditions encountered, the shaft lengths, amount of aggregate

used, verification of the modulus test readings, and tests on the compacted aggregate lifts. GeoSource

would be pleased to provide this service.

SEISMIC HAZARDS DETERMINATION

Earthquake hazard evaluation is a complex task. Seismic sources must be identified and

characterized, path effects must be evaluated (i.e., selection of appropriate attenuation

relationships), and ground motions must be completed. Finally, an analysis of the motion with

respect to the proposed construction must be made. In addition to the multi-discipline nature of this

process, there is substantial parameter and modeling uncertainty associated with each of the steps.

Typically, code based approaches are used for seismic hazard analyses. Our seismic hazard

evaluation follows the IBC 2009 procedures.

United States Geological Society (USGS) has developed and mapped maximum earthquake

response spectra for two design levels: an earthquake having a 10% probability of exceedance in 50

years and an earthquake having a 2% probability of exceedance in 50 years. The motions

developed by USGS represent soft rock conditions, which are assumed to be representative of the

JCSBC 02-02-2016



soil/rock that would be encountered below a depth of approximately 100 feet below existing grades at the site.

The USGS "soft rock" peak ground accelerations for the 10%/50 year and 2%/50 year events are 5.10% g and 18.60% g, respectively. Maximum spectral accelerations at the 0.2 second/1.0 second periods for the 10%/50 year and 2%/50 year events are 5.10% g / 2.10% g and 15.40% g / 5.40% g, respectively. Based on the subsurface information, the project site would be characterized as a Site Class C per the 2009 International Building Code (IBC). In addition, there is no significant risk of liquefaction or mass movement of the on-site soils due to a seismic event.

BUILDING FLOOR SLABS

The recommendations outlined in the Site Preparation and Structural Fill sections of this report are intended to produce subgrades that are suitable for support of building floor slabs. These recommendations include capping the building pad with a minimum of 24 inches of select, low volume change material below the floor slab and leveling course. The select fill layer below the floor slabs has been recommended to reduce the potential for subgrade volume change and floor slab movement. The recommended low plasticity structural fill thickness is in addition to any granular section that will be required below the floor slabs. The moisture content of the subgrade soils should be maintained within the recommended range until floor slabs are completed. Depending upon weather conditions, periodic wetting may be required.

Where possible, floor slabs should be designed and constructed as free slabs to allow for some differential movement between the walls, column points and floor slabs. It is recommended that a granular leveling course, having a minimum thickness of 4 inches, be used below normally loaded building floor slabs supported on soil subgrades. The granular section provides a capillary moisture break and acts as a leveling course. Clean crushed limestone gravel, with a nominal size of ½ to ¾ inch, would be recommended for the leveling course. A modulus of subgrade reaction of 100 pci may be used to design floor slabs constructed on an untreated clay subgrade.



In areas where floor loads are greater than 200 psf, it is recommended that a minimum of 12 inches of crushed limestone aggregate be placed below the building floor slab. The crushed rock may be substituted for a portion of 18 inches of select, low volume change fill layer recommended for normally loaded floor slabs. The purpose of the crushed rock is to provide an improved subgrade for the more heavily loaded floor slab areas. In addition, the crushed rock will also provide a good working surface during construction. It is recommended that the crushed rock have a gradation similar to KDOT AB-3. The crushed rock should be placed in 6 inch lifts and compacted to a minimum of 95 percent of the material's maximum dry density as determined by ASTM D 698. A modulus of subgrade reaction of 250 pci may be used to design floor slabs constructed on 12 inches of compacted crushed limestone aggregate.

Subsurface moisture and moisture vapor naturally migrate upward through the soil and, where the soil is covered by a building or pavement, this moisture will collect. To reduce the impact of this subsurface moisture and the potential impact of future induced moisture (such as landscape irrigation or precipitation), the current industry standard is to place a vapor retarder below the compacted crushed limestone layer. This membrane typically consists of visquene or polyvinyl plastic sheeting, having a thickness of at least 10 mils. It should be noted that although vapor barrier systems are currently the industry standard, this system may not be completely effective in preventing floor slab moisture problems. These systems typically will not necessarily assure that floor slab moisture transmission rates will meet floor covering manufacturer standards and that indoor humidity levels be appropriate to inhibit mold growth. The design and construction of such systems are totally dependent on the proposed use and design of the proposed building and all elements of building design and function should be considered in the slab-on-grade floor design. Building design and construction may have a greater role in perceived moisture problems since sealed buildings/rooms or inadequate ventilation may produce excessive moisture in a building and affect indoor air quality.

Special precautions must be taken during the placement and curing of all concrete slabs. Excessive slump (high water-cement ratio) of the concrete and/or improper curing procedures used during either hot or cold weather conditions could lead to excessive shrinkage, cracking or curling of the



slabs. High water-cement ratio and/or improper curing also greatly increase the water vapor permeability of the concrete. We recommend that all concrete placement and curing operations be performed in accordance with the American Concrete Institute (ACI) Manual.

The above procedures should reduce the potential for subgrade moisture variations and consequently reduce floor slab movement and cracking. However, these procedures will not completely eliminate the volume change characteristics of the natural clay soils and, because of the presence of unaltered clay soils that extend to much greater depths, some long-term volume change may occur along with some floor slab movement and cracking. Isolation of floor slabs from walls and columns should be considered to accommodate minor differential movement of floor slabs. If it is desired to further minimize the potential for subgrade volume change, the use of a greater thickness of low volume change material beneath the floor slab should be considered.

LATERAL EARTH PRESSURES

Based on our experience with soils similar to those encountered at the site, it is recommended that the walls of the utility tunnel be designed using an equivalent fluid pressure of 55 pounds per cubic foot. This lateral earth pressure assumes an "at rest" stress distribution condition; i.e., no wall rotation is allowed. The recommended load distribution does not include a factor of safety or take into account the influence of any hydrostatic loading of the walls. Also, the stress distributions do not include the influence of any foundations, pavement or other surcharge loads located in or adjacent to wall backfill.

To prevent hydrostatic loading on the walls and/or seepage into the utility tunnel, it is recommended that perforated drain lines be installed at the base of the walls and also under the bottom floor slab of the tunnel. The drain lines should be sloped to provide positive gravity and should extend to a sump or storm drain where the water is removed. The drain line should be wrapped with filter fabric to prevent intrusion of fines. The drain line should be backfilled with free draining granular material extending vertically above the drain line to within 2 feet of final grade. The remaining portion of the excavation should be backfilled with cohesive soils to minimize the infiltration of surface water. The



granular section behind the wall should have a minimum width of 2 feet and should be encapsulated in the suitable filter fabric to minimize intrusion of fines. The use of a prefabricated drainage blanket on the foundation wall could also be considered to prevent hydrostatic loading. Drainage blankets should be installed in accordance with the manufacturer's recommendations.

PAVEMENTS

Parking and drive area subgrades should be prepared in accordance with the recommendations given in the Site Preparation and Structural Fill sections of this report. The site soils are considered poor subgrade materials for support of pavements. Based on the soil types encountered at this site and previous experience with materials of this type, a design CBR value of 3 is recommended for design of pavement sections. For this design value, a full-depth asphaltic concrete section having a minimum thickness of 6 inches is recommended for automobile parking areas and 7.5 inches is recommended for the access drives. For asphaltic concrete pavements, a minimum surface course thickness of 2 inches is normally recommended.

Service drives used by semi-trailer and other heavy delivery trucks require thicker pavement sections. GeoSource would be pleased to provide specific thickness recommendations for heavy duty pavements, after we receive additional information regarding the type and number of trucks that are projected to use this facility over the design life of the pavement. Portland cement concrete pavements are recommended for approach slabs, dock aprons, truck drives and parking areas, trash dumpster pads and other areas where heavy wheel loads will be concentrated. It is recommended that the concrete pavements in these areas have a minimum thickness of 8 inches. We normally recommend a 4-inch leveling and drainage course of clean, crushed rock be placed below all concrete pavements.

sections.

GEOSOURCE

Portland cement concrete pavements are recommended for the trash dumpster pad and other paved areas subjected to concentrated wheel loads and high stresses. The minimum recommended thickness in these areas is 7 inches. Normally, a 4-inch layer of granular fill is placed below concrete pavement

We recommend that the pavement subgrades be evaluated by proofrolling immediately prior to paving. The moisture content and density of the top 8 inches of the subgrade should be checked within two days prior to commencement of actual paving operations. If the material is not in compliance with the required ranges of moisture or density, the subgrade should then be moisture conditioned and recompacted. If any significant event, such as precipitation, occurs after the evaluation, the subgrade should be reviewed by qualified personnel immediately prior to placing the pavement. The subgrade should be in its finished form at the time of the final review.

Proper drainage is a key to the long term performance of any pavement section. It is recommended that all pavements be properly sloped to provide rapid runoff of surface water. Water should not be allowed to pond on or adjacent to pavements, since this could result in saturation of the subgrade and cause premature deterioration of pavements. Pavements in Kansas are normally subjected to 30 or more freeze-thaw cycles in any given year. Because of this, periodic maintenance of all of the pavements is essential to long term performance and should be anticipated. This should include sealing of all cracks and joints and by maintaining proper surface drainage next to paved areas.

PLANS AND SPECIFICATIONS REVIEW

It is recommended that the geotechnical engineer be provided the opportunity to review the plans and specifications so that comments can be made regarding the interpretation and implementation of our geotechnical engineering recommendations in the design and specifications. In the event that GeoSource is not given the opportunity to perform this recommended review, we will assume no responsibility for misinterpretation of our geotechnical engineering recommendations.

GEO**S**OURCE

CONSTRUCTION OBSERVATION AND TESTING

To effectively achieve the intent of the geotechnical recommendations presented in this report and to maintain continuity from design through construction, GeoSource should be retained to provide observation and testing services during earthwork and foundation construction phases of the project. This will provide the geotechnical engineer with the opportunity to observe the subsurface conditions encountered during construction, evaluate the applicability of the geotechnical recommendations presented in our report as they relate to the soil and bedrock conditions encountered, and to provide follow up recommendations if conditions differ from those described in our report.

LIMITATIONS

The analysis and recommendations submitted in this report are based in part upon the subsurface information obtained from the exploration points performed at the indicated locations and our present knowledge of the proposed construction as outlined in the Project Description. Subsurface conditions may vary between the exploration points and across the site and our report does not reflect any variations which may occur. The nature and extent of such variations may not become evident until construction. If subsurface conditions are encountered during construction that differ from those described in this report, GeoSource should be notified immediately so that a review may be made and any supplemental recommendations provided. If the scope of the proposed construction, including the proposed loads, floor slab elevations or locations, changes from that described in this report, our recommendations should also be reviewed and the recommendations modified accordingly.

This report has been prepared in accordance with the generally accepted geotechnical engineering practice as it exists in the area at the time of our study. No warranty is expressed or implied. The recommendations provided in this report are based on the assumption that an adequate program of observation and testing will be conducted during the construction phase in order to evaluate




compliance with our recommendations. Our scope of services did not include any environmental assessment or exploration for the presence of hazardous or toxic materials in the soil, surface water, groundwater or air, on, below or around this site.


This report has been prepared for the exclusive use of our client for specific application to the project discussed. Any party other than the client who wishes to use this report shall notify GeoSource in writing of such intended use. Additional work may be required before an updated report can be issued. Non-compliance with any of these requirements will release GeoSource from any liability resulting from the use of this report by any unauthorized party and client agrees to defend, indemnify and hold harmless GeoSource from any claim or liability associated with such unauthorized or non-compliance.



APPENDIX

FIGURE 1: BORING LOCATION SKETCH
FIGURE 2: GENERALIZED SUBSURFACE PROFILE
BORING LOGS
GENERAL NOTES AND TERMS
BORING LOG SYMBOLS





BOREHOLE INFORMATION Page 1 of 1								of 1		LOG OF BORING NO. B-1	
ST	ATION			OFFSE	ΞT				PRO	DJECT NAME Proposed Kansas Energy & Service Center	
NORTHING EASTING									SIT	SW 7th Street and Van Buren Street Topeka, Kansas	
DRLLING COMPANY GeoSource, LLC METHOD 4-inch Flight Augers HAMMER Auto								uto	OW	NER / ARCHITECT State of Kansas / HTK Architects	
IVIL		4-1110		_						Offset 4 feet east due to utilities	
SAMPLE NO.	SAMPLE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	GRAPHIC LOG	DEPTH, Feet.	MATERIAL DESCRIPTION	
/S	/S	₩	N H H	208	22	žŏ	15 X	้อ	ä	Approx. Surface Elevation:	923.4
	PA								-	Asphaltic Concrete (3")	
1	ST	15		*1500	102	25.6	CL		- -	FILL, lean clay, medium stiff, light brown, trace fine sand	920.9
	PA								-	FILL, lean to fat clay, stiff, dark gray brown,	
2	SS	18	7	*1500		21.6	CL CH		5 -	trace gravel, brick, cinders and miscellaneous construction debris	
	PA								-	6.0	917.4
	PA								- -	FAT CLAY, stiff, brown mottled light gray and rust	
3	ST	20		4410	101	28.0	СН		- - -		
	PA								10 -	11.7 **LIMESTONE, weathered, broken and seamy 12.8 to very hard, light gray	911.7 910.6
										AUGER REFUSAL @ 12.8 FEET	
										ATTERBERG LIMITS Sample 1, Depth 1-3 feet LL PL 9L 9I 37 18 19 **Rock classification is based on drilling characteristics and visual observation of disturbed samples. Core samples may reveal other rock types.	
* (Cal	ibrated	 Pene	trometer	· ** F	Rock Str	enath ir	n psi	_			
							•	te bound	dary line	es between soil and rock types. In-situ the transition may be gradual.	
WA	TER	LEVE	L OBS	SERVAT	IONS	;				BORING STARTED 12-17-14	
Ā	12.0	feet \	W.D.				٢	3=	0	BORING COMPLETED 12-17-14	
Ţ	12.0	feet A	A.B.				Yr	our Source	for Geot	echnical and Materials Engineering RIG CME-55 DRILLER	МС
Backfilled @ Completion										2 1 1 2 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1	31399

BOREHOLE INFORMATION Page 1 of 2										LOG OF BORING NO. B-2					
STATION OFFSET									PROJECT NAME Proposed Kansas Energy & Service Center						
NORTHING EASTING										SITE LOCATION SW 7th Street and Van Buren Street					
DRLLING COMPANY GeoSource, LLC										Topeka, Kansas					
ME	THOD	4-inc	h Flight	Augers	ŀ	HAMMEI	R A	uto	OW	NER / ARCHITECT State of Kansas / HTK Architects					
	111		z					(1)		Offset 8 feet west due to utilities					
Š.	ΤΥΡΙ	Ρ	RD ATIO		L S	₹ T, %	MBOL) C C (Feet.	MATERIAL DESCRIPTION					
SAMPLE NO.	SAMPLE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	3RAPHIC LOG	DEPTH, Feet.	WATERIAL DESCRIPTION					
SAN	SAN	RE(STA PEN BLC	STR	DR	MO	N N N N	GR/	DEF	Approx. Surface Elevation: 92	22.4				
	PA							XXX	-	Asphaltic Concrete (5")					
1	СТ	12		2420	107	22.7	CI		-	FILL, lean clay, stiff, light brown brown, trace					
1	ST	13		2420	107	22.7	CL		-	fine sand	19.9				
	PA								-	FILL, fat clay, stiff, gray brown					
2	SS	18	8	*4000		29.4	CL		-	<u>ries.</u> , lat city, stiff, gity brown					
2	22	18	8	*4000		29.4	СН		5 -	5.0 91	17.4				
									-	FILL, lean to fat clay, soft, dark gray brown and					
	PA								-	geenish gray mixed, trace gravel (Stong Fuel Odor)					
	IA								_	Odoi)					
									-						
3	ST	18	9	*1000		55.7	CL		-						
	51	10		1000		33.7	СН		10 -	10.3	12.1				
									-	** <u>SHALE</u> , weathered, soft, olive tan					
	PA								-		10.9 10.3				
									-		10.5				
			D O D						-	LIMESTONE, hard, solid, medium to thick-bedded, fossiliferous, buff to light gray					
R1	NQ3	100%	RQD= 75%	**4990	138	8.7			-						
									15 -						
									-						
				**8040	150	5.4			-						
D2	NICO	700/	RQD=						-	18.0	04.4				
K2	INQ3	78%	57%						-	SHALE, mod. hard, very thin bedded, tan					
									-		03.3				
				**3180	145	6.5			20 -	LIMESTONE, hard, solid, medium bedded, fossiliferous, buff to light gray					
* Cal			rometer		Rock Str		•	. " "							
10.00							oximat	e bound	lary line	es between soil and rock types. In-situ the transition may be gradual.					
WATER LEVEL OBSERVATIONS										BORING STARTED 12-17-14					
✓ Dry Prior to Coring✓ 4.0 feet A.C.R.										BORING COMPLETED 12-17-14	10				
<u> </u>							Yo	ur Source	for Geot	echinical and Materials Engineering	IC				
Backfilled @ Completion										APPROVED JJZ JOB# D14G13	399				

BOREHOLE INFORMATION Page 2 of 2								of 2			LO	G OF E	BORING	NO.	B-2		
ST	ATION			OFFSE	ΞT				PRO	OJECT NAME	Pr	oposed K	ansas Energ	gy & Se	rvice Ce	nter	
NORTHING EASTING								SITI	E LOCATION	SV	W 7th Str	eet and Van	Buren	Street			
DRLLING COMPANY GeoSource, LLC												opeka, Ka					
METHOD 4-inch Flight Augers HAMMER Auto								uto	OW	NER / ARCHITI	ECT	State of	Kansas / HT	'K Arcl	nitects		
SAMPLE NO.	SAMPLE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	GRAPHIC LOG	DEPTH, Feet.			MATE	ERIAL DESC	RIPTIO	N		
R3	NQ3	100%	RQD= 100%	**7480	152	3.5			- - -	22.5	MES ossil	TONE, h iferous, lig	ard, solid, thi ght gray	ck-bedd	ed,		899.9
										ВО	TTO	OM OF B	ORING				
	-	The str			resent t			te bound	dary line	es between soi	<u>I and</u>	rock types.	In-situ the transi		<u>be gradual.</u> 12-17	-14	
⊩			to Co				٢	7=	\Box	Sou	P	OF.	BORING COM	PLETED	12-17	-14	
Ţ	4.0	feet /	A.C.R.						_	echnical and Mate			RIG CN	IE-55	DRILLER		МС
Backfilled @ Completion													APPROVED	JJZ	JOB#	D140	31399

BOREHOLE INFORMATION Page 1 of 1								of 1		LOG OF BORING NO. B-3					
STATION OFFSET									PRO	DJECT NAME Proposed Kansas Energy & Service Center					
NO	ORTHIN	G		EAS ⁻	ΓING				SITI	ELOCATION SW 7th Street and Van Buren Street					
DRLLING COMPANY GeoSource, LLC										Topeka, Kansas					
METHOD 4-inch Flight Augers HAMMER Auto									OW	OWNER / ARCHITECT State of Kansas / HTK Architects					
SAMPLE NO.	SAMPLE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	SRAPHIC LOG	DEPTH, Feet.	MATERIAL DESCRIPTION					
S	S	<u> </u>	N L M			≥0	⊃s	Ü		Approx. Surface Elevation:	924.9				
	PA								-	Asphaltic Concrete (5")					
1	ST	14		4500	115	15.3	CL		-	FILL, lean clay, very stiff, light brown, trace fine sand	922.4				
	PA								-		922.4				
2	SS	18	20	*1500		19.0	CL CH		- - 5 -	FILL, lean to fat clay, medium stiff to stiff, dark gray brown, trace gravel, brick, cinders and miscellaneous construction debris					
	PA								- - - -						
3	SS	18	9	*3000		31.3	CL CH		10 -						
									-	11.0	913.9				
	PA								_	**SHALE, weathered, soft, olive tan					
	171								_	**LIMESTONE, weathered, broken and seamy	912.5				
									-	13.6 to very hard, light gray	911.3				
										AUGER REFUSAL @ 13.6 FEET ATTERBERG LIMITS Sample 1, Depth 1-3 feet LL PI 9I 9I 39 PI 20 **Rock classification is based on drilling characteristics and visual observation of disturbed samples. Core samples may reveal other rock types.					
* C.a	librated	l Pene	trometer	** 5	Cock Str	ength ir	l n psi								
								te bound	dary line	s between soil and rock types. In-situ the transition may be gradual.					
WA	TER	LEVE	L OBS	SERVAT	IONS	3				BORING STARTED 12-18-14					
Ā	Dry	W.D.						7=	0	BORING COMPLETED 12-18-14					
Ţ	Dry	A.B.					Yo	our Source	for Geot	echnical and Materials Engineering RIG CME-55 DRILLER	МС				
Backfilled @ Completion											31399				

ВС	REHO	OLE IN	FORMA	ATION		Pa	nge 1	of 2		LOG OF BORING NO. B-4
ST	ATION			OFFSE	Т				PRO	DJECT NAME Proposed Kansas Energy & Service Center
NC	RTHIN	G		EAST	ING				SITI	ELOCATION SW 7th Street and Van Buren Street
DR	LLING	COMPA	NY G e	eoSource	, LLC					Topeka, Kansas
ME	THOD	4-inc	h Flight	Augers	ŀ	HAMME	R A ı	uto	OW	NER / ARCHITECT State of Kansas / HTK Architects
SAMPLE NO.	SAMPLE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	SRAPHIC LOG	DEPTH, Feet.	MATERIAL DESCRIPTION
0)	•,	ш.	ол ш			20	00	U		Approx. Surface Elevation: 928 Asphaltic Concrete (5")
	PA								-	· · · · · · · · · · · · · · · · · · ·
1	ST	10		1500	107	19.3	CL		-	FILL, lean clay, medium stiff, light brown, trace fine sand 925
	PA								_	FILL, fat clay, stiff, dark gray brown mixed, trace
2	SS	18	8	*3000		27.0	СН		-	gravel and miscellaneous construction rubble
									5 –	¥
	PA								- - - -	7.2 920 FAT CLAY, very stiff, light gray mottled light
3	ST	18	10	*4500		17.5	СН		-	brown
									10 -	10.5
	PA								-	**SHALE, weathered, soft, olive tan 916
				**7800	153	5.2			-	LIMESTONE, hard, solid, thin-bedded, fossiliferous, buff 915
R1	NQ3	94%	RQD= 56%						-	SHALE, weathered, soft, tan to light brown 14.6 913
				**1970	136	15.2			15 -	<u>LIMESTONE</u> , hard, solid, medium to
R2	NO3	100%	RQD=	**9520	149	5.6			- - - -	thick-bedded, fossiliferous, buff to light gray
			65%	**4410	146	5.7			20 -	
* Cali			rometer		ock Str					
W/A				i lines rep SERVAT			oximat	te bound	ary line	es between soil and rock types. In-situ the transition may be gradual. BORING STARTED 12-18-14
╟ <u></u>			to Co		10143	'		-		BORING STARTED 12-18-14 BORING COMPLETED 12-18-14
⊩			4.C.R.	9			1/4	JE	U Cost	PIG CME-55 DRILLER MC
l				mpletic	n		Yo	our Source	ror Geot	echnical and Materials Engineering APPROVED JJZ JOB # D14G139
Щ			<u></u>							302 5140100

во	REHO	LE IN	FORMA	ATION		Pa	age 2 o	of 2		LOG OF BORING NO. B-4
STA	ATION			OFFSE	T				PRO	ROJECT NAME Proposed Kansas Energy & Service Center
NOF	RTHING	3		EAS	ΓING				SITI	TE LOCATION SW 7th Street and Van Buren Street
DRL	LING C	OMPA	NY G e	oSourc	e, LLC					Topeka, Kansas
MET	THOD	4-inc	h Flight	Augers		HAMME	R A ı	uto	OW	WNER / ARCHITECT State of Kansas / HTK Architects
SAMPLE NO.	SAMPLE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	GRAPHIC LOG	DEPTH, Feet.	MATERIAL DESCRIPTION
D2	N 102	250/	ROD=						-	- 20.9 SHALE, hard, very thin bedded, gray 907
R3	NQ3	25%	RQD=					T T	-	LIMESTONE, hard, light gray 22.5 LIMESTONE, hard, light gray
* Calit			rometer			rength ir				BOTTOM OF BORING BOTTOM OF BORING BOTTOM OF BORING
WAT				ERVA1					,	BORING STARTED 12-18-14
 			to Co				٢	==		SOURCE BORING COMPLETED 12-18-14
¥,	5.0 1	feet A	A.C.R.							otechnical and Materials Engineering RIG CME-55 DRILLER MC
ı	Back	filled	@ Co	mpletio	on					APPROVED JJZ JOB# D14G139

ВС	DREHO	DLE IN	IFORM <i>A</i>	TION		Pa	age 1	of 1		LOG OF BORING NO. B-5	
	ATION			OFFSE	T		J		PRO	DJECT NAME Proposed Kansas Energy & Service Center	
	RTHIN	G		EAS ⁻	ΓING				SITI	ELOCATION SW 7th Street and Van Buren Street	
DR	RLLING	COMPA	ANY G e	oSource	e, LLC				Oiri	Topeka, Kansas	
ME	THOD	4-inc	h Flight	Augers	I	HAMME	R A	uto	OW	NER / ARCHITECT State of Kansas / HTK Architects	
SAMPLE NO.	SAMPLE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	3RAPHIC LOG	DEPTH, Feet.	MATERIAL DESCRIPTION	
S)	Ŋ	<u>~</u>	S E B	⊃ Ø ₫	۵٩	ΣU	⊃ة	Ö		••	927.7
	PA								-	Asphaltic Concrete (5")	
1	ST	16		2940	109	20.3	CL		- - -	FILL, lean clay, stiff, light brown, trace fine sand	924.7
2	ST	13		5300	106	22.1	CL CH		- - - 5 -	FILL, lean to fat clay, very stiff to medium stiff, dark gray brown, trace gravel, brick, cinders and miscellaneous construction debris	<u>924. /</u>
	PA								- - - -		
3	ST	10		2050	106	22.1	CL CH		-	9.0	918.7
	D.1								10 -	FAT CLAY, stiff, reddish brown	
	PA								-		915.7 915.2
									_		915.2
										AUGER REFUSAL @ 12.5 FEET ATTERBERG LIMITS Sample 1, Depth 1-3 feet LL PL PI 36 19 17 **Rock classification is based on drilling characteristics and visual observation of disturbed samples. Core samples may reveal other rock types.	
* Cal	ibrated	I Pene	trometer	** F	Rock Str	ength ir	n psi				
		The str	atification	n lines rep	resent t	he appr	•	te bound	dary line	es between soil and rock types. In-situ the transition may be gradual.	
	TER	LEVE	L OBS	ERVA 1	IONS	}				BORING STARTED 12-17-14	
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	9.0							SE		BOURCE BORING COMPLETED 12-17-14	
<u> </u>	10.0	feet .	A.B.				Yo	our Source	for Geot	echnical and Materials Engineering RIG CME-55 DRILLER	MC
	Back	cfillec	l @ Co	mpletio	on					APPROVED JJZ JOB# D14G	1399

STATION OFFSET NORTHING EASTING DRILING COMPANY GeoSource, LLC METHOD 4-Inch Flight Augers HAMMER Auto OWNER! ARCHITECT State of Kansas / HTK Architects OWNER! ARCHITECT State of Kansas / HTK Architects MATERIAL DESCRIPTION Approx. Surface Elevation: 923.6 PA 1 ST 14 *2500 104 21.1 CL PA 2 SS 18 16 *2000 22.3 CL PA PA 1 ST 14 *2500 104 21.1 CL PA PA 2 SS 18 7 *2500 20.1 CT. PA PA PA PA PA PA PA PA PA P	В	OREHO	OLE IN	IFORMA	TION		Pa	age 1 d	of 1		LOG OF BORING NO. B-6	
DRILING COMPANY GeoSource, LLC	ST	ATION			OFFSE	T				PRO	DJECT NAME Proposed Kansas Energy & Service Center	
MATERIAL DESCRIPTION Approx. Surface Elevation: 92.1.1 ST 14 *2500 104 21.1 CL PA 2 SS 18 16 *2000 22.3 CL PA PA 2 SS 18 7 *2500 20.1 CL PA 2 SS 18 7 *2500 20.1 CL PA 2 SS 18 7 *2500 20.1 CL PA PA 2 SS 18 7 *2500 20.1 CL PA PA PA PA PA PA PA PA PA P	NO	ORTHIN	G		EAS	ΓING				SIT		
MATERIAL DESCRIPTION Spanned by Spanned	DF	RLLING	COMPA	NY G	eoSource	e, LLC					•	
Asphaltic Concrete (5") FILL. lean clay, stiff, light brown, trace fine sand 2.5 921.1 FILL. lean to fat clay, medium stiff to stiff, dark gray brown, trace gravel, brick, cinders and miscellaneous construction debris FILL. lean to fat clay, medium stiff to stiff, dark gray brown, trace gravel, brick, cinders and miscellaneous construction debris FILL. lean to fat clay, medium stiff to stiff, dark gray brown, trace gravel, brick, cinders and miscellaneous construction debris FILL. lean to fat clay, medium stiff to stiff, dark gray brown (Possible Fill) FILL. lean to fat clay, medium stiff to stiff, dark gray brown (Possible Fill) 7.8 915.8 LEAN CLAY. stiff, dark gray brown (Possible Fill) 11.3 **SHALE. weathered, soft, olive tan 911.5 12.7 **LIMESTONE, hard, gray 910.9 AUGER REFUSAL @ 12.7 FEET **Rock classification is based on drilling characteristics and visual observation of disturbed samples. Core samples may reveal other rock types. **Calibrated Penetrometer ** Rock Strength in psi The straffication lines represent the approximate boundary lines between soil and rock types. In-situ the transition may be gradual. WATER LEVEL OBSERVATIONS **Dry W.D.** **Dry W.D.** **Dry A.B.** **Dry A.B.* **Dry A.B.* **Dry A.B.** **Samples Total Angles Inginesting Borking Complete Distriction of 12-19-14 **Borking Complete Distriction of 12-19-14 **Borki	ME	THOD	4-inc	h Flight	Augers		HAMMEI	R A ı	uto	OW	NER / ARCHITECT State of Kansas / HTK Architects	
Asphaltic Concrete (5") FILL. lean clay, stiff, light brown, trace fine sand 2.5 921.1 FILL. lean to fat clay, medium stiff to stiff, dark gray brown, trace gravel, brick, cinders and miscellaneous construction debris FILL. lean to fat clay, medium stiff to stiff, dark gray brown, trace gravel, brick, cinders and miscellaneous construction debris FILL. lean to fat clay, medium stiff to stiff, dark gray brown, trace gravel, brick, cinders and miscellaneous construction debris FILL. lean to fat clay, medium stiff to stiff, dark gray brown (Possible Fill) FILL. lean to fat clay, medium stiff to stiff, dark gray brown (Possible Fill) 7.8 915.8 LEAN CLAY. stiff, dark gray brown (Possible Fill) 11.3 **SHALE. weathered, soft, olive tan 911.5 12.7 **LIMESTONE, hard, gray 910.9 AUGER REFUSAL @ 12.7 FEET **Rock classification is based on drilling characteristics and visual observation of disturbed samples. Core samples may reveal other rock types. **Calibrated Penetrometer ** Rock Strength in psi The straffication lines represent the approximate boundary lines between soil and rock types. In-situ the transition may be gradual. WATER LEVEL OBSERVATIONS **Dry W.D.** **Dry W.D.** **Dry A.B.** **Dry A.B.* **Dry A.B.* **Dry A.B.** **Samples Total Angles Inginesting Borking Complete Distriction of 12-19-14 **Borking Complete Distriction of 12-19-14 **Borki	AMPLE NO.	AMPLE TYPE	ECOVERY	TANDARD ENETRATION LOWS/FT.	NCONFINED TRENGTH SF	RY DENSITY CF	IOISTURE ONTENT, %	NIFIED OIL SYMBOL	RAPHIC LOG	EPTH, Feet.		
The stratification lines represent the approximate boundary lines between soil and rock types. FILL, lean clay, stiff, light brown, trace fine sand 2.5 921.1 FILL, lean clay, stiff, light brown, trace gravel, brick, cinders and miscellaneous construction debris FILL, lean to fat clay, medium stiff to stiff, dark gray brown, trace gravel, brick, cinders and miscellaneous construction debris FILL, lean clay, stiff, light brown, trace fine sand 2.5 921.1 FILL, lean clay, stiff, light brown, trace fine sand 2.5 921.1 FILL, lean clay, stiff, light brown, trace fine sand 2.5 921.1 FILL, lean clay, stiff, light brown, trace fine sand 2.5 921.1 FILL, lean clay, stiff, light brown, trace fine sand 2.5 921.1 FILL, lean clay, stiff, light brown, trace fine sand 2.5 921.1 FILL, lean clay, stiff, light brown, trace fine sand 2.5 921.1 FILL, lean clay, stiff, light brown, trace fine sand 2.5 921.1 FILL, lean clay, stiff, light brown, trace fine sand 2.5 921.1 FILL, lean clay, stiff, light brown, trace fine sand 2.5 921.1 FILL, lean clay, stiff, light brown, trace gravel, brick, cinders and miscellaneous construction debris FILL, lean clay, stiff, light brown, trace gravel, brick, cinders and miscellaneous construction debris FILL, lean clay, stiff, light brown, trace gravel, brick, cinders and miscellaneous construction debris FILL, lean clay, stiff, light brown, trace gravel, brick, cinders and miscellaneous construction debris FILL, lean clay, stiff, light brown, trace gravel, brick, cinders and miscellaneous construction debris FILL, lean clay, stiff, light brown, trace gravel, brick, cinders and miscellaneous construction debris FILL, lean clay, stiff, lean clay, stiff, laght gravel prock, cinders and miscellaneous construction debris FILL, lean clay, stiff, laght gravel prock, cinders and miscellaneous construction debris FILL, lean clay, stiff, laght gravel prock, cinders and miscellaneous construction debris FILL, lean clay, stiff, laght gravel prock, cinders and miscellaneous construction debr	S	Ŋ	~	N L M	⊃ ⊗ <u></u>		≥0	Dσ	Ŋ		• •	923.6
PA		PA								-	Asphaltic Concrete (5")	
PA 2 SS 18 16 *2000 22.3 CL PA 3 SS 18 7 *2500 20.1 CL PA PA *Calibrated Penetrometer ** Rock Strength in psi The stratification lines represent the approximate boundary lines between soil and rock types. *Calibrated Penetrometer ** Rock Strength in psi The stratification lines represent the approximate boundary lines between soil and rock types. *Calibrated Penetrometer ** Rock Strength in psi The stratification lines represent the approximate boundary lines between soil and rock types. In-situ the transition may be gradual. WATER LEVEL OBSERVATIONS ▼ Dry W.D. ▼ Dry AB.	1	ST	14		*2500	104	21.1	CL		-	<u>FILL</u> , lean clay, stiff, light brown, trace fine sand	
2 SS 18 16 *2000 22.3 CL PA PA PA 3 SS 18 7 *2500 20.1 CL PA					2000	101		CL		_	2.5	921.1
PA		PA								-	FILL, lean to fat clay, medium stiff to stiff, dark	
PA 3 SS 18 7 *2500 20.1 CL PA 10- 11.3 12.1 **SHALE, weathered, soft, olive tan 911.5 12.7 **LIMESTONE, hard, gray 910.9 AUGER REFUSAL @ 12.7 FEET **Rock classification is based on drilling characteristics and visual observation of disturbed samples. Core samples may reveal other rock types. WATER LEVEL OBSERVATIONS Dry W.D. *Dry AB. 7.8 915.8 LEAN CLAY, stiff, dark gray brown (Possible Fill) 11.3 12.1 **SHALE, weathered, soft, olive tan 911.5 12.7 **LIMESTONE, hard, gray 910.9 AUGER REFUSAL @ 12.7 FEET **Rock classification is based on drilling characteristics and visual observation of disturbed samples. Core samples may reveal other rock types. BORING STARTED 12-19-14 BORING COMPLETED 12-19-14 RIG CME-55 DRILLER MC	2	SS	18	16	*2000		22.3			-	gray brown, trace gravel, brick, cinders and miscellaneous construction debris	
The stratification lines represent the approximate boundary lines between soil and rock types. 7.8 915.8 LEAN CLAY, stiff, dark gray brown (Possible Fill) 11.3 912.3 12.1 **SHALE, weathered, soft, olive tan 911.5 12.7 **LIMESTONE, hard, gray 910.9 AUGER REFUSAL @ 12.7 FEET **Rock classification is based on drilling characteristics and visual observation of disturbed samples. Core samples may reveal other rock types. The stratification lines represent the approximate boundary lines between soil and rock types. In-situ the transition may be gradual. WATER LEVEL OBSERVATIONS □ Dry W.D. □ Dry A.B. □ Dry W.D. □ Dr								СН		5 -		
AUGER REFUSAL @ 12.7 FEET **Calibrated Penetrometer ** Rock Strength in psi The stratification lines represent the approximate boundary lines between soil and rock types. **Calibrated Penetrometer ** Rock Strength in psi The stratification lines represent the approximate boundary lines between soil and rock types. **Calibrated Penetrometer ** Rock Strength in psi The stratification lines represent the approximate boundary lines between soil and rock types. In-situ the transition may be gradual. WATER LEVEL OBSERVATIONS ▼ Dry W.D. ▼ Dry A.B.		PA								- - -	7.8	915.8
AUGER REFUSAL @ 12.7 FEET **Calibrated Penetrometer ** Rock Strength in psi The stratification lines represent the approximate boundary lines between soil and rock types. **Calibrated Penetrometer ** Rock Strength in psi The stratification lines represent the approximate boundary lines between soil and rock types. **Calibrated Penetrometer ** Rock Strength in psi The stratification lines represent the approximate boundary lines between soil and rock types. In-situ the transition may be gradual. WATER LEVEL OBSERVATIONS ▼ Dry W.D. ▼ Dry A.B.										-	LEAN CLAV stiff dark gray brown (Possible	
PA PA	3	SS	18	7	*2500		20.1	CL		- - 10 -	Fill)	
*Calibrated Penetrometer **Rock Strength in psi The stratification lines represent the approximate boundary lines between soil and rock types. *Calibrated Penetrometer **Rock Strength in psi The stratification lines represent the approximate boundary lines between soil and rock types. *BALE, weathered, soft, olive tan 911.5 **SHALE, weathered, soft, olive tan 911.5 **Calibrated Penetrometer **Rock classification is based on drilling characteristics and visual observation of disturbed samples. Core samples may reveal other rock types. *Calibrated Penetrometer **Rock Strength in psi The stratification lines represent the approximate boundary lines between soil and rock types. In-situ the transition may be gradual. WATER LEVEL OBSERVATIONS *Dry W.D. *Dry W.D. *Dry A.B. *Calibrated Penetrometer **Rock Strength in psi The stratification lines represent the approximate boundary lines between soil and rock types. In-situ the transition may be gradual. *BORING STARTED 12-19-14 BORING COMPLETED 12-19-14 RIG CME-55 DRILLER MC										-	11.2	0122
*Calibrated Penetrometer ** Rock Strength in psi The stratification lines represent the approximate boundary lines between soil and rock types. *Calibrated Penetrometer ** Rock Strength in psi The stratification lines represent the approximate boundary lines between soil and rock types. *BORING STARTED 12-19-14 BORING COMPLETED 12-19-14 *RIG CME-55 DRILLER MC		PA								-	**SUALE weathered soft alive ten	
**Rock classification is based on drilling characteristics and visual observation of disturbed samples. Core samples may reveal other rock types. **Calibrated Penetrometer **Rock Strength in psi The stratification lines represent the approximate boundary lines between soil and rock types. In-situ the transition may be gradual. WATER LEVEL OBSERVATIONS Variable Dry W.D. Dry A.B. **Rock classification is based on drilling characteristics and visual observation of disturbed samples. Core samples may reveal other rock types. In-situ the transition may be gradual. BORING STARTED 12-19-14 BORING COMPLETED 12-19-14 RIG CME-55 DRILLER MC										_	-	
The stratification lines represent the approximate boundary lines between soil and rock types. In-situ the transition may be gradual. WATER LEVEL OBSERVATIONS □ Dry W.D. □ Dry W.D. □ Dry A.B. □ D											**Rock classification is based on drilling characteristics and visual observation of disturbed samples. Core samples may reveal	
The stratification lines represent the approximate boundary lines between soil and rock types. In-situ the transition may be gradual. WATER LEVEL OBSERVATIONS ☐ Dry W.D. ☐ Dry W.D. ☐ Dry W.D. ☐ Dry W.D. ☐ OF Geotechnical and Materials Engineering ☐ CME-55 ☐ DRILLER MC	<u> </u>											
WATER LEVEL OBSERVATIONS ☐ Dry W.D. ☐ Dry A.B. ☐ Dry A.B. ☐ Dry A.B. ☐ D	* Cal							•	e hound	lary line	se between soil and rock types. In situ the transition may be gradual	
☑ Dry W.D. ☑ Dry W.D. ☐ BORING COMPLETED 12-19-14 RIG CME-55 DRILLER MC	WA							OAIIIIdl	o bourt	aciy III K	1	
▼ Dry A.B. Vour Source for Geotechnical and Materials Engineering RIG CME-55 DRILLER MC						.0110	•			_		
Your Source for Geotechnical and Materials Engineering								Ĺ	JE	U	PIG CME-55 DRILLER	MC
II DACKINEU (U COMDIEUO) II				I @ Cn	mpletic	on		Yo	ur Source	for Geot	ecitifical difu Materials Engineering	

В	DREHO	DLE IN	IFORMA	ATION		Pa	age 1	of 1		LOG OF BORING NO.	3-7	
ST	ATION			OFFSE	T				PRO	ECT NAME Proposed Kansas Energy & Serv	vice Cent	er
	RTHIN		NY G	EAST					SITI	SW 7th Street and Van Buren St Topeka, Kansas	treet	
				Augers		HAMMEI	R A	uto	OW	State of Kansas / HTK Archit	tects	
SAMPLE NO.	SAMPLE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	3RAPHIC LOG	DEPTH, Feet.	MATERIAL DESCRIPTION		
S)	S	<u>~</u>	N L M	⊃ Ø ₽		≥0	⊃ s	Ö		Approx. Surface Ele	vation:	925.0
	PA								-	Asphaltic Concrete (5")		
1	ST	20		2950	107	20.0	CL		- -	<u>FILL</u> , lean clay, stiff, light brown, trace	fine sand	
	PA								-	3.0		922.0
2	SS	12	76			11.4			-	RUBBLE FILL, brick, cinders, limeston concrete rubble in a clay matrix	ne and/or	
3	PA SS	3	50/3"			15.1			5			
	PA								10	11.1 **SHALE, weathered, soft, grayish tan 12.4		913.9 912.6
									-	** <u>LIMESTONE</u> , weathered, broken and to very hard, light gray	d seamy	911.5
									-	AUGER REFUSAL @ 13.5 FEET ATTERBERG LIMITS Sample 1, Depth 1-3 feet LL PL PI 34 19 15 **Rock classification is based on drilling characteristics and visual observation disturbed samples. Core samples may other rock types.	of	711.0
* Cal			trometer			ength ir						
							oximat	te bound	dary line	between soil and rock types. In-situ the transition may be		
WA ∑				ERVAT	IUNS	•				BORING STARTED	12-18-1	
Ā	Dry						L	ĴΕ		BORING COMPLETED	12-18-1	
	Dry		I @ C^	mpletio	n .		Yo	our Source	for Geot	nnical and Materials Engineering	JOB# D	MC 14G1399

						_				_
BORE	IOLE IN	NFORMA	ATION		Pa	age 1	of 1		LOG OF BORING NO. B-8	
STATIO	N		OFFSE	T				PRO	OJECT NAME Proposed Kansas Energy & Service Center	
NORTHI DRI LING		ANY G	EAS ⁻ eo Sourc e					SIT	SW 7th Street and Van Buren Street Topeka, Kansas	
			Augers		HAMME	r A	uto	ow	NER / ARCHITECT State of Kansas / HTK Architects	
SAMPLE NO.	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	GRAPHIC LOG	DEPTH, Feet.	MATERIAL DESCRIPTION	
" "	+-	S E E			≥ō	⊃ŏ	Ŋ		Approx. Surface Elevation: 9 Asphaltic Concrete (5")	924.9
PA								-	•	
1 ST	10		3630	110	19.0			- -	FILL, lean clay, stiff, light brown, trace fine sand 2.5	922.4
PA								-	FILL, lean to fat clay, medium stiff, dark gray	
2 SS	18	5	*2500		23.3			-	brown, trace gravel, brick, cinders and miscellaneous construction debris	
PA								5	7.5	917.4
3 SS PA		50/4"						-	RUBBLE FILL, brick, cinders, limestone or concrete debris in a clay matrix	
IA							<i>***</i>		AUGER REFUSAL @ 9.4 FEET	915. <u>5</u>
* Calibrate					rength in				Driller' Note: Auger refusal on apparent limestone and/or concrete rubble.	
WATER						oximat	ie bound	uai y IIN6	es between soil and rock types. In-situ the transition may be gradual. BORING STARTED 12-18-14	
H	W.D.					٢	7=		BORING COMPLETED 12-18-14	
▼ Dry	A.B.	_				Yo	our Source	e for Geot	echnical and Materials Engineering RIG CME-55 DRILLER	MC
Bac	kfilled	d @ Co	mpletio	on					APPROVED JJZ JOB# D14G	1399

ВС	DREHO	DLE IN	IFORMA	TION		Pa	age 1	of 1		LOG OF BORING NO. B-9	
ST	ATION			OFFSE	T				PRO	OJECT NAME Proposed Kansas Energy & Service Center	
	RTHIN		ANY G	EAS ⁻ eo Sourc e	TING				SIT	SW 7th Street and Van Buren Street Topeka, Kansas	
				Augers	·	HAMME	r A	uto	OW	NER / ARCHITECT State of Kansas / HTK Architects	
SAMPLE NO.	LE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	3RAPHIC LOG	DEPTH, Feet.	MATERIAL DESCRIPTION	
SAMP	SAMPLE	RECC	STAN PENE BLOW	UNCC STRE PSF	DRY I	MOIS	UNIFII SOIL	GRAP	DEPT	Approx. Surface Elevation: 9	26.2
	PA								_	Asphaltic Concrete (5")	
1	ST	8		2590	109	17.8	CL		- - -	FILL, lean clay, stiff, light brown, trace fine sand 2.5	923.7
	PA								-	FILL, lean to fat clay, soft to medium stiff, dark	
2	SS	18	4	*1500		25.7	CL CH		-	gray brown, trace gravel, brick, cinders and miscellaneous construction debris	
	PA						- CI		5		
3	SS	18	10	*2000		30.7	CL CH		-	_	
	PA								10 -	¥ ▼	211.0
									-		911.9 911.3
										AUGER REFUSAL @ 14.9 FEET	
										ATTERBERG LIMITS Sample 1, Depth 1-3 feet LL PL PI 34 18 16 **Rock classification is based on drilling	
										characteristics and visual observation of disturbed samples. Core samples may reveal other rock types.	
* Cal			trometer		Rock Str		•				
\/\/A				lines rep			roxima	te bound	dary line	es between soil and rock types. In-situ the transition may be gradual. BORING STARTED 12-17-14	
VVA	10.5			PERVAI	IONS	•	_			BORING COMPLETED 12-17-14	
Ţ	10.0						L	JE		PIG CME-55 DRILLER	MC
				mpletio	on		Y	Jul. 2000ce	ior Geor	pechnical and Materials Engineering APPROVED JJZ JOB# D14G1	

	DEU		IFORM <i>A</i>	TION		Dr	age 1	of 1		1.0	OG OF BO	ORING N	<u> </u>	B-10		
		JLE IIV	IFORIVIA		_	г	ige i	01 1								
	ATION	_		OFFSE					PRO	OJECT NAME	Proposed Ka	ansas Energ	y & S	ervice Ce	nter	
	ORTHIN			EAS					SIT		SW 7th Stre Topeka, Kai		Buren	Street		
				eoSource			- 4	-4-	OW	/NER / ARCHITEC	•	Kansas / HT	K Arc	hitects		
ME	THOD	4-inc	n Filgnt	Augers		HAMME T	R A	uto	-							
	PE		NO		_	%	占	90	نډا	Offset 4 fe	eet east due to	o parked cai	rs			
SAMPLE NO	SAMPLE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	GRAPHIC LOG	DEPTH, Feet.		MATE	RIAL DESCI	RIPTIO	NC		
MPL	MPL	0	AND	NEN'S	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	OIST	NE S	ZAPF	PT.							
S	S	8	R R R	228	P. S.	ĭŏ	58	GF	B			Approx. Sur	face E	Elevation	:	927.6
											altic Concret Revers	te (4")				
	PA								-	- Brick	R Pavers					
									-	FILL	<u>,</u> lean to fat common, trace gra	lay, medium	stiff, d	ark gray		
										mis	scellaneous co	onstruction de	ebris	ша		
1	ST	6		*1500	98	26.5	CL CH		-	1						
							Сп		5 -	-						
									-							
	PA								-	6.8						920.8
									_	FAT	CLAY, very	stiff light or:	avish t	an mottlec	1	
										rus		stiii, iigiit git	uy1511 t	un mottree	•	
2	SS	18	10	*4500		17.1	СН		-	_						
						-,,,			10 -	1						
	PA									11.4						016.2
										11.4 12.0 ** LI	MESTONE,	hard, gray				916.2 915.6
										AUG	ER REFUSA	AL @ 12 O F	TET			
												O				
										**Roc cha	ck classificati aracteristics ar	on is based o nd visual obs	ın drıll ervatio	ing on of		
											turbed sample ner rock types.		ıples m	nay reveal		
										Oth	ici rock types.					
* Ca	ibratod	I Dono	 trometer	** =	Cock Str	onath ir	nei	1								
Ca							•	 te boun	 dary line	 es between soil ar	ınd rock types. Ir	n-situ the transit	tion may	/ be gradual.		
WA	TER	LEVE	L OBS	SERVAT	IONS	;						BORING STAR	TED	12-18	3-14	
Ā	Dry	W.D.					(7=				BORING COMP	LETED	12-18	3-14	
Ī	Dry	A.B.					Yr	our Source	e for Gent	cechnical and Materials	Is Engineering	RIG CM	E-55	DRILLER		МС
	Back	cfillec	l @ Co	mpletio	on		10	our our or	J 101 0000	and wide life	anginouting	APPROVED	JJZ	JOB#	D140	31399

В	OREHO	DLE IN	IFORMA	ATION		Pa	age 1	of 1		LOG OF BORING NO. B	3-11	
ST	ATION			OFFSE	Τ				PRO	JECT NAME Proposed Kansas Energy & Serv	vice Center	
NC	ORTHIN	G		EAS	ΓING				SIT	LOCATION SW 7th Street and Van Buren St	treet	
DF	RLLING	COMPA	ANY G	eoSource	e, LLC					Topeka, Kansas		
ME	THOD	4-inc	h Flight	Augers	ı	HAMME	R A	uto	OW	IER / ARCHITECT State of Kansas / HTK Archi	tects	
	ш		z					(J		Offset 6 feet east due to parked cars		
Ŏ.	TYP	Ϋ́	RD ATIO		LISI	RE ∏,%	MBOI	000	Feet.	MATERIAL DESCRIPTION	ı	
SAMPLE NO	SAMPLE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	GRAPHIC LOG	DEPTH, Feet.	WATERIAL DESCRIPTION	•	
SAI	SAI	RE	STA PEN BLC	STR	PCF	§	NOS NOS	GR	l H	Approx. Surface Ele	evation:	929.8
										Asphaltic Concrete (4")		
	PA								-	Brick Pavers		
									- -	<u>FILL</u> , lean clay, medium stiff, dark gray trace fine sand and gravel	brown,	
1	ST	10		1420	97	25.8	CL			trace fine sand and graver		
1	51	10		1420	91	23.6	CL		-			
									5 -			
	PA								-			
	IA								-	7.0		922.8
									-	FAT CLAY, very stiff, light grayish tan	mottled	
									-	rust		
2	SS	18	10	*5500		24.1	СН		10			
									10 -			
	PA								-	11.8		918.0
									-	12.7 **LIMESTONE, hard, gray		917.1
										AUGER REFUSAL @ 12.7 FEET		
										**Rock classification is based on drilling	α	
										characteristics and visual observation	of	
										disturbed samples. Core samples may other rock types.	/ reveal	
* Cal			trometer		Rock Str		•					
14/4							oxima	te bound	dary line	s between soil and rock types. In-situ the transition may be		
WA		W.D.		SERVAT	IUNS	1	-	_		BORING STARTED BORING COMPLETED	12-18-14 12-18-14	
Ā	Dry						Ĺ	JE		DUURUE	12-18-14 DRILLER	MC
			 @ Co	mpletio	on .		Yo	our Source	e for Geot	of initial and ividue has Engineering		G1399

В	OREHO	OLE IN	IFORMA	ATION		Pa	age 1	of 2		LOG OF BORING NO. B-12	
S1	ATION			OFFSE	ΞT				PRO	OJECT NAME Proposed Kansas Energy & Service Center	
N	ORTHIN	G		EAS	TING				SIT	ELOCATION SW 7th Street and Van Buren Street	
DF	RLLING	COMPA	ANY G	eoSource	e, LLC					Topeka, Kansas	
M	ETHOD	4-inc	h Flight	Augers	I	HAMME	R A	uto	OW	NER / ARCHITECT State of Kansas / HTK Architects	
			7					(D		Offset 6 feet east due to parked cars	
Ö	SAMPLE TYPE		3D ATION T.	ONFINED	SITY	T, %	1BOL	GRAPHIC LOG	eet.		
SAMPLE NO	PLE	RECOVERY	NS/F	ONF ENG	DEN		SYN	PHIC	DEPTH, Feet.	MATERIAL DESCRIPTION	
SAM	SAM	REC	STANDARD PENETRATIC BLOWS/FT.	UNCONFINE STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, 9	UNIFIED SOIL SYMBOL	GRA	DEP.	Approx. Surface Elevation:	930.7
									_	Asphaltic Concrete (3")	330.7
									-	Brick Pavers	
	PA								-	FILL, lean to fat clay, medium stiff, dark gray	
									_	brown mixed, trace gravel	
							CL		-		
1	ST	10		1480	98	25.9	CH		-		
									5 -		
									-	6.0	924.7
	PA								-	FAT CLAY, very stiff, light grayish tan mottled	
									_	rust	
	CT	10		4440	107	20.0	CII		-		
3	ST	12		4440	107	20.0	СН		-		
									10 -		
									-	11.0	919.7
	PA								-	** <u>SHALE</u> , weathered, soft, olive tan to light gray	
									-		
4	SS	1	50/1"			6.4			-	13.8	916.9
									1.5	**LIMESTONE, weathered, seamy to	
									15 -	thin-bedded, buff to light gray 16.0	914.7
	PA								-		<i>71</i> 7.7
									-	** SHALE , hard, gray	
									_	18.0 18.6 **LIMESTONE, hard, gray	912.7 912.1
									-	18.0 ENVESTONE, hard, gray	912.1
										AUGER REFUSAL @ 18.6 FEET	
* Ca	librated	l Pene	trometer	· ** F	L Rock Str	ength ir	⊥ n psi	1			
		The str	atification	n lines rep	resent t	the appi	roxima	te bound	dary line	es between soil and rock types. In-situ the transition may be gradual.	
l				SERVAT	TIONS	3				BORING STARTED 12-18-14	
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		W.D.						3E		SOURCE BORING COMPLETED 12-18-14	
Ţ	Dry	A.B.					Yo	our Source	e for Geot	cechnical and Materials Engineering RIG CME-55 DRILLER	MC
	Back	cfillec	1 @ Co	mpletio	on					APPROVED JJZ JOB# D140	G1399

BOREH	OLE IN	FORMA	ATION		Pa	age 2 d	of 2		L	.00	OF B	ORIN	IG I	NO.	B-12		
STATION			OFFSE	T				PRO	DJECT NAME	Pr	oposed K	(ansas	Ener	gy & Se	ervice Co	enter	
NORTHIN	IG		EAS	TING				SITI	E LOCATION		V 7th Str		l Van	Buren	Street		
DRLLING			eoSource	e, LLC				0)4/	NED / ADOLUT		peka, Ka		. / TT	FIZ A	l.:44		
METHOD	4-incl	h Flight	Augers	1	HAMME	R A	uto	OW	NER / ARCHITE	ECI	State of	Kansas	S / H.	IK Arc	nitects		
SAMPLE NO.	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	GRAPHIC LOG	DEPTH, Feet.			MATE	ERIAL [DESC	CRIPTIC	DN		
									d d	hara listur	classificat cteristics a bed samp rock types	and visu les. Co	ıal ob	servatio	n of		
* Calibrated					ength ir the appr		e bound	 dary line	es between soil	l and	rock types.	In-situ th	e trans	sition may	be gradua	l.	
WATER	LEVE	L OBS	ERVAT	TIONS	3							BORIN	G STA	RTED	12-1	8-14	
 	W.D.						SE		Sou	R	CE	BORING	G COM	1PLETED	12-1	8-14	
l -	A.B.								echnical and Mater			RIG		ME-55	DRILLER		МС
∥ Bacl	kfilled	@ Co	mpletio	on								APPRO	VED	JJZ	JOB#	D14	G1399

В	OREHO	OLE IN	IFORM <i>A</i>	ATION		Pa	ige 1	of 2		L	OG OF B	ORING	NO.	B-13	
ST	ATION			OFFSE	T				PRO	OJECT NAME	Proposed K	ansas Ener	gy & So	ervice Ce	nter
NC	ORTHIN	G		EAS ⁻	ΓING				SITE	E LOCATION	SW 7th Stre		n Buren	Street	
DF	RLLING	COMPA	ANY G e	eoSource	e, LLC						Topeka, Ka				
ME	THOD	4-inc	h Flight	Augers	ا	HAMME	R A	uto	OW	NER / ARCHITE	State of]	Kansas / H	TK Arc	hitects	
SAMPLE NO.	SAMPLE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	3RAPHIC LOG	DEPTH, Feet.			RIAL DES			
Š	Š	<u>~</u>	S E B	⊃ \(\oldsymbol{\text{\tin}\text{\tett{\text{\tetx{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\texi}\text{\text{\text{\text{\text{\texi}\text{\text{\texi}\text{\text{\texi}\text{\text{\text{\tet{\text{\text{\text{\text{\text{\texi}\text{\texi}\text{\te		≥υ	⊃٥	Ŋ				Approx. Su	urface E	levation	: 931.9
	PA								- - - -	Bric <u>FIL</u>	haltic Concreck Pavers L, lean to fat cace gravel	. ,	ark gray	brown,	
1	ST	9		2830	104	28.3	СН		- - - 5 -						006
	PA								- - - -	5.5 FAT	ΓCLAY, very	stiff, gray b	orown		926.4
3	SS	18	12	*3500		23.6	СН		10 -	9.5	E CL AV	/:00 11:	1.1		922.4
	PA								- - -	11.8	<u>ΓCLAY</u> , very	stiff, redais	sn brown	1	920.1
									<u>-</u> -	1	HALE, weatherown	ered, soft, o	live tan	to gray	
4	SS	15	56/9"			20.7			-	14.5	IMECTONE		~ ~ ~ ~		917.4
									15 – -	16.0	IMESTONE, nin-bedded, lig	ht gray	seamy u	· · · · · · · · · · · · · · · · · · ·	915.9
	PA								-	** <u>S</u>]	HALE, hard, §	gray			
									-	18.2					913.7
									-	18.7_** <u>L</u>	<u>IMESTONE,</u>	hard, gray			913.2
										AUG	GER REFUSA	AL @ 18.7	FEET		
* Cal	librated	l Pene	trometer	** F	Rock Str	ength ir	n psi								
							•	e bound	dary line	es between soil	and rock types. I	In-situ the tran	sition may	/ be gradual	
	TER	LEVE	L OBS	SERVAT	IONS	;						BORING STA	ARTED	12-18	3-14
Δ	Dry	W.D.	1					SF		SOUR	RCF	BORING CO	MPLETED	12-18	3-14
Ţ	Dry	A.B.					Yo	ur Source	e for Geot	echnical and Materi	ials Engineering	RIG C	ME-55	DRILLER	MC
	Back	cfillec	d @ Co	mpletio	on							APPROVED	JJZ	JOB#	D14G1399


BOREHOLE INFORMATION	ION P	age 2 of 2	L	OG OF BORING NO.	B-13
STATION	OFFSET		PROJECT NAME	Proposed Kansas Energy & S	ervice Center
NORTHING	EASTING		SITE LOCATION	SW 7th Street and Van Burer	Street
	Source, LLC		OMMED / ADOLUTE	Topeka, Kansas	-1.244
METHOD 4-inch Flight A	ugers HAMME	R Auto	OWNER / ARCHITE	State of Kansas / HTK Ar	enitects
SAMPLE NO. SAMPLE TYPE RECOVERY STANDARD PENETRATION BLOWS/FT.	DRY DENSITY PCF MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL GRAPHIC LOG	DEPTH, Feet.	MATERIAL DESCRIPTI	ON
			cl di	ock classification is based on dril naracteristics and visual observati isturbed samples. Core samples is ther rock types.	on of
* Calibrated Penetrometer The stratification lin	** Rock Strength i nes represent the app		ary lines between soil	and rock types. In-situ the transition ma	y be gradual.
WATER LEVEL OBSE	RVATIONS			BORING STARTED	12-18-14
▽ Dry W.D.		GE	o Soul	BORING COMPLETED	12-18-14
▼ Dry A.B.			for Geotechnical and Mater	PIG CME 55	DRILLER MC
Backfilled @ Com	pletion			APPROVED JJZ	JOB# D14G1399


BOREHOLE INFORMATION Page 1 of 1					Pa	age 1	of 1		LOG OF BORING NO. B-14		
ST	ATION	OFFSET				PRO	DJECT NAME Proposed Kansas Energy & Service Center				
NO	ORTHIN	G		EAS ⁻	ΓING				SIT	ELOCATION SW 7th Street and Van Buren Street	
DF	RLLING	COMPA	ANY G e	eoSource	e, LLC					Topeka, Kansas	
ME	THOD	4-inc	h Flight	Augers		HAMME	R A	uto	OW	NER / ARCHITECT State of Kansas / HTK Architects	
SAMPLE NO.	SAMPLE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	3RAPHIC LOG	DEPTH, Feet.	MATERIAL DESCRIPTION	
S .	S	<u> </u>	N L M	⊃ ໙ ໕		≥0	s	U		• •	921.5
	PA								-	Asphaltic Concrete (5")	
1	ST	10		1450	109	21.8	CL		-	FILL, lean to fat clay, medium stiff, light brown, trace fine sand	919.0
	PA								-	FILL , fat clay, medium stiff to stiff, reddish	
2	SS	18	5	*2000		18.5	СН		- - -	brown, dark brown and brown layers, trace gravel	
	PA								5 - - - - -		
3	SS	18	6	*2500		36.5	СН		10-		
									-	11.3	910.2
	PA								-	**LIMESTONE, weathered, seamy	
	111								_	**SHALE weethered geft ton	909.1
									-	13.2	908.3 907.8
										**Rock classification is based on drilling characteristics and visual observation of disturbed samples. Core samples may reveal other rock types.	
* Cal			trometer atification			rength ir	•	te bound	dary line	es between soil and rock types. In-situ the transition may be gradual.	
WA				SERVAT			SAIL LIG	. Journ	~~ı y 1111C	BORING STARTED 12-19-14	
Σ	Dry						_			BORING COMPLETED 12-19-14	
Ţ	Dry						Ĺ	フヒ	U	DURLE RIG CME SE DRILLER	MC
Backfilled @ Completion			our Source	ior, Reot	echinical and Makerials Engineering	1399					

BOREHOLE INFORMATION Page 1 of 1						Pa	age 1	of 1		LOG OF BORING NO. B-15	
ST	ATION			OFFSE	T				PRO	DJECT NAME Proposed Kansas Energy & Service Center	
NO	ORTHIN	G		EAST	ΓING				SITI	ELOCATION SW 7th Street and Van Buren Street	
DF	RLLING	COMPA	NY G e	oSource	e, LLC					Topeka, Kansas	
M	ETHOD	4-inc	h Flight	Augers		HAMME	R A	uto	OW	NER / ARCHITECT State of Kansas / HTK Architects	
SAMPLE NO.	SAMPLE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	GRAPHIC LOG	DEPTH, Feet.	MATERIAL DESCRIPTION	20.2
0,	0,		07 E E	300 E		20	5 %			• •	20.2
	PA								-	Ţ	
1	SS	18	14	*1000		19.7	CL CH		- - -	FILL, lean to fat clay, soft, to medium stiff, dark gray brown, tan and brown mixed, with some gravel and miscellaneous construction rubble	
	PA	1.4	55/011			27.4	CL		-		
2	SS	14	55/8"			27.4	СН		5 –	4.7	15.5
	PA								-	RUBBLE FILL, brick, cinders, limestone or concrete debris in a clay matrix	013.7
										AUGER REFUSAL @ 6.5 FEET	
* Ca			rometer			rength in					
WA				lines rep			roximat	te bound	dary line	es between soil and rock types. In-situ the transition may be gradual. BORING STARTED 12-18-14	
VV		feet \		LIVAI	IONS	•	_			201-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-	
<u> </u>									_	PIG CME-55 DRILLER N	MC
▼ 0.8 feet A.B. Backfilled @ Completion				Yo	our Source	e ror Geot	echnical and Materials Engineering APPROVED JJZ JOB # D14G1				

BOREHOLE INFORMATION Page 1 of 1					Pa	age 1	of 1		LOG OF BORING NO. B-16		
ST	ATION			OFFSE	T				PRO	DJECT NAME Proposed Kansas Energy & Service Center	
NC	PRTHIN	G		EAS ⁻	ΓING				SITE	ELOCATION SW 7th Street and Van Buren Street	
DF	RLLING	COMPA	ANY G	eoSourc	e, LLC					Topeka, Kansas	
ME	THOD	4-inc	h Flight	Augers	ا	HAMME	R A	uto	OW	NER / ARCHITECT State of Kansas / HTK Architects	
SAMPLE NO.	SAMPLE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	3RAPHIC LOG	DEPTH, Feet.	MATERIAL DESCRIPTION	
0,		ш.	ОЛЕ Ш	J 00 IL		20	00			Approx. Surface Elevation: S Asphaltic Concrete (5")	929.0
	PA								-	Asphaluc Concrete (5')	
1	ST	8		5990	106	13.4	CL		- - -	FILL, lean clay, very stiff, light brown, trace fine sand	926.5
2	ST	13		4570	105	22.9	CL CH		- - -	FILL, lean to fat clay, very stiff, brown	
	PA								5 - - - -	FAT CLAY, very stiff, light brown to gray brown mottled rust and light gray	923.5
3	SS	18	8	*4500		20.6	СН		- - 10 –	10.0	919. <u>0</u>
* Cal	ibrated	Pene	trometer	** F	Rock Str	ength ir	n psi			BOTTOM OF BORING	
							oximat	te bound	dary line	es between soil and rock types. In-situ the transition may be gradual.	
				SERVA1	TIONS)		_		BORING STARTED 12-18-14	
<u>Ā</u>	Dry							3E		BORING COMPLETED 12-18-14	
Ţ	Dry	A.B.					Yo	our Source	e for Geot	echnical and Materials Engineering RIG CME-55 DRILLER	MC
Backfilled @ Completion							APPROVED JJZ JOB# D14G	1399			

	UNII	FIED SOIL CLAS	SIFICATION (AS	TM D-24	187-98)	
MATERIAL TYPES	CRITER	RIA FOR ASSIGNING SOIL GI	ROUP NAMES	GROUP SYMBOL	SOIL GROUP NAMES & LEGE	:ND
	GRAVELS	CLEAN GRAVELS	Cu>4 AND 1 <cc<3< td=""><td>GW</td><td>WELL-GRADED GRAVEL</td><td></td></cc<3<>	GW	WELL-GRADED GRAVEL	
LS.	>50% OF COARSE	<5% FINES	Cu>4 AND 1>Cc>3	GP	POORLY-GRADED GRAVEL),
SOILS D ON /E	FRACTION RETAINED ON NO 4. SIEVE	GRAVELS WITH FINES	FINES CLASSIFY AS ML OR CL	GM	SILTY GRAVEL	
COARSE-GRAINED 8 >50% RETAINED 0 NO. 200 SIEVE		>12% FINES	FINES CLASSIFY AS CL OR CH	GC	CLAYEY GRAVEL	
E-GR. RET	SANDS	CLEAN SANDS	Cu>6 AND 1 <cc<3< td=""><td>sw</td><td>WELL-GRADED SAND</td><td>•</td></cc<3<>	sw	WELL-GRADED SAND	•
ARSE >50% NC	>50% OF COARSE	<5% FINES	Cu>6 AND 1>Cc>3	SP	POORLY-GRADED SAND	. ö ö.
8 ^	FRACTION PASSES ON NO 4. SIEVE	SANDS AND FINES	FINES CLASSIFY AS ML OR CL	SM	SILTY SAND ::	
		>12% FINES	FINES CLASSIFY AS CL OR CH	SC	CLAYEY SAND	
	SILTS AND CLAYS	INODCANIC	PI>7 AND PLOTS>"A" LINE	CL	LEAN CLAY	
SOILS ES VE	LIQUID LIMIT<50	INORGANIC	PI>4 AND PLOTS<"A" LINE	ML	SILT	
		ORGANIC	LL (oven dried)/LL (not dried)<0.75	OL	ORGANIC CLAY OR SILT	
3RAII 0% P 0. 200	SILTS AND CLAYS	INODCANIC	PI PLOTS >"A" LINE	СН	FAT CLAY	
FINE-GRAINED >50% PASS NO. 200 SIE	LIQUID LIMIT>50	INORGANIC	PI PLOTS <"A" LINE	МН	ELASTIC SILT	Ш
"		ORGANIC	LL (oven dried)/LL (not dried)<0.75	ОН	ORGANIC CLAY OR SILT	
HIGHLY C	RGANIC SOILS	PRIMARILY ORGANIC MATTER, DARK IN	I COLOR, AND ORGANIC ODOR	PT	PEAT	<u>, </u>





BEDROCK PROPERTIES & DESCRIPTIONS

ROCK QUALIT	Y DESIGNATION	BEDDING CHA	RACTERISTICS
DESCRIPTION	RQD (%)	<u>TERM</u>	THICKNESS (inches)
Very Poor	0 - 25	Massive	> 60
Poor	25 - 50	Very Thick Bedder	d 36 - 60
Fair	50 - 75	Thick Bedded	12 - 36
Good	75 - 90	Medium Bedded	4 - 12
Excellent	90 -100	Thin Bedded	1 - 4
		Very Thin Bedded	0.4 - 1
DEGREE OF W	EATHEDING	Laminated	< 0.4

Slightly Weathered - Slight decomposition of Parent material in joints and seams. Weathered - Well-developed and decomposed joints and seams. Highly Weathered - Rock highly decomposed, may be extreemly broken.

BEDROCK DISCONTINUITIES

Bedding Planes Planes dividing the individual layers, beds or strata of rocks. Fractures in rock, generally more or less vertical to the bedding. Joints Seams Applies to bedding planes with an unspecified degree of weathering.

PENETRATION RESISTANCE (RECORDED AS BLOWS / 0.5 FT)								
SAND & 0	GRAVEL		SILT & CLAY					
RELATIVE DENSITY	BLOWS/FOOT*	CONSISTENCY	BLOWS/FOOT*	COMPRESSIVE STRENGTH (TSF)				
VERY LOOSE	0 - 4	VERY SOFT	0 - 2	0 - 0.25				
LOOSE	4 - 10	SOFT	2 - 4	0.25 - 0.50				
MEDIUM DENSE	10 - 30	MEDIUM STIFF	4 - 8	0.50 - 1.0				
DENSE	30 - 50	STIFF	8 - 15	1.0 - 2.0				
VERY DENSE	OVER 50	VERY STIFF	15 - 30	2.0 - 4.0				
		HARD	OVER 30	OVER 4.0				

^{*} NUMBER OF BLOWS OF 140 LB HAMMER FALLING 30 INCHES TO DRIVE A 2 INCH O.D. (1-3/8 INCH I.D.) SPLIT-BARREL SAMPLER THE LAST 12 INCHES OF AN 18-INCH DRIVE (ASTM-1586 STANDARD PENETRATION TEST).



General Notes and Terms

BORING LOG SYMBOLS

SURFACE MATERIALS

COHESIVE SOILS

LARGE GRANULAR SOILS



TOPSOIL



SILT



CLAYEY GRAVEL



FILL MATERIAL



CLAYEY SILT



SILTY GRAVEL



ASPHALTIC CONCRETE



LEAN CLAY



POORLY GRADED GRAVEL



CONCRETE



LEAN TO FAT CLAY



WELL GRADED GRAVEL



GRANULAR BASE





COBBLES & BOULDERS

GRANULAR SOILS





SHALE

BEDROCK UNITS



JOINT OR VOID

WEATHERED BEDROCK



SILTY SAND



FISSILE SHALE



WEATHERED SHALE



FINE SAND



SANDSTONE



WEATHERED SANDSTONE



POORLY GRADED SAND



LIMESTONE



WEATHERED LIMESTONE



WELL GRADED SAND





GRAVELLY SAND



Annual Qualifications 2014

	idai Qualifications i					ncilla
No.	Firm Name	Contact	e-mail address	Phone Number	Location	Geotechnical
1	Alfred Benesch & Company	Chris Burns	cburns@benesch.com	913-213-5143	Manhattan	Х
4	APEX Environmental Consultants,	Christopher S. Frey	cfrey@4apex.com	913-338-2739	Lenexa	Х
16	Cook Flatt & Strobel Engineers, P.	Robert S. Chambers	chambers@cfse.com	785-272-4706	Topeka	Х
25	GeoSource, LLC	Axel Novion	anovion@geosourceeng.com	816-326-8751	Topeka	Х
31	HNTB Corporation	Michael R. Hess	mhess@hntb.com	816-472-1201	Kansas City, MO	Х
32	HNTB Corporation	Michael R. Hess	mhess@hntb.com	913-491-1333	Overland Park	Х
38	Kaw Valley Engineering, Inc.	Keith Beatty	beatty@kveng.com	620-208-5240	Emporia	Х
39	Kaw Valley Engineering, Inc.	Leon Osbourn	ldo@kveng.com	785-762-5040	Junction City	Х
40	Kaw Valley Engineering, Inc.	Coby Crowl	cobyc@kveng.com	816-468-5858	Kansas City, MO	Х
41	Kaw Valley Engineering, Inc.	Gary Leeds	<u>Leeds@kveng.com</u>	913-894-5150	Lenexa	X
42	Kaw Valley Engineering, Inc.	Bill Delker	delker@kveng.com	785-823-3400	Salina	X
66	Olsson Associates	Sterling Cramer	scramer@olssonassociates.com	913-381-1170	Holdrege, NE	X
69	Olsson Associates	Sterling Cramer	scramer@olssonassociates.com	913-381-1170	Lincoln, NE	X
72	Olsson Associates	Sterling Cramer	scramer@olssonassociates.com	913-381-1170	Olathe	Х
73	Olsson Associates	Sterling Cramer	scramer@olssonassociates.com	913-381-1170	Omaha, NE	X
83	Professional Engineering Consulta	Greg Schunk	Greg.Schunk@pec1.com	316-262-2691	Wichita	X
84	Professional Engineering Consulta		Mike.Berry@pec1.com	785-233-8300	Topeka	X
85	Professional Engineering Consulta	Jarrod E. Mann	Jarrod.Mann@pec1.com	785-842-6464	Lawrence	X
86	Professional Engineering Consulta	Bruce D. Remsberg	Bruce.Remsberg@pec1.com	620-235-0195	Pittsburg	X
96	Simpson Gumpertz & Heger, Inc.	Neal S. Anderson	NSAnderson@sgh.com	847-648-6025	Waltham, MA	X

DEPARTMENT OF ADMINISTRATION
OFFICE OF FACILITIES & PROCUREMENT MANAGEMENT
DESIGN & CONSTRUCTION
800 S.W. JACKSON, SUITE 700 TOPEKA, KANSAS 66612
PHONE: 785.296.8899 FAX: 785.296.3456

PROJECT #:

PROJECT TITLE

AGENCY NAME

BUILDING NUMBER(S)

DATE IINSERT DATE: DRAWN BY [INSERT NAME]

SHEET CONTENT

A-000000

SHEET NO.

ORIGINAL CONTRACT
DOCUMENTS

DEPARTMENT OF ADMINISTRATION

OFFICE OF FACILITIES & PROCUREMENT MANAGE

DESIGN & CONSTRUCTION

800 S.W. JACKSON, SUITE 700 TOPEKA, KANSAS 66612

PHONE: 785.296.8899 FAX: 785.296.3456

SHEET CONTENT

A - 000000

SHEET NO. ORIGINAL CONTRACT DOCUMENTS

JCSBC 02-02-2016 Att.9E.--058

Ф #

DEPARTMENT OF ADMINISTRATION
OFFICE OF FACILITIES & PROCUREMENT MANAG
DESIGN & CONSTRUCTION
800 S.W. JACKSON, SUITE 700 TOPEKA, KANSAS 66612
PHONE: 785.296.8899 FAX: 785.296.3456

ORIGINAL CONTRAC DOCUMENTS JCSBC 02-02-2016 Att.9E.--059

SHEET CONTENT

A - 000000


SHEET NO.

DRAWN BY [INSERT NAME]


DATE],


PROJECT #:
PROJECT TITLE
AGENCY NAME
BUILDING NUMBER(S)

 \Box



JCSBC 02-02-2016 Att.9E.--060





NEW ENERGY & SERVICE FACILITY - BORING LOCATIONS
NOT TO SCALE

JCSBC 02-02-2016 Att.9E.--062

Annual Qualifications 2014

	idai Qualifications i					ncilla
No.	Firm Name	Contact	e-mail address	Phone Number	Location	Geotechnical
1	Alfred Benesch & Company	Chris Burns	cburns@benesch.com	913-213-5143	Manhattan	Х
4	APEX Environmental Consultants,	Christopher S. Frey	cfrey@4apex.com	913-338-2739	Lenexa	Х
16	Cook Flatt & Strobel Engineers, P.	Robert S. Chambers	chambers@cfse.com	785-272-4706	Topeka	Х
25	GeoSource, LLC	Axel Novion	anovion@geosourceeng.com	816-326-8751	Topeka	Х
31	HNTB Corporation	Michael R. Hess	mhess@hntb.com	816-472-1201	Kansas City, MO	Х
32	HNTB Corporation	Michael R. Hess	mhess@hntb.com	913-491-1333	Overland Park	Х
38	Kaw Valley Engineering, Inc.	Keith Beatty	beatty@kveng.com	620-208-5240	Emporia	Х
39	Kaw Valley Engineering, Inc.	Leon Osbourn	ldo@kveng.com	785-762-5040	Junction City	Х
40	Kaw Valley Engineering, Inc.	Coby Crowl	cobyc@kveng.com	816-468-5858	Kansas City, MO	Х
41	Kaw Valley Engineering, Inc.	Gary Leeds	<u>Leeds@kveng.com</u>	913-894-5150	Lenexa	X
42	Kaw Valley Engineering, Inc.	Bill Delker	delker@kveng.com	785-823-3400	Salina	X
66	Olsson Associates	Sterling Cramer	scramer@olssonassociates.com	913-381-1170	Holdrege, NE	X
69	Olsson Associates	Sterling Cramer	scramer@olssonassociates.com	913-381-1170	Lincoln, NE	X
72	Olsson Associates	Sterling Cramer	scramer@olssonassociates.com	913-381-1170	Olathe	X
73	Olsson Associates	Sterling Cramer	scramer@olssonassociates.com	913-381-1170	Omaha, NE	X
83	Professional Engineering Consulta	Greg Schunk	Greg.Schunk@pec1.com	316-262-2691	Wichita	X
84	Professional Engineering Consulta		Mike.Berry@pec1.com	785-233-8300	Topeka	X
85	Professional Engineering Consulta	Jarrod E. Mann	Jarrod.Mann@pec1.com	785-842-6464	Lawrence	X
86	Professional Engineering Consulta	Bruce D. Remsberg	Bruce.Remsberg@pec1.com	620-235-0195	Pittsburg	X
96	Simpson Gumpertz & Heger, Inc.	Neal S. Anderson	NSAnderson@sgh.com	847-648-6025	Waltham, MA	X

GEOTECHNICAL ENGINEERING REPORT

Proposed Kansas Energy and Service Center SW 7th Street and SW Van Buren Street Topeka, Kansas

Project No. D14G1399

December 31, 2014

Prepared for:

Kansas Department of Administration HTK Architects, PA

Prepared by:





December 31, 2014

Ms. Ramona A. Flower State of Kansas Office of Facilities & Procurement Management 800 SW Jackson Street, Suite 600 Topeka, Kansas 66612-1216

Subject: Geotechnical Engineering Report

Proposed Kansas Energy and Service Center SW 7th Street and SW Van Buren Street

Topeka, Kansas Project No. D14G1399

Dear Ms. Flower:

We have completed the subsurface exploration and geotechnical engineering evaluation for the above referenced project. The purpose of the exploration was to obtain information on the subsurface conditions within the building site and, based on this information to provide geotechnical engineering recommendations for design and construction of foundations for the proposed structures.

In summary, the borings encountered existing fill and naturally deposited soils underlain by shale and limestone bedrock that continued to the depths explored. The existing fill was quite variable and contained some rubble. Because of this, we have recommended that the proposed building be supported on drilled pier foundations that extend through the fill to the underlying limestone bedrock.

This report completes our current scope of services for this project. The enclosed report describes our exploration procedures and presents the results of the testing and evaluation along with design and construction recommendations for this project. We appreciate the opportunity to work with you on this project and are prepared to provide the recommended construction services.

Respectfully submitted,

GeoSource, LLC

8574

John J. Zey, P.E.

Kansas: 8574

Axel S. Novion, P.E.

Kansas: 15390

Cc: Mr. Dennis A. Haugh, AIA - HTK Architects, PA

Mr. Clark Basinjer, PE – Bob D. Campbell & Company



TABLE OF CONTENTS

<u>SECTION</u>	PAGE
INTRODUCTION	1
PROJECT DESCRIPTION	1
DRILLING AND SAMPLING PROCEDURES	2
LABORATORY TESTING PROGRAM	4
SITE CONDITIONS	5
SUBSURFACE CONDITIONS	6
GROUNDWATER OBSERVATIONS	8
CONCLUSIONS AND RECOMMENDATIONS	9
SITE PREPARATION	11
CLIMATE CONDITIONS	13
EXCAVATIONS	13
STRUCTURAL FILL	14
FOUNDATIONS	15
DRILLED PIER FOUNDATIONS	15
GEOPIER FOUNDATION SYSTEM	18
SEISMIC HAZARDS DETERMINATION	19
BUILDING FLOOR SLABS	20
LATERAL EARTH PRESSURES	22
PAVEMENTS	23
PLANS AND SPECIFICATIONS REVIEW	24
CONSTRUCTION OBSERVATION AND TESTING	25
LIMITATIONS	25

APPENDIX

Figure 1: Boring Location Sketch Figure 2: Generalized Subsurface Profile Boring Logs

General Notes and Terms

Boring Log Symbol

GEOTECHNICAL ENGINEERING REPORT

PROPOSED ENERGY AND SERVICE CENTER

SW 7TH STREET AND SW VAN BUREN STREET

TOPEKA, KANSAS

Project No. D14G1399 December 31, 2014

INTRODUCTION

GeoSource has completed the subsurface exploration and geotechnical engineering evaluation of the

site for the proposed Kansas Energy and Service Center building, which is located southeast of the

intersection of SW 7th Street and SW Van Buren Street in Topeka, Kansas. Our services for this

project were provided in general accordance with our November 26, 2014 proposal. The

exploration work was authorized on December 4, 2014 with the issuance of Purchase Order No.

17300-000017324 by the Kansas Department of Administration.

PROJECT DESCRIPTION

We understand that the proposed building will be a two story, steel frame structure, with metal stud

infill walls and brick veneer or stone panel exterior facing. The new building will have overall plan

dimensions of approximately 120 by 160 feet. Maximum column loads for the new building were

estimated by the Structural Engineer to be less than 260 kips. The finished floor elevation of the

new building has tentatively been set at elevation 928.76 feet, USGS datum. The floor for the

service base on the east side of the building will be stepped to follow the grade of the existing alley.

The floor slab elevation at the northeast corner of the building will be at elevation 925.54 feet, the

floor slab elevation at the southeast corner will be at 928.76 feet, and the intermediate floor slab

elevation will be at 927.04 feet. The bottom of the elevator pit has tentatively been set at elevation

924.76 feet. At this proposed floor elevation up to 6 feet of new fill will be required to establish

grades for the proposed building area.

Light duty parking lots are planned for the areas on the north and south sides of the new building.

The parking lots will provide space for about 40 automobiles and other light personnel vehicles.



Drives will connect the parking lots to SW 7th Street and/or to the existing alley. No other specific information was provided regarding the design life of the pavement section.

A new utility tunnel will extend from the proposed Energy and Service Center building to the Kansas Statehouse along SW Van Buren Street. The plan and profile drawing of the tunnel that was provided to GeoSource indicated that the bottom of the tunnel will extend to about elevation $912 \pm$ feet at the proposed building site and will be at about elevation $915 \pm$ feet at the Statehouse parking garage. The tunnel will have a height of about $8 \pm$ feet and will be constructed of reinforced concrete.

The scope of the exploration and engineering evaluation for this study, as well as the conclusions and recommendations in this report, were based on our understanding of the project as described above. If pertinent details of the project have changed or otherwise differ from our descriptions, we must be notified and engaged to review the changes and modify our recommendations, if needed.

DRILLING AND SAMPLING PROCEDURES

The field work for this project was performed between December 17 and 19 of 2014. A total of sixteen exploratory test borings were drilled for this project. Figure 1 in the Appendix shows the approximate locations of the borings with reference to the proposed building lines and other site features. The boring locations were established by GeoSource personnel. Distances from the existing city streets and other reference features to the boring locations were measured using a calibrated wheel. Right angles for locating the borings were estimated. The ground surface elevations shown on the boring logs are approximate and were determined using an engineer's level and rod. The elevations were referenced to the rim of the existing storm water manhole (SWMH), located on the west side of SW Van Buren Street about 165 feet south of SW 7th Street. The elevation of the manhole was given as 924.49 feet, USGS datum, on the site plan that was provided to GeoSource. The locations and elevations of the borings should be considered accurate only to the degree implied by the methods used to make these measurements.



The borings were performed with a truck-mounted, rotary drill rig using 4-inch diameter flight augers to advance the boreholes. Representative samples of the overburden soils and bedrock units were obtained at selected intervals using the Shelby tube and split-barrel sampling procedures as outlined in ASTM Specifications D-1587 and D-1586, respectively. The Shelby tube sampling procedure utilizes a thin-walled, steel tube with a sharp cutting edge that is pushed hydraulically into the bottom of the boring to obtain relatively undisturbed samples of cohesive or moderately cohesive soils. The samples were sealed and returned to our laboratory for further examination, classification and testing.

The split-barrel sampling procedure utilizes a standard 2-inch O.D. split-barrel sampler that is driven into the bottom of the boring with an automatic hammer. The number of blows required to advance the sampler the last 12 inches of a normal 18-inch penetration is recorded as the Standard Penetration Resistance Value (N). These "N" values are indicated on the boring logs at their depth of occurrence and provide an indication of the consistency of clays and the relative hardness of weathered bedrock units. A higher efficiency is achieved with the automatic hammer compared to the conventional safety hammer operated with a cathead and rope. This higher efficiency has an appreciable effect on the Standard Penetration Resistance Values (N). The effect of the automatic hammer's efficiency has been considered in the interpretation and analysis of the subsurface information for this report.

Borings B-2 and B-4 were continued below the point of auger refusal through use of NQ3-diamond bit coring procedures. This diameter core barrel provides a sample having a diameter that is slightly smaller than 2 inches. Descriptions of the rock core are presented on the respective boring logs in addition to recovery and Rock Quality Designation (RQD) for the core recovered. Recovery is defined as the length of core obtained expressed as a percentage of the total length cored. Rock Quality Designation is defined as the total length of core pieces, 4 inches or greater in length, expressed as a percentage of the total length cored. Rock Quality Designation provides an indication of the integrity of the rock mass and relative extent of seams and bedding planes.



Boring logs are included in the Appendix of this report and present such data as soil and bedrock descriptions, consistency and relative hardness evaluations, depths, sampling intervals and observed groundwater conditions. Conditions encountered in each of the borings were monitored and recorded by the drill crew. Field logs were prepared by the drill crew that included visual classification of the materials encountered during drilling, as well as drilling characteristics. Our final boring logs represent the geotechnical engineer's interpretation of the field logs combined with laboratory observation and testing of the samples. Stratification boundaries indicated on the boring logs were based on observations during our field work, an extrapolation of information obtained by examining samples from the borings and comparisons of soils and/or bedrock types with similar engineering characteristics. Locations of these boundaries are approximate, and the transitions between soil and bedrock types may be more gradational in nature rather than clearly defined.

LABORATORY TESTING PROGRAM

The laboratory testing program consisted of performing water content, dry unit weight and unconfined compression tests on representative portions of undisturbed samples obtained with the Shelby tube sampler. A calibrated hand penetrometer was used to determine the approximate unconfined compressive strength of samples that were deformed or otherwise unsuitable for unconfined compression testing. The hand penetrometer has been correlated with unconfined compression tests, and provides a better estimate of the consistency and strength than visual observation alone. Moisture content determinations were also performed on samples obtained using the split-barrel sampler. The results of the laboratory tests are presented on the respective boring logs.

Atterberg Limits tests were conducted on representative samples of the onsite soils. These tests provide information on the plasticity of the soil, which is a basis for soil classification and for estimating the potential of subgrade soils to change volume with variations in moisture content. Results of these tests are also indicated on the respective boring logs.

In addition, unconfined compression tests were performed on selected rock cores to evaluate the compressive strength of the bedrock units encountered in the borings. The results of the unconfined



compression tests are shown on the respective boring logs in the Appendix of this report. The unconfined compressive strengths are in psi (pounds per square inch).

As part of the testing program, the soil samples were classified by a geotechnical engineer using visual and manual procedures outlined in ASTM D-2487 and D-2488. The descriptions of the soils indicated on the boring logs are in accordance with the enclosed General Notes and the Unified Soil Classification System. Estimated group symbols according to the Unified Soil Classification System are shown on the boring logs. A brief description of this classification system is included in the Appendix of this report.

The bedrock units encountered in the borings were described in accordance with the enclosed General Notes for Bedrock on the basis of visual classification of disturbed auger cuttings and drilling characteristics. Core samples may reveal other rock types.

SITE CONDITIONS

The proposed building site is located southeast of the intersection of SW 7th Street and SW Van Buren Street in Topeka, Kansas. The site was bounded on the north by SW 7th Street, on the west by SW Van Buren Street and on the east by an existing alley. At the time the borings were performed, the site was a paved parking lot. Historical photographs indicated that the site was previously occupied by a power plant and several other buildings in the past. The borings encountered undocumented clay fill, most of which contained variable amounts of bricks, cinders, gravel and other miscellaneous construction debris from the former buildings. Auger refusal was encountered on rubble at boring locations B-8 and B-15, suggesting that buried foundations or basement walls and slabs or large concrete or limestone fragments are buried beneath portions of the proposed building site. At Boring B-2, a strong fuel odor was detected in the undocumented fill encountered between depths of about 5 to 10.3 feet.



SUBSURFACE CONDITIONS

The following presents a general summary of the major strata encountered during our subsurface exploration and includes a discussion of the results of field and laboratory tests conducted. Specific subsurface conditions encountered at the boring locations are presented on the individual boring logs in the Appendix of this report. Figure 2 in the Appendix shows a Generalized Subsurface Profile, based on the information obtained from the borings. The stratification lines shown on the boring logs and profile represent the approximate boundaries between soil and bedrock types; insitu, the transition between materials may be more gradational in nature rather than clearly defined.

All of the borings were drilled in paved areas and encountered about 3 to 5 inches of asphaltic concrete pavement at the surface. Borings B-10 through B-13 were drilled on SW Van Buren Street along the alignment of the proposed utility tunnel and encountered brick pavers below the asphalt pavement.

The pavement section was underlain by undocumented fill that continued to depths of about 5.5 to 14.3 feet below the existing ground surface at the boring locations. The upper 2-½ to 3 feet of the fill was generally comprised of medium stiff to very stiff, light brown lean clay (CL), with a trace of fine sand. Laboratory tests performed on samples of this lean clay fill indicated moisture contents in the range of 13.4 to 25.6 percent, with dry densities of 102 to 115 pcf and unconfined compressive strengths of 1,450 to 5,990 psf. Atterberg Limits performed on this material indicated Liquid Limits in the range of 34 to 39, with Plasticity Indices of 15 to 20.

Beneath the upper fill layer, the borings encountered moderate to high plasticity fill that contained variable amounts of brick, cinders, gravel and other miscellaneous construction debris. No significant amounts of wood, trash or other unsuitable materials were encountered at the boring locations. As previously discussed, fuel contaminated soils were encountered in Boring B-2 below a depth of about 5 feet. In addition, significant amounts of rubble, including large size debris were encountered in Borings B-7, B-8 and B-15. Buried obstructions within the rubble fill were encountered in Borings B-8 and B-15. These obstructions could be buried foundation or large size



fragments of concrete or limestone. Laboratory tests performed on samples of the undocumented fill indicated moisture contents in the range of 11.4 to 55.7 percent, with dry densities of 97 to 106 pcf and unconfined compressive strengths of 1,420 to 5,300 psf. Standard Penetration Tests performed in the existing fill yielded "N" values ranging from 4 to 76 blows for one foot of penetration or less.

The undocumented fill was underlain by naturally deposited clay soils at 9 of the 16 boring locations. The natural clay soils were deposited by glacial ice that covered northeast Kansas in the Pleistocene Period. The glacial soils were visually classified as stiff to very stiff, lean clays (CL) and fat clays (CH). Laboratory tests performed on samples of the natural clay soils indicated moisture contents in the range of 17.1 to 28.0 percent, with dry densities of 102 to 107 pcf and unconfined compressive strengths of 2,050 to 4,440 psf. Soil colors varied from brown to light brown to reddish brown, with light gray and rust mottling. Standard Penetration Tests performed in the natural clay soils yielded "N" values in the range of 7 to 12 blows for one foot of penetration or less.

The undocumented fill and naturally deposited glacial clay soils were underlain by interbedded layers of shale and limestone bedrock that are part of the Topeka Limestone Formation of the Pennsylvanian Age Shawnee Group. The bedrock was encountered in the borings at depths ranging from about 10.3 to 14.3 feet across the proposed building site. The uppermost bedrock unit encountered was the weathered remnants of the Turner Creek Shale Member. The Turner Creek Shale is typically 2 to 5 feet thick and consists of weathered, olive tan to gray brown, clayey to silty shale. The Turner Creek Shale was underlain by the Sheldon Limestone Member. The Sheldon Limestone was described as a buff to light gray, fossiliferous limestone. The thickness of this limestone unit varied from about 1.5 feet to 2.8 feet across the site. The Jones Point Shale Member was encountered below the Sheldon Limestone and this bedrock unit typically consists of gray, silty to clayey shale that was about 1.8 to 2.2 feet thick at the boring locations where it was encountered.

The Jones Point Shale was underlain by the Curzon Limestone, which is the thickest limestone unit of the Topeka Formation. The Curzon Member is typically comprised of two or more beds of medium to thick-bedded, buff to light gray, fossiliferous limestone. The thickness of the Curzon



Limestone ranged from about 5.9 to 6.3 feet at the boring locations where it was encountered. The Curzon Member was underlain by the Iowa Point Shale Member. The Iowa Point Member is typically a hard, gray, clayey to silty shale that locally contains sandstone layers. At the proposed building site, the Iowa Point Shale had a thickness of only about 1 to 2 feet. The Iowa Point Shale was underlain by the Hartford Limestone Member, which is the basal member of the Topeka Limestone Formation. The Hartford Member typically has a total thickness of about 5 to 6 feet and consisted of massive, gray to bluish gray, fossiliferous limestone. Core samples of the bedrock from Borings B-2 and B-4 had recovery rates of 78 to 100 percent, with Rock Quality Designation (RQD) values in the range of 56 to 100 percent, indicating fair to good quality rock. The unconfined strength of the limestone units ranged from about 1,970 to 9,520 psi.

GROUNDWATER OBSERVATIONS

Groundwater observations were made in the boreholes both during and following completion of the drilling operations. Groundwater was encountered in Borings B-1, B-5, B-9 and B-15 at depths ranging from about 0.5 to 12.0 feet below the existing ground surface. At Boring B-15, groundwater was encountered very near the existing ground surface. The other borings remained, dry prior to coring, and no visible groundwater seepage was observed at the time the borings were performed.. The materials encountered in the test borings have relatively low permeabilities and observations over an extended period of time through use of piezometers or cased borings would be required to better define current groundwater conditions.

Coring of the bedrock at boring locations B-2 and B-4 required the introduction of water into the borehole as a drilling fluid to cool the bit and to flush the cuttings from the hole. No noticeable loss of drilling fluid was noted. The water levels indicated on the boring logs where coring procedures were used represent the water level in the borings after removal of casing and drill tools and is generally not an indicated of a true water table.

Page 9

GEOSOURCE

Groundwater in the underlying bedrock typically flows through joints and fissures in the limestone

bedrock units. The shale bedrock units are generally less permeable and do not transmit significant

amounts of groundwater seepage.

The composition of the glacial soils is often erratic due to the random nature of its deposition. Glacial

deposits frequently contain isolated pockets of water bearing sands and gravel, as well as cobbles and

large boulder size materials. Water bearing lenses within natural glacial deposits are generally limited

in extent. Excavations encountering such lenses typically experience a sudden influx of groundwater

due to the high permeability of the materials within the lens. Foundation and other excavations that

encounter trapped water within the glacial soils can normally be dewatered using conventional sump

pumps.

Fluctuations of groundwater levels can occur due to seasonal variations in the amount of rainfall,

runoff, and other factors not evident at the time the borings were performed. The possibility of

groundwater level fluctuations should be considered when developing the design and construction

plans for the project.

CONCLUSIONS AND RECOMMENDATIONS

Based on the results of our evaluation, it is our professional opinion that the proposed project site

can be developed for the proposed building and utility tunnel using conventional grading and

foundation construction techniques. The existing undocumented fill was quite variable across the

site and contained significant amounts of rubble and construction debris at some of the boring

locations. Because of this, the undocumented fill is not suitable for support of shallow spread

footings.

We have recommended that the proposed building be supported on drilled pier foundations that

extend through the undocumented fill and naturally deposited glacial clay soils and are founded in

the Curzon Limestone Member that underlies the proposed building site. Recommendations for

02-02-2016

Att.9E.--075

GEO**S**OURCE

design and construction of drilled pier foundations are presented in the follow sections of this report.

As an alternative to supporting the proposed building on drilled pier foundations, shallow foundation support bearing on a *Geopier*[®] reinforced subgrade would appear to be a viable foundation option for this project that may potentially provide an economic benefit to this project. Geopiers are rammed aggregate piers that are installed by a specialty contractor using a proprietary method. Recommendations for design and construction of geopiers is normally provided by Geopier US, the company that developed this method of ground improvement and foundation support.

The major concern, from a geotechnical engineering standpoint, is the presence of undocumented fill and the potential for encountering old foundations, walls and other buried structures, as well as large concentrations of rubble from the former buildings that previously occupied the site. If buried structures and/or large concentration rubble are encountered, they could hamper the installation of the drilled pier foundations and/or the drilling of the boreholes for the Geopiers. Removal and replacement of the existing undocumented fill does not appear to be an economical option for this project. One way to deal with the uncertainty, would be to establish a contingency fund for removal of old buried structures and/or rubble in areas affected by the new construction.

The construction of the proposed utility tunnel between the proposed building and Statehouse Parking Garage should be relatively straight forward. The borings indicated that some rock excavation will likely be required to install the tunnel at the currently proposed bottom elevations. Removal of the rock will likely require the use of pneumatic breakers, rock teeth or some other method of hard rock removal. Groundwater was not encountered in the borings that were drilled along the proposed tunnel alignment. However, it would be prudent to include underdrains below the floor slab of the tunnel and adjacent to the tunnel walls to prevent hydrostatic loading of the walls and seepage into the tunnel, should groundwater levels change in the future.



To reduce the potential for subgrade volume change and floor slab movement, we have recommended that a minimum of 24 inches of select, low volume change material be placed below building floor slabs. Thorough site preparation will be required to correct areas that were disturbed by previous construction activity at the proposed building site. The recommendations given in the following sections of this report describe subgrade preparation for building foundations, floor slabs and pavements, as well as undercutting procedures to remove existing fill, soft soils, expansive clays and other unsuitable materials. Proper fill placement techniques are also discussed and include: recommended types of fill materials, maximum lift thickness, as well as soil moisture content and compaction criteria for structural fill sections.

The recommendations submitted herein are based, in part, upon data obtained from our subsurface exploration. It should be recognized that subsurface conditions may vary between the exploration points and that the nature and extent of any subsurface variations that may exist at the proposed site will not become evident until exposed during construction. If variations appear evident, then the recommendations presented in this report should be reevaluated. In the event that any changes in the nature, design, location or floor slab elevations of the proposed building are planned, the conclusions and recommendations contained in this report should not be considered valid unless the changes are reviewed by the geotechnical engineer and our recommendations modified in writing, if necessary.

SITE PREPARATION

Initial site preparation for the proposed project should commence with the removal of the existing pavement section and the demolition of any existing structures that are located within proposed construction areas. Demolition should include complete removal of all grade supported slabs, pavements, sidewalks and shallow spread footings. All broken concrete, asphalt and other debris from demolition of these structures should be removed from the site. Areas disturbed during demolition of the existing structures should be thoroughly evaluated by the geotechnical engineer prior to placement of structural fill. All disturbed soils should be undercut prior to placement of structural fill.



Relocation of any existing utility lines within the zone of influence of proposed construction areas should also be completed as part of the site preparation. The lines should be relocated to areas outside of the proposed construction. Excavations created during the removal of the existing lines should be cut wide enough to allow for use of heavy construction equipment to recompact the fill. In addition, the base of the excavations should be thoroughly evaluated by a geotechnical engineer or engineering technician prior to placement of fill. All fill should be placed in accordance with the recommendations presented in the Structural Fill section of this report.

Following completion of the demolition work, it is recommended that the exposed grade be scarified to a minimum depth of 8 inches and be moisture conditioned to bring the moisture content of the soils into the range recommended for structural fill. Moisture conditioning is the process of adjusting the moisture content of the scarified materials to a moisture content that is within a range of 0 to 4 percent above the optimum moisture content as determined by the Standard Proctor (ASTM D-698) compaction procedure. Following moisture conditioning, the scarified materials should be recompacted to a minimum of 95 percent of Standard Proctor (ASTM D-698) maximum dry density. Soft or unstable areas that hamper compaction of the subgrade should be undercut and replaced with structural fill.

Following moisture conditioning and prior to placement of any new fill, it is recommended that the exposed grade be proofrolled. Proofrolling of the subgrade provides a more stable base for placement of structural fill and aids in identifying soft or disturbed areas. Unsuitable areas identified by the proofrolling operation should be undercut and replaced with structural fill. Proofrolling can be accomplished through use of a fully-loaded, tandem-axle dump truck or similar equipment providing an equivalent subgrade loading. Suitable structural fill should then be placed to design grades as soon as practical after reworking the subgrade to avoid moisture changes in the underlying soils.

If soft or unstable conditions are encountered during the proofrolling operation, stabilization of the soils may be required. Clean crushed rock having a particle diameter of 3 to 6 inches could be used to stabilize the subgrade prior to placement of structural fill. After initial undercutting, the large rock would be spread over the unstable subgrade and worked into the soft soils by close tracking with a

Page 13

GEOSOURCE

bulldozer or other suitable construction equipment. Additional rock would be added until the subgrade becomes firm enough to support construction equipment. The use of a geotextile fabric, in conjunction with crushed rock, could also be considered as a means of stabilizing the exposed grade.

CLIMATIC CONDITIONS

Weather conditions will influence the site preparation required. In spring and late fall, following periods of rainfall, the moisture content of the near surface soils may be significantly above the optimum moisture content. Additionally, it is common to encounter wet, unstable soils upon removal of the site pavements or flatwork as a result of moisture becoming trapped beneath relatively impervious concrete or asphalt pavements. These conditions could seriously impede grading by causing an unstable subgrade condition. Typical remedial measures include aerating the wet subgrade, removal of the wet materials and replacing them with dry materials or treating the wet material with fly ash.

If site grading commences during summer months, the moisture contents of the onsite soils may be abnormally low, which can significantly increase the swell potential of the clay soils. Typically, discing and moisture conditioning of the exposed subgrade materials to the moisture content criteria outlined in the Structural Fill section will reduce this swell potential of the dry materials. As an alternative, the dry materials could be undercut and replaced with structural fill.

EXCAVATIONS

Excavations will be required for foundations, underground utilities and a utility tunnel for this project. It is anticipated that the foundation excavations will be in undocumented fill and naturally deposited clay soils above the water table. These materials can generally be excavated with conventional earthmoving equipment such as backhoes and large track hoes. Rubble fill and buried structures within the undocumented fill could hamper excavations in some areas of the site. Utility excavations that extend into the underlying weathered shale bedrock with a Standard Penetration Resistance (N) value of less than 25 blows per foot can generally be excavated with conventional earthmoving

Page 14

GEO**S**OURCE

equipment such as backhoes, large track hoes, loaders, etc. The borings indicated that the proposed utility tunnel excavation along SW Van Buren Street will extend into harder, less weathered shale and/or limestone bedrock units. Removal of the hard shale and limestone will be more difficult and will probably require the use of rock teeth, pneumatic breakers, or some other method of hard rock removal to complete the excavation for the utility tunnel.

Temporary construction slopes should be designed in strict compliance with the most recent governing regulations. The naturally deposited clay soils encountered in the borings would generally be classified as Type B soils, under Part 1926 of the OSHA regulations pertaining to open excavations. For these soils, it is recommended that temporary construction slopes be no steeper than 1(H) to 1(V). Construction slopes should be closely observed for signs of mass movement: tension cracks near the crest, bulging at the toe, etc. If potential stability problems are observed, the geotechnical engineer should be immediately contacted. The responsibility for excavation safety and stability of temporary construction slopes should lie solely with the contractor.

STRUCTURAL FILL

All structural fill should consist of approved materials, free of organic matter and debris. Fill placed within 24 inches below the building floor slab and leveling course materials should consist of a lower plasticity cohesive soil having a liquid limit less than 45. Higher plasticity soils could be used as structural fill in the lower portion of deep fill sections in the building area and/or as structural fill in pavement areas where more movement can generally be tolerated. Fill should be placed in lifts having a maximum loose lift thickness of 9 inches. All fill should be compacted to a minimum of 95 percent of the material's maximum dry density as determined by ASTM D-698 (standard Proctor compaction). The moisture content of the fill at time of compaction should be within a range of 0 to 4 percent above optimum moisture content as defined by the standard Proctor compaction procedure. Moisture contents should be maintained within this range until completion of the building floor slab.

Granular materials that do not have a well-defined moisture-density relationship that are placed below foundations and other structures should be compacted to a minimum of 70 percent of the materials

Page 15

GEOSOURCE

maximum relative density as determined by ASTM Specifications D-4253 and 4254. Granular backfill materials placed next to structures should be compacted to a minimum of 65 percent of the materials maximum relative density. There is no specific moisture content requirement for compaction of sands and sandy soils and the moisture content of these soils should be maintained in a suitable range that facilitates the compaction of the sand.

Based on the proposed floor slab elevations, it appears that it will be necessary to import fill material to the site. It is recommended the low volume change material be imported to complete the required fill sections.

FOUNDATIONS

The borings encountered undocumented fill with variable amounts of rubble and construction debris. The undocumented fill is not considered suitable for support of shallow spread footings. Because of this, we have recommended that the proposed building be supported on drilled pier foundations that extend through the undocumented fill and naturally deposited glacial clay soils and are founded in the Curzon Limestone that underlies the proposed building site. As an alternate to supporting the proposed building on drilled pier foundations, shallow foundation support bearing on a *Geopier*® reinforced subgrade would appear to be a viable foundation option for this project. As previously discussed, Geopiers are rammed aggregate piers that are installed by a specialty contractor using a proprietary method. Recommendations for design and construction of geopiers is normally provided by Geopier US, the company that developed this method of ground improvement and foundation support.

DRILLED PIER FOUNDATIONS

Based on the subsurface conditions encountered at the site, it recommended that the proposed building be supported by a drilled pier and grade beam foundation system. It is recommended that all drilled piers be founded in the Curzon Limestone. Based on the borings, it is anticipated that the bearing elevations of the drilled piers will range from about 908 to 913 feet, across the proposed



building site. Greater penetration into the bedrock may be required at some locations depending on the extent and severity of bedrock weathering. Drilled piers that are founded in suitable limestone may be designed and proportioned using an allowable end bearing pressure of 60,000 psf.

Any uplift loads acting on the foundations can be resisted by the effective dead weight of the piers plus an allowable side friction value of 250 psf for the portion of the shaft in soils and 2,000 psf for the portion of the shaft in weathered shale and/or limestone bedrock.

Properly reinforced drilled piers are also capable of resisting transient lateral loads from wind and/or earthquakes. It has been our experience that drilled piers with a minimum shaft diameter of 30 inches and an embedment length of at least 10 feet are capable of resisting lateral loads of 25 kips or more, with maximum top of pier deflections of ½ inch or less. If desired, GeoSource can perform a more comprehensive lateral load analysis and provide additional recommendations, when final loads become available. All piers subject to lateral loads should be properly reinforced.

All piers should have a minimum shaft diameter of 36-inches in order to accommodate dewatering equipment and/or to permit access for proper hand cleaning and observation of the base. Some groundwater seepage should be anticipated during the installation of drilled piers and use of temporary casing and dewatering techniques may be required. Temporary casing may also be required in areas where significant amounts of debris and/or rubble are present in the undocumented fill. To minimize disturbance to the bearing surfaces caused by ponding of water, it is recommended that concrete be placed the same day that the piers are drilled. It is also recommended that temporary casing be installed when personnel are required to enter a drilled pier excavation to clean or observe the bearing surface.

To minimize disturbance to the bearing surfaces caused by ponding of water, it is recommended that concrete be placed the same day that the drilled shafts are completed. The bottom of the pier excavation should be clean and free of water and loose materials prior to placement of the reinforcing steel and concrete. Concrete placement should be continuous from the bottom to the top elevation of the shaft. For dry excavations, concrete may be placed by the free fall method,

Kansas Energy & Service Center

Page 17

Project No. D14G1399

GEO**S**OURCE

provided that it can be directed down the center of the shaft without hitting the reinforcing steel or

sides of the excavation. Wet excavated shafts will require that the concrete either be pumped from

the bottom up or placed using a tremie. The tremie pipe should be clean and have a sufficient inside

diameter for use with the specific concrete mix, but not less than 10 inches. The discharge end of

the tremie should allow free radial flow of the concrete and be immersed at least 5 feet in concrete

and maintain a positive pressure differential during placement to prevent water or spoil intrusion.

It is anticipated that the drilled piers can be installed with conventional drilling equipment. It is

possible that obstructions, such as rubble fill or old buried foundations, walls and other structures from

the former buildings may be encountered during the installation of the drilled piers. Core barrels, rock

augers or special construction methods may be required to remove obstructions and/or to remove loose

rock and other materials to properly prepare the foundation bearing surface for the drilled piers.

Temporary steel casing and dewatering procedures may be required for proper installation of the

drilled piers. If concrete will be placed in conjunction with the use of temporary casing, there must

be a sufficient head of concrete inside the casing to prevent soil and water from entering the pier

excavation as the temporary casing is pulled. It is recommend that concrete be designed to have a

minimum slump in the range of 6 to 8 inches to reduce the potential for arching as the casing is

removed.

It is recommended that all drilled pier and/or footing excavations be observed and evaluated by the

geotechnical engineer or his representative immediately prior to placement of foundation concrete.

Unsuitable areas identified at this time should be corrected. Corrective procedures would be

dependent upon conditions encountered and will most probably include deepening of the drilled

piers.

Long-term structural settlement of drilled piers designed and constructed as outlined above should

be minor; i.e., ½ inch or less.

02-02-2016

Att.9E.--083



GEOPIER FOUNDATION SYSTEM

As an alternate to supporting the proposed building on drilled pier foundations, shallow foundation support bearing on a *Geopier*[®] reinforced subgrade appears to be a viable option for this project and may potentially provide an economic benefit to this project. Based on our experience with the *Geopier* soil reinforcement system, we anticipate that a *Geopier* reinforced subgrade could be designed to increase the net allowable soil bearing pressure at this site while limiting foundation settlement.

The *Geopier* soil reinforcement system has been used for a number of years to support structures as an alternative to deep foundations and/or to the removal and replacement of soft or unsuitable soils. The system allows the use of conventional spread footings and floor slabs cast on-grade, and reliably controls settlement to within design tolerances.

The *Geopier* soil reinforcement system consists of highly densified aggregate piers. The *Geopier* elements are installed by drilling 30-inch diameter holes, and ramming thin lifts of well-graded aggregate within the holes to form very stiff, high-density aggregate piers. The drilled holes for this project should extend through the undocumented fill to the underlying bedrock, a depth of about 13 to 19 feet below the finished floor elevation of the existing building. Following drilling of the geopier hole, well graded aggregate is compacted in 12-inch loose lifts in the drill hole. Ramming takes place with a high-energy beveled tamper that both densifies the aggregate and forces the aggregate laterally into the sidewalls of the hole. This action increases the lateral stress in surrounding soils, thereby further stiffening the reinforced composite soil mass. The result of *Geopier* installation is a significant strengthening and stiffening of subsurface soils that then support floor slabs and high-capacity footings.

Geopier designs are based on a two-layer settlement analysis as described by Lawton et al. (1994) and in the Geopier Reference Manual. Settlements within the "upper zone" (zone of soil that is reinforced with Geopier elements) are computed using a weighted modulus method that accounts for the stiffness of the Geopier elements, the stiffness of the matrix soil, and the area coverage of Geopier elements below supported footings. Settlements within the "lower zone" (zone of soils beneath the upper zone

Page 19

GEO**S**OURCE

which receives lower intensity footing stresses) are computed using conventional geotechnical

settlement methods.

The Geopier soil reinforcement system is a design-build system and Geopier US should be

contacted to provide engineering analyses and project specific design information for this project.

Please contact Mr. Aaron J. Gaul, of *Geopier Foundation Company – Midwest at (816) 531-6026*

regarding the final system design, including the allowable foundation bearing pressure, Geopier

shaft lengths and spacing, anticipated floor slab thickness, and a cost to support the proposed

building.

If the Geopier system is selected, Quality Assurance testing should be performed during installation,

including documentation of the soil conditions encountered, the shaft lengths, amount of aggregate

used, verification of the modulus test readings, and tests on the compacted aggregate lifts. GeoSource

would be pleased to provide this service.

SEISMIC HAZARDS DETERMINATION

Earthquake hazard evaluation is a complex task. Seismic sources must be identified and

characterized, path effects must be evaluated (i.e., selection of appropriate attenuation

relationships), and ground motions must be completed. Finally, an analysis of the motion with

respect to the proposed construction must be made. In addition to the multi-discipline nature of this

process, there is substantial parameter and modeling uncertainty associated with each of the steps.

Typically, code based approaches are used for seismic hazard analyses. Our seismic hazard

evaluation follows the IBC 2009 procedures.

United States Geological Society (USGS) has developed and mapped maximum earthquake

response spectra for two design levels: an earthquake having a 10% probability of exceedance in 50

years and an earthquake having a 2% probability of exceedance in 50 years. The motions

developed by USGS represent soft rock conditions, which are assumed to be representative of the

JCSBC 02-02-2016

GEO**S**OURCE

soil/rock that would be encountered below a depth of approximately 100 feet below existing grades at the site.

The USGS "soft rock" peak ground accelerations for the 10%/50 year and 2%/50 year events are 5.10% g and 18.60% g, respectively. Maximum spectral accelerations at the 0.2 second/1.0 second periods for the 10%/50 year and 2%/50 year events are 5.10% g / 2.10% g and 15.40% g / 5.40% g, respectively. Based on the subsurface information, the project site would be characterized as a Site Class C per the 2009 International Building Code (IBC). In addition, there is no significant risk of liquefaction or mass movement of the on-site soils due to a seismic event.

BUILDING FLOOR SLABS

The recommendations outlined in the Site Preparation and Structural Fill sections of this report are intended to produce subgrades that are suitable for support of building floor slabs. These recommendations include capping the building pad with a minimum of 24 inches of select, low volume change material below the floor slab and leveling course. The select fill layer below the floor slabs has been recommended to reduce the potential for subgrade volume change and floor slab movement. The recommended low plasticity structural fill thickness is in addition to any granular section that will be required below the floor slabs. The moisture content of the subgrade soils should be maintained within the recommended range until floor slabs are completed. Depending upon weather conditions, periodic wetting may be required.

Where possible, floor slabs should be designed and constructed as free slabs to allow for some differential movement between the walls, column points and floor slabs. It is recommended that a granular leveling course, having a minimum thickness of 4 inches, be used below normally loaded building floor slabs supported on soil subgrades. The granular section provides a capillary moisture break and acts as a leveling course. Clean crushed limestone gravel, with a nominal size of ½ to ¾ inch, would be recommended for the leveling course. A modulus of subgrade reaction of 100 pci may be used to design floor slabs constructed on an untreated clay subgrade.



In areas where floor loads are greater than 200 psf, it is recommended that a minimum of 12 inches of crushed limestone aggregate be placed below the building floor slab. The crushed rock may be substituted for a portion of 18 inches of select, low volume change fill layer recommended for normally loaded floor slabs. The purpose of the crushed rock is to provide an improved subgrade for the more heavily loaded floor slab areas. In addition, the crushed rock will also provide a good working surface during construction. It is recommended that the crushed rock have a gradation similar to KDOT AB-3. The crushed rock should be placed in 6 inch lifts and compacted to a minimum of 95 percent of the material's maximum dry density as determined by ASTM D 698. A modulus of subgrade reaction of 250 pci may be used to design floor slabs constructed on 12 inches of compacted crushed limestone aggregate.

Subsurface moisture and moisture vapor naturally migrate upward through the soil and, where the soil is covered by a building or pavement, this moisture will collect. To reduce the impact of this subsurface moisture and the potential impact of future induced moisture (such as landscape irrigation or precipitation), the current industry standard is to place a vapor retarder below the compacted crushed limestone layer. This membrane typically consists of visquene or polyvinyl plastic sheeting, having a thickness of at least 10 mils. It should be noted that although vapor barrier systems are currently the industry standard, this system may not be completely effective in preventing floor slab moisture problems. These systems typically will not necessarily assure that floor slab moisture transmission rates will meet floor covering manufacturer standards and that indoor humidity levels be appropriate to inhibit mold growth. The design and construction of such systems are totally dependent on the proposed use and design of the proposed building and all elements of building design and function should be considered in the slab-on-grade floor design. Building design and construction may have a greater role in perceived moisture problems since sealed buildings/rooms or inadequate ventilation may produce excessive moisture in a building and affect indoor air quality.

Special precautions must be taken during the placement and curing of all concrete slabs. Excessive slump (high water-cement ratio) of the concrete and/or improper curing procedures used during either hot or cold weather conditions could lead to excessive shrinkage, cracking or curling of the



slabs. High water-cement ratio and/or improper curing also greatly increase the water vapor permeability of the concrete. We recommend that all concrete placement and curing operations be performed in accordance with the American Concrete Institute (ACI) Manual.

The above procedures should reduce the potential for subgrade moisture variations and consequently reduce floor slab movement and cracking. However, these procedures will not completely eliminate the volume change characteristics of the natural clay soils and, because of the presence of unaltered clay soils that extend to much greater depths, some long-term volume change may occur along with some floor slab movement and cracking. Isolation of floor slabs from walls and columns should be considered to accommodate minor differential movement of floor slabs. If it is desired to further minimize the potential for subgrade volume change, the use of a greater thickness of low volume change material beneath the floor slab should be considered.

LATERAL EARTH PRESSURES

Based on our experience with soils similar to those encountered at the site, it is recommended that the walls of the utility tunnel be designed using an equivalent fluid pressure of 55 pounds per cubic foot. This lateral earth pressure assumes an "at rest" stress distribution condition; i.e., no wall rotation is allowed. The recommended load distribution does not include a factor of safety or take into account the influence of any hydrostatic loading of the walls. Also, the stress distributions do not include the influence of any foundations, pavement or other surcharge loads located in or adjacent to wall backfill.

To prevent hydrostatic loading on the walls and/or seepage into the utility tunnel, it is recommended that perforated drain lines be installed at the base of the walls and also under the bottom floor slab of the tunnel. The drain lines should be sloped to provide positive gravity and should extend to a sump or storm drain where the water is removed. The drain line should be wrapped with filter fabric to prevent intrusion of fines. The drain line should be backfilled with free draining granular material extending vertically above the drain line to within 2 feet of final grade. The remaining portion of the excavation should be backfilled with cohesive soils to minimize the infiltration of surface water. The



granular section behind the wall should have a minimum width of 2 feet and should be encapsulated in the suitable filter fabric to minimize intrusion of fines. The use of a prefabricated drainage blanket on the foundation wall could also be considered to prevent hydrostatic loading. Drainage blankets should be installed in accordance with the manufacturer's recommendations.

PAVEMENTS

Parking and drive area subgrades should be prepared in accordance with the recommendations given in the Site Preparation and Structural Fill sections of this report. The site soils are considered poor subgrade materials for support of pavements. Based on the soil types encountered at this site and previous experience with materials of this type, a design CBR value of 3 is recommended for design of pavement sections. For this design value, a full-depth asphaltic concrete section having a minimum thickness of 6 inches is recommended for automobile parking areas and 7.5 inches is recommended for the access drives. For asphaltic concrete pavements, a minimum surface course thickness of 2 inches is normally recommended.

Service drives used by semi-trailer and other heavy delivery trucks require thicker pavement sections. GeoSource would be pleased to provide specific thickness recommendations for heavy duty pavements, after we receive additional information regarding the type and number of trucks that are projected to use this facility over the design life of the pavement. Portland cement concrete pavements are recommended for approach slabs, dock aprons, truck drives and parking areas, trash dumpster pads and other areas where heavy wheel loads will be concentrated. It is recommended that the concrete pavements in these areas have a minimum thickness of 8 inches. We normally recommend a 4-inch leveling and drainage course of clean, crushed rock be placed below all concrete pavements.

GEOSOURCE

Portland cement concrete pavements are recommended for the trash dumpster pad and other paved areas subjected to concentrated wheel loads and high stresses. The minimum recommended thickness in these areas is 7 inches. Normally, a 4-inch layer of granular fill is placed below concrete pavement sections.

We recommend that the pavement subgrades be evaluated by proofrolling immediately prior to paving. The moisture content and density of the top 8 inches of the subgrade should be checked within two days prior to commencement of actual paving operations. If the material is not in compliance with the required ranges of moisture or density, the subgrade should then be moisture conditioned and recompacted. If any significant event, such as precipitation, occurs after the evaluation, the subgrade should be reviewed by qualified personnel immediately prior to placing the pavement. The subgrade should be in its finished form at the time of the final review.

Proper drainage is a key to the long term performance of any pavement section. It is recommended that all pavements be properly sloped to provide rapid runoff of surface water. Water should not be allowed to pond on or adjacent to pavements, since this could result in saturation of the subgrade and cause premature deterioration of pavements. Pavements in Kansas are normally subjected to 30 or more freeze-thaw cycles in any given year. Because of this, periodic maintenance of all of the pavements is essential to long term performance and should be anticipated. This should include sealing of all cracks and joints and by maintaining proper surface drainage next to paved areas.

PLANS AND SPECIFICATIONS REVIEW

It is recommended that the geotechnical engineer be provided the opportunity to review the plans and specifications so that comments can be made regarding the interpretation and implementation of our geotechnical engineering recommendations in the design and specifications. In the event that GeoSource is not given the opportunity to perform this recommended review, we will assume no responsibility for misinterpretation of our geotechnical engineering recommendations.



CONSTRUCTION OBSERVATION AND TESTING

To effectively achieve the intent of the geotechnical recommendations presented in this report and to maintain continuity from design through construction, GeoSource should be retained to provide observation and testing services during earthwork and foundation construction phases of the project. This will provide the geotechnical engineer with the opportunity to observe the subsurface conditions encountered during construction, evaluate the applicability of the geotechnical recommendations presented in our report as they relate to the soil and bedrock conditions encountered, and to provide follow up recommendations if conditions differ from those described in our report.

LIMITATIONS

The analysis and recommendations submitted in this report are based in part upon the subsurface information obtained from the exploration points performed at the indicated locations and our present knowledge of the proposed construction as outlined in the Project Description. Subsurface conditions may vary between the exploration points and across the site and our report does not reflect any variations which may occur. The nature and extent of such variations may not become evident until construction. If subsurface conditions are encountered during construction that differ from those described in this report, GeoSource should be notified immediately so that a review may be made and any supplemental recommendations provided. If the scope of the proposed construction, including the proposed loads, floor slab elevations or locations, changes from that described in this report, our recommendations should also be reviewed and the recommendations modified accordingly.

This report has been prepared in accordance with the generally accepted geotechnical engineering practice as it exists in the area at the time of our study. No warranty is expressed or implied. The recommendations provided in this report are based on the assumption that an adequate program of observation and testing will be conducted during the construction phase in order to evaluate




compliance with our recommendations. Our scope of services did not include any environmental assessment or exploration for the presence of hazardous or toxic materials in the soil, surface water, groundwater or air, on, below or around this site.


This report has been prepared for the exclusive use of our client for specific application to the project discussed. Any party other than the client who wishes to use this report shall notify GeoSource in writing of such intended use. Additional work may be required before an updated report can be issued. Non-compliance with any of these requirements will release GeoSource from any liability resulting from the use of this report by any unauthorized party and client agrees to defend, indemnify and hold harmless GeoSource from any claim or liability associated with such unauthorized or non-compliance.



APPENDIX

FIGURE 1: BORING LOCATION SKETCH
FIGURE 2: GENERALIZED SUBSURFACE PROFILE
BORING LOGS
GENERAL NOTES AND TERMS
BORING LOG SYMBOLS





В	OREHO	OLE IN	IFORMA	ATION		Pa	age 1	of 1		LOG OF BORING NO. B-1	
ST	ATION			OFFSE	ΞT				PRO	DJECT NAME Proposed Kansas Energy & Service Center	
	ORTHIN			EAS1					SIT	SW 7th Street and Van Buren Street Topeka, Kansas	
				eoSource t Augers	•	HAMMEI	D A	uto	OW	NER / ARCHITECT State of Kansas / HTK Architects	
IVIL		4-1110		_						Offset 4 feet east due to utilities	
SAMPLE NO.	SAMPLE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	GRAPHIC LOG	DEPTH, Feet.	MATERIAL DESCRIPTION	
/S	/S	₩	N H H	208	22	žŏ	15 X	้อ	ä	Approx. Surface Elevation:	923.4
	PA								-	Asphaltic Concrete (3")	
1	ST	15		*1500	102	25.6	CL		- -	FILL, lean clay, medium stiff, light brown, trace fine sand	920.9
	PA								-	FILL, lean to fat clay, stiff, dark gray brown,	
2	SS	18	7	*1500		21.6	CL CH		5 -	trace gravel, brick, cinders and miscellaneous construction debris	
									3 -	6.0	917.4
	PA								- -	FAT CLAY, stiff, brown mottled light gray and rust	
3	ST	20		4410	101	28.0	СН		- - - 10 –		
	PA								- - - -	11.7 ** <u>LIMESTONE</u> , weathered, broken and seamy to very hard, light gray	911.7 910.6
										AUGER REFUSAL @ 12.8 FEET	
										ATTERBERG LIMITS Sample 1, Depth 1-3 feet LL PL PI 37 18 19 **Rock classification is based on drilling characteristics and visual observation of disturbed samples. Core samples may reveal other rock types.	
* Cc	libratad		trometer	. ** 「	Rock Str	congth :-	n nei	-			
Ca							•	 te bound	 dary line	es between soil and rock types. In-situ the transition may be gradual.	
WA				SERVAT						BORING STARTED 12-17-14	
Σ	12.0	feet \	W.D.				٢	7-		BORING COMPLETED 12-17-14	
Ţ	12.0	feet A	A.B.				Vr	nur Source	for Goot	echnical and Materials Engineering RIG CME-55 DRILLER	MC
	Back	cfillec	1 @ Co	mpletic	on		"	our course	, 101 0000	200 C 100 C	31399

ВС	DREHO	OLE IN	FORMA	ATION		Pa	ige 1 d	of 2		LOG OF BORING NO. B-2	
ST	ATION			OFFSE	Т				PRO	DJECT NAME Proposed Kansas Energy & Service Center	
NC.	RTHIN	G		EAST	ING				SIT	ELOCATION SW 7th Street and Van Buren Street	
DR	LLING	COMPA	NY G	eoSource	e, LLC					Topeka, Kansas	
ME	THOD	4-inc	h Flight	Augers	ŀ	HAMMEI	R A	uto	OW	NER / ARCHITECT State of Kansas / HTK Architects	
	Е		Z	0	>	_		g		Offset 8 feet west due to utilities	
Ö.	: TYP	RΥ	RD ATIC	E E	NSIT	RE IT, %	MBO	CLO	Feet.	MATERIAL DESCRIPTION	
SAMPLE NO.	SAMPLE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	3RAPHIC LOG	DEPTH, Feet.	INDICE CONTROL OF THE PERSON AND ADDRESS OF THE PERSON ADDRESS OF THE PERSON AND ADDRESS OF THE PERSON ADDRESS O	
SAI	SAI	R	ST, BE	NU STI	DR PC	₩ S S	SS	GR	DE	Approx. Surface Elevation: 92	22.4
	PA								-	Asphaltic Concrete (5")	
1	ST	13		2420	107	22.7	CL		-	FILL , lean clay, stiff, light brown brown, trace	
1	51	13		2420	107	22.1	CL		-	2.5 fine sand 91	19.9
	PA								-	FILL, fat clay, stiff, gray brown	
2	SS	18	8	*4000		29.4	CL		-	<u> </u>	
<u> </u>	55	10		1000		,-r	СН		5 -	5.0	17.4
									-	FILL, lean to fat clay, soft, dark gray brown and	
	PA								-	geenish gray mixed, trace gravel (Stong Fuel Odor)	
									_	/	
									-		
3	ST	18	9	*1000		55.7	CL CH		-		
							CII		10 -		12.1
	PA								-	** <u>SHALE</u> , weathered, soft, olive tan 11.5	10.9
	111								-		10.3
									-	LIMESTONE, hard, solid, medium to	
D1	NO2	1000/	RQD=	**4000	138	8.7		77	-	thick-bedded, fossiliferous, buff to light gray	
KI	NQS	100%	75%	**4990	136	0.7			-		
									15 -		
				**8040	150	5.4			-		
					-20	5.,			-		
R2	NQ3	78%	RQD= 57%						-	18.0 90 SHALE, mod. hard, very thin bedded, tan	04.4
										1	03.3
				**3180	145	6.5			20 -	<u>LIMESTONE</u> , hard, solid, medium bedded,	
* Cal	ibrotos	I Donot	rometer	** □	ock Str	onath :-	nei	11 11	- 0	fossiliferous, buff to light gray	
Lal							•	e bound	lary line	s between soil and rock types. In-situ the transition may be gradual.	
WA	TER	LEVE	L OBS	ERVAT	IONS					BORING STARTED 12-17-14	
$\overline{\Sigma}$	Dry	Prior	to Co	ring				F	05	BORING COMPLETED 12-17-14	
Ā	4.0	feet /	A.C.R.				Yo	ur Source	for Geot	echnical and Materials Engineering RIG CME-55 DRILLER M	/IC
	Back	rfilled	l @ Co	mpletio	n					APPROVED JJZ JOB# D14G1;	399

В	OREHO	DLE IN	FORMA	ATION		Pa	age 2 (of 2		LOG OF BORING NO. B-2
ST	ATION			OFFSE	T				PRO	Proposed Kansas Energy & Service Center
	ORTHIN			EAS					SITI	SW 7th Street and Van Buren Street
ll	RLLING			oSourc					OW	Topeka, Kansas VNER / ARCHITECT State of Kansas / HTK Architects
ME	ETHOD	4-inc	h Flight	Augers		HAMMEI	R A	uto	OVV	State of Kansas / ITTK Architects
SAMPLE NO.	SAMPLE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	GRAPHIC LOG	DEPTH, Feet.	MATERIAL DESCRIPTION
R3	NQ3	100%	RQD= 100%	**7480	152	3.5			- - -	LIMESTONE, hard, solid, thick-bedded, fossiliferous, light gray 22.5
										BOTTOM OF BORING
* Ca	librated	l Penet	trometer	 ** F	L Rock Str	ength ir	l n psi			
							oximat	e bound	dary line	les between soil and rock types. In-situ the transition may be gradual.
l				ERVA1	TIONS	;	// 34			BORING STARTED 12-17-14
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\			to Co	ring				ЭE		SOURCE BORING COMPLETED 12-17-14
<u> </u>			A.C.R. I @ Co	mpletio	on		Yo	ur Source	for Geot	RIG CME-55 DRILLER MC APPROVED JJZ JOB# D14G139

В	OREHO	OLE IN	IFORMA	ATION		Pa	age 1	of 1			LOG OF E	BORING	NO.	B-3		
S1	ATION			OFFSE	Т				PRO	OJECT NAME	Proposed K	ansas Energ	gy & Se	rvice Ce	nter	
N	ORTHIN	G		EAST	ΓING				SIT	E LOCATION	SW 7th Stre		Buren	Street		
DI	RLLING	COMPA	ANY G	eoSource	e, LLC						Topeka, Ka					
М	ETHOD	4-inc	h Flight	Augers	I	HAMME	R A	uto	OW	/NER / ARCHITI	ECT State of	Kansas / HT	K Arcl	nitects		
SAMPLE NO.	SAMPLE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	SRAPHIC LOG	DEPTH, Feet.			RIAL DESC				
S	S	<u>~</u>	N L M	⊃∾⊡		≥0	s	O				Approx. Su	rface E	levation	:	924.9
	PA								-	Asp	ohaltic Concre	ete (5")				
1	ST	14		4500	115	15.3	CL		-		<u>L</u> , lean clay, v and	ery stiff, ligh	t brown	, trace fir	ne	922.4
	PA								_	EII	L, lean to fat o	olov, modium	ctiff to	ctiff dorl	,	
2	SS	18	20	*1500		19.0	CL CH		- - - 5 -		gray brown, trac miscellaneous c	e gravel, bri	ck, cind		Λ	
3	PA SS	18	9	*3000		31.3	CL CH		- - - - - - -							
									10 -	11.0						913.9
	D.								-			1 0 1				713.7
	PA								-	12.4	SHALE, weath			1		912.5
									-	-	LIMESTONE, o very hard, lig		эгокеп а	nd seamy	y	911.3
										AU AT Sa 1 3 **R c d	GER REFUS. TTERBERG ample 1, Depth LL PL 39 19 Rock classificate tharacteristics a listurbed sample ther rock types	LIMITS 1-3 feet PI 20 ion is based ond visual objes. Core sar	on drilli servatio	n of		
* Ca			trometer			ength ir	•									
							oxima	te bound	dary line	es between soi	l and rock types.					
l				SERVAT	IONS	i						BORING STAF		12-18		
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	Dry		1					ĴΕ		JOU	RCE	BORING COM		12-18		
<u> </u>	Dry						Yo	our Source	for Geot	echnical and Mater	rials Engineering		1E-55	DRILLER		MC
	Back	cfillec	1 @ Co	mpletion	on							APPROVED	JJZ	JOB#	D140	31399

ВС	REHO	OLE IN	FORMA	ATION		Pa	nge 1	of 2		LOG OF BORING NO. B-4
ST	ATION			OFFSE	Т				PRO	DJECT NAME Proposed Kansas Energy & Service Center
NC	RTHIN	G		EAST	ING				SITI	ELOCATION SW 7th Street and Van Buren Street
DR	LLING	COMPA	NY G e	eoSource	, LLC					Topeka, Kansas
ME	THOD	4-inc	h Flight	Augers	ŀ	HAMME	R A ı	uto	OW	NER / ARCHITECT State of Kansas / HTK Architects
SAMPLE NO.	SAMPLE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	SRAPHIC LOG	DEPTH, Feet.	MATERIAL DESCRIPTION
0)	•,	ш.	ол ш			20	00	U		Approx. Surface Elevation: 928 Asphaltic Concrete (5")
	PA								-	· · · · · · · · · · · · · · · · · · ·
1	ST	10		1500	107	19.3	CL		-	FILL, lean clay, medium stiff, light brown, trace fine sand 925
	PA								_	FILL, fat clay, stiff, dark gray brown mixed, trace
2	SS	18	8	*3000		27.0	СН		-	gravel and miscellaneous construction rubble
									5 –	¥
	PA								- - - -	7.2 920 FAT CLAY, very stiff, light gray mottled light
3	ST	18	10	*4500		17.5	СН		-	brown
									10 -	10.5
	PA								-	**SHALE, weathered, soft, olive tan 916
				**7800	153	5.2			-	LIMESTONE, hard, solid, thin-bedded, fossiliferous, buff 915
R1	NQ3	94%	RQD= 56%						-	SHALE, weathered, soft, tan to light brown 14.6 913
				**1970	136	15.2			15 -	<u>LIMESTONE</u> , hard, solid, medium to
R2	**9520 149 5.6									thick-bedded, fossiliferous, buff to light gray
	**4410 146 5.7									
* Cali			rometer		ock Str					
W/A				i lines rep SERVAT			oximat	te bound	ary line	es between soil and rock types. In-situ the transition may be gradual. BORING STARTED 12-18-14
╟ <u></u>			to Co		10143	'		-		BORING STARTED 12-18-14 BORING COMPLETED 12-18-14
⊩			4.C.R.	9			1/4	JE	U Cost	PIG CME-55 DRILLER MC
l				mpletic	n		Yo	our Source	ror Geot	echnical and Materials Engineering APPROVED JJZ JOB # D14G139
Щ			<u></u>	,						302 5140100

во	REHO	LE IN	FORMA	ATION		Pa	age 2 o	of 2		LOG OF BORING NO. B-4
STA	ATION			OFFSE	T				PRO	ROJECT NAME Proposed Kansas Energy & Service Center
NOF	RTHING	3		EAS	ΓING				SITI	TE LOCATION SW 7th Street and Van Buren Street
DRL	LING C	OMPA	NY G e	oSourc	e, LLC					Topeka, Kansas
MET	THOD	4-inc	h Flight	Augers		HAMME	R A ı	uto	OW	WNER / ARCHITECT State of Kansas / HTK Architects
SAMPLE NO.	SAMPLE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	GRAPHIC LOG	DEPTH, Feet.	MATERIAL DESCRIPTION
D2	N 102	250/	ROD=						-	- 20.9 SHALE, hard, very thin bedded, gray 907
R3	NQ3	25%	0%					T T	-	LIMESTONE, hard, light gray 22.5 LIMESTONE, hard, light gray
* Calit	R3 NQ3 25% RQD= 0%									BOTTOM OF BORING BOTTOM OF BORING BOTTOM OF BORING
WAT				ERVA1					,	BORING STARTED 12-18-14
 			to Co				٢	==		SOURCE BORING COMPLETED 12-18-14
¥,	5.0 1	feet A	A.C.R.							otechnical and Materials Engineering RIG CME-55 DRILLER MC
ı	Back	filled	@ Co	mpletio	on					APPROVED JJZ JOB# D14G139

ВС	DREHO	DLE IN	IFORM <i>A</i>	TION		Pa	age 1	of 1		LOG OF BORING NO. B-5	
	ATION			OFFSE	T		J		PRO	DJECT NAME Proposed Kansas Energy & Service Center	
	RTHIN	G		EAS ⁻	ΓING				SITI	ELOCATION SW 7th Street and Van Buren Street	
DR	RLLING	COMPA	ANY G e	oSource	e, LLC				Oiri	Topeka, Kansas	
ME	THOD	4-inc	h Flight	Augers	I	HAMME	R A	uto	OW	NER / ARCHITECT State of Kansas / HTK Architects	
SAMPLE NO.	SAMPLE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	3RAPHIC LOG	DEPTH, Feet.	MATERIAL DESCRIPTION	
S)	Ŋ	<u>~</u>	S E B	⊃ Ø ₫	۵٩	ΣU	⊃ة	Ö		••	927.7
	PA								-	Asphaltic Concrete (5")	
1	ST	16		2940	109	20.3	CL		- - -	FILL, lean clay, stiff, light brown, trace fine sand	924.7
2	ST	13		5300	106	22.1	CL CH		- - - 5 -	FILL, lean to fat clay, very stiff to medium stiff, dark gray brown, trace gravel, brick, cinders and miscellaneous construction debris	<u>924. /</u>
	PA								- - - -		
3	ST	10		2050	106	22.1	CL CH		-	9.0	918.7
	D.1								10 -	FAT CLAY, stiff, reddish brown	
	PA								-		915.7 915.2
									_		915.2
										AUGER REFUSAL @ 12.5 FEET ATTERBERG LIMITS Sample 1, Depth 1-3 feet LL PL PI 36 19 17 **Rock classification is based on drilling characteristics and visual observation of disturbed samples. Core samples may reveal other rock types.	
* Cal	ibrated	I Pene	trometer	** F	Rock Str	ength ir	n psi				
		The str	atification	n lines rep	resent t	he appr	•	te bound	dary line	es between soil and rock types. In-situ the transition may be gradual.	
	TER	LEVE	L OBS	ERVA 1	IONS	}				BORING STARTED 12-17-14	
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	9.0							SE		BOURCE BORING COMPLETED 12-17-14	
<u> </u>	10.0	feet .	A.B.				Yo	our Source	for Geot	echnical and Materials Engineering RIG CME-55 DRILLER	MC
	Back	cfillec	l @ Co	mpletio	on					APPROVED JJZ JOB# D14G	1399

В	OREHO	DLE IN	IFORM <i>A</i>	ATION		Pa	age 1	of 1		LOG OF BORING NO. B-6	
ST	ATION			OFFSE	T				PRO	DJECT NAME Proposed Kansas Energy & Service Center	
NO	ORTHIN	G		EAST	ΓING				SIT	ELOCATION SW 7th Street and Van Buren Street	
DF	RLLING	COMPA	ANY G	eoSource	e, LLC					Topeka, Kansas	
ME	ETHOD	4-inc	h Flight	Augers		HAMME	R A	uto	OW	NER / ARCHITECT State of Kansas / HTK Architects	
SAMPLE NO.	SAMPLE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	3RAPHIC LOG	DEPTH, Feet.	MATERIAL DESCRIPTION	
S	S)	<u>~</u>	N L M	⊃ ⊗ <u></u>		≥0	⊃ø	Ö		••	923.6
	PA								-	Asphaltic Concrete (5")	
1	ST	14		*2500	104	21.1	CL		-	FILL , lean clay, stiff, light brown, trace fine sand 2.5	921.1
	PA								-		
2	SS	18	16	*2000		22.3	CL CH		- - - 5 -	FILL, lean to fat clay, medium stiff to stiff, dark gray brown, trace gravel, brick, cinders and miscellaneous construction debris	
	PA								- - -	7.8	915.8
3	SS	18	7	*2500		20.1	CL		10 -	LEAN CLAY, stiff, dark gray brown (Possible Fill)	
	PA								-	11.3	912.3
	111								-	'	911.5
									_	AUGER REFUSAL @ 12.7 FEET **Rock classification is based on drilling characteristics and visual observation of disturbed samples. Core samples may reveal other rock types.	<u>910.9</u>
* Cal	librated	l Pene	⊥ trometer	· ** F	L Rock Str	ength ir	n psi	-			
							•	te bound	dary line	es between soil and rock types. In-situ the transition may be gradual.	
	TER	LEVE	L OBS	SERVAT	TIONS	3				BORING STARTED 12-19-14	
Σ										BORING COMPLETED 12-19-14	
Ţ	Dry	A.B.					Yo	our Source	for Geot	echnical and Materials Engineering RIG CME-55 DRILLER	MC
	Back	fillec	l @ Co	mpletio	on					APPROVED JJZ JOB# D14G	1399

ВС	DREHO	DLE IN	IFORMA	ATION		Pa	age 1	of 1		LOG OF BORING NO. B-7	
ST	ATION			OFFSE	Т				PRO	DJECT NAME Proposed Kansas Energy & Service Center	
NC	RTHIN	G		EAST	ΓING				SITI	ELOCATION SW 7th Street and Van Buren Street	
DR	RLLING	COMPA	ANY G	oSource	e, LLC					Topeka, Kansas	
ME	THOD	4-inc	h Flight	Augers	I	HAMME	R A	uto	OW	NER / ARCHITECT State of Kansas / HTK Architects	
SAMPLE NO.	SAMPLE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	SRAPHIC LOG	ЭЕРТН, Feet.	MATERIAL DESCRIPTION	
<u>σ</u>		Ľ.	S E B] J W F		≥0	<u>⊃</u> ∽	0		• •	925.0
	PA								-	Asphaltic Concrete (5")	
1	ST	20		2950	107	20.0	CL		- - -	FILL, lean clay, stiff, light brown, trace fine sand	
	PA								-	3.0	<u>922.0</u>
2	SS	12	76			11.4			- -	RUBBLE FILL, brick, cinders, limestone and/or concrete rubble in a clay matrix	
3	PA SS	3	50/3"			15.1			5		
	PA								-	11.1	913.9
	171								-	** <u>SHALE</u> , weathered, soft, grayish tan 12.4	912.6
									_	**LIMESTONE, weathered, broken and seamy	911.5
* Cal			trometer			rength ir	•			AUGER REFUSAL @ 13.5 FEET ATTERBERG LIMITS Sample 1, Depth 1-3 feet LL PL PI 9I 34 19 15 **Rock classification is based on drilling characteristics and visual observation of disturbed samples. Core samples may reveal other rock types.	311.0
							oxima	te bound	dary line	es between soil and rock types. In-situ the transition may be gradual.	
	TER	LEVE	L OBS	ERVAT	TIONS	3				BORING STARTED 12-18-14	
Σ	Dry	W.D.						SF		BORING COMPLETED 12-18-14	
T	Dry	A.B.					Yo	our Source	for Geot	echnical and Materials Engineering RIG CME-55 DRILLER	MC
	Back	cfilled	l @ Co	mpletio	on					APPROVED JJZ JOB# D14G	1399

						_				_
BORE	IOLE IN	NFORMA	ATION		Pa	age 1	of 1		LOG OF BORING NO. B-8	
STATIO	N		OFFSE	T				PRO	OJECT NAME Proposed Kansas Energy & Service Center	
NORTHI DRI LING		ANY G	EAS ⁻ eo Sourc e					SIT	SW 7th Street and Van Buren Street Topeka, Kansas	
			Augers		HAMME	r A	uto	ow	NER / ARCHITECT State of Kansas / HTK Architects	
SAMPLE NO.	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	GRAPHIC LOG	DEPTH, Feet.	MATERIAL DESCRIPTION	
" "	+-	S E E			≥ō	⊃ŏ	Ŋ		Approx. Surface Elevation: 9 Asphaltic Concrete (5")	924.9
PA								-	•	
1 ST	10		3630	110	19.0			- -	FILL, lean clay, stiff, light brown, trace fine sand 2.5	922.4
PA								-	FILL, lean to fat clay, medium stiff, dark gray	
2 SS	18	5	*2500		23.3			-	brown, trace gravel, brick, cinders and miscellaneous construction debris	
PA								5	7.5	917.4
3 SS PA		50/4"						-	RUBBLE FILL, brick, cinders, limestone or concrete debris in a clay matrix	
IA							<i>***</i>		AUGER REFUSAL @ 9.4 FEET	915. <u>5</u>
* Calibrate					rength in				Driller' Note: Auger refusal on apparent limestone and/or concrete rubble.	
WATER						oximat	ie bound	uai y IIN6	es between soil and rock types. In-situ the transition may be gradual. BORING STARTED 12-18-14	
H	W.D.					٢	7=		BORING COMPLETED 12-18-14	
▼ Dry	A.B.	_				Yo	our Source	e for Geot	echnical and Materials Engineering RIG CME-55 DRILLER	MC
Bac	kfilled	d @ Co	mpletio	on					APPROVED JJZ JOB# D14G	1399

ВС	DREHO	DLE IN	IFORMA	TION		Pa	age 1	of 1		LOG OF BORING NO. B-9	
ST	ATION			OFFSE	T				PRO	OJECT NAME Proposed Kansas Energy & Service Center	
	RTHIN		ANY G	EAS ⁻ eo Sourc e	TING				SIT	SW 7th Street and Van Buren Street Topeka, Kansas	
				Augers	·	HAMME	r A	uto	OW	NER / ARCHITECT State of Kansas / HTK Architects	
SAMPLE NO.	LE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	3RAPHIC LOG	DEPTH, Feet.	MATERIAL DESCRIPTION	
SAMP	SAMPLE	RECC	STAN PENE BLOW	UNCC STRE PSF	DRY I	MOIS	UNIFII SOIL	GRAP	DEPT	Approx. Surface Elevation: 9	26.2
	PA								_	Asphaltic Concrete (5")	
1	ST	8		2590	109	17.8	CL		- - -	FILL, lean clay, stiff, light brown, trace fine sand 2.5	923.7
	PA								-	FILL, lean to fat clay, soft to medium stiff, dark	
2	SS	18	4	*1500		25.7	CL CH		-	gray brown, trace gravel, brick, cinders and miscellaneous construction debris	
	PA						- CI		5		
3	SS	18	10	*2000		30.7	CL CH		-	_	
	3 SS 18 10 *2000 30.7 CL PA								10 -	¥ ▼	211.0
									-		911.9 911.3
										AUGER REFUSAL @ 14.9 FEET	
										ATTERBERG LIMITS Sample 1, Depth 1-3 feet LL PL PI 34 18 16 **Rock classification is based on drilling	
										characteristics and visual observation of disturbed samples. Core samples may reveal other rock types.	
* Cal			trometer		Rock Str		•				
\/\/A				lines rep			roxima	te bound	dary line	es between soil and rock types. In-situ the transition may be gradual. BORING STARTED 12-17-14	
VVA	10.5			PERVAI	IONS	•	_			BORING COMPLETED 12-17-14	
Ţ	10.0						L	JE		PIG CME-55 DRILLER	MC
				mpletio	on		Y	Jul. 2000ce	ior Geor	pechnical and Materials Engineering APPROVED JJZ JOB# D14G1	

	DEU		IFORM <i>A</i>	TION		Dr	age 1	of 1		10	OG OF BO	ORING N	<u> </u>	B-10		
		JLE IIV	IFORIVIA		_	г	ige i	01 1								
	ATION	_		OFFSE					PRO	OJECT NAME	Proposed Ka	ansas Energ	y & S	ervice Ce	nter	
	ORTHIN			EAS					SIT		SW 7th Stre Topeka, Kai		Buren	Street		
				eoSource			- 4	-4-	OW	/NER / ARCHITEC	•	Kansas / HT	K Arc	hitects		
ME	THOD	4-inc	n Filght	Augers		HAMME T	R A	uto	-							
	PE		NO		_	%	占	90	نډا	Offset 4 fe	eet east due to	o parked cai	rs			
SAMPLE NO	SAMPLE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	GRAPHIC LOG	DEPTH, Feet.		MATE	RIAL DESCI	RIPTIO	NC		
MPL	MPL	0	AND	NEN'S	<u>`</u>	OIST	NE S	- SAPF	PT							
S	SA	8	R R R	228	P. S.	ĭŏ	58	GF	B			Approx. Sur	face E	Elevation	:	927.6
											altic Concret Revers	te (4")				
	PA								-	- Brick	R Pavers					
									-	FILL	<u>,</u> lean to fat common, trace gra	lay, medium	stiff, d	ark gray		
										mis	scellaneous co	onstruction de	ebris	ша		
1	ST	6		*1500	98	26.5	CL CH		-	1						
							Сп		5 -	-						
									-	_						
	PA								-	6.8						920.8
									_	FAT	CLAY, very	stiff light or:	avish t	an mottlec	1	
										rus		stiii, iigiit git	uy1511 t	un mottree	•	
2	SS	18	10	*4500		17.1	СН		-	_						
						-,,,			10 -	1						
	PA									11.4						016.2
										11.4 12.0 ** LI	MESTONE,	hard, gray				916.2 915.6
										AUG	ER REFUSA	AL @ 12 O F	TET			
												O				
										**Roc cha	ck classificati aracteristics ar	on is based o nd visual obs	ın drıll ervatio	ing on of		
											turbed sample ner rock types.		ıples m	nay reveal		
										Oth	ici rock types.					
* Ca	ibratod	I Dono	 trometer	** =	Cock Str	onath ir	nei	1								
Ca							•	 te bound	 dary line	 es between soil ar	ınd rock types. Ir	n-situ the transit	tion may	/ be gradual.		
WA	TER	LEVE	L OBS	SERVAT	IONS	;						BORING STAR	TED	12-18	3-14	
Ā	Dry	W.D.					(7=				BORING COMP	LETED	12-18	3-14	
Ī	Dry	A.B.					Yr	our Source	e for Gent	cechnical and Materials	Is Engineering	RIG CM	E-55	DRILLER		МС
	Back	cfillec	l @ Co	mpletio	on		10	our our or	J 101 0000	and wide life	anginouting	APPROVED	JJZ	JOB#	D140	31399

BOREHOLE INFORMATION Page 1 of 1										L	OG OF B	ORING N	Ю.	B-11		
STATION OFFSET							PRO	OJECT NAME	Proposed K	ansas Energ	y & S	ervice Ce	nter			
NORTHING EASTING DRLLING COMPANY GeoSource, LLC							SIT	E LOCATION	SW 7th Stre Topeka, Ka	eet and Van	Buren	Street				
METHOD 4-inch Flight Augers HAMMER Aut							r A	uto	OW	NER / ARCHITE	State of]	Kansas / HT	K Arc	hitects		
					(2)		Offset 6	feet east due t	o parked ca	rs						
SAMPLE NO.	SAMPLE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	GRAPHIC LOG	DEPTH, Feet.		MATE	RIAL DESC	RIPTIC	ON		
SAM	SAM	REC	STAI PEN BLO	UNC STR PSF	DRY	MON	NOS	GRA	DEP			Approx. Sur	face E	Elevation	: 9:	29.8
	PA								-	Brio FIL	ck Pavers L, lean clay, nace fine sand a	ete (4")				
1	ST	10		1420	97	25.8	CL		-							
2	PA SS	18	10	*5500		24.1	СН		5		<u>Γ CLAY</u> , very ust	stiff, light gr	ayish t	an mottled		022.8
	PA								-	12.7	IMESTONE, GER REFUS		ЕЕТ			018.0 017.1
										**Rock classification is based on drilling characteristics and visual observation of disturbed samples. Core samples may reveal other rock types.						
* Ca			trometer		Rock Str		•	to hours	dany line	e between seil	and rook turner	n-citu the trees	tion ma	/ he gradual		
The stratification lines represent the approximate bound WATER LEVEL OBSERVATIONS									uary IIN6	es Derween soll	anu fock types.	BORING STAR		<u>be gradual.</u> 12-18		
✓ Dry W.D.								2-				BORING COMF		12-18		
₹ Dry AB									e for Geotechnical and Materials Engineering			RIG CM	E-55	DRILLER	N	MC
Backfilled @ Completion										APPF			JJZ	JOB#	D14G1	399

В	OREHO	OLE IN	IFORMA	ATION		Pa	age 1	of 2		LOG OF BORING NO. B-12				
S1	ATION			OFFSE	ΞT				PRO	DJECT NAME Proposed Kansas Energy & Service Center				
NO	ORTHIN	G		EAS	TING				SIT	E LOCATION SW 7th Street and Van Buren Street				
DF	RLLING	COMPA	ANY G	eoSource	e, LLC					Topeka, Kansas				
ME	THOD	4-inc	:h Flight	t Augers	ı	HAMME	R A	uto	OW	NER / ARCHITECT State of Kansas / HTK Architects				
	111		z					(1)		Offset 6 feet east due to parked cars				
ON	ΙΔ	Σ	AD ATION T.	ONFINED	LISI	7, 7,%	/BOI) LOC	-eet.	MATERIAL RECORDITION				
SAMPLE NO	SAMPLE TYPE	RECOVERY	NDA ETR, WS/F	UNCONFINE STRENGTH PSF		MOISTURE CONTENT, 9	SYN	GRAPHIC LOG	DEPTH, Feet.	MATERIAL DESCRIPTION				
SAN	SAN	REC	STANDARD PENETRATIC BLOWS/FT.	STR	DRY DENSITY PCF	M O O O O O O	UNIFIED SOIL SYMBOL	GRA	DEP	Approx. Surface Elevation:	930.7			
									_	Asphaltic Concrete (3")				
	D.								-	Brick Pavers				
	PA								-	FILL, lean to fat clay, medium stiff, dark gray				
									-	brown mixed, trace gravel				
1	1 ST 10 1480 98 25.9								-					
	1 ST 10 1480 98 25.								-					
									5 -	6.0	924.7			
	PA								-		<u> </u>			
	PA								-	FAT CLAY, very stiff, light grayish tan mottled rust				
									-	1000				
3	ST	12		4440	107	20.0	CH		-					
									10 -					
									-	11.0	919.7			
	PA								-	**SHALE, weathered, soft, olive tan to light gray				
	171								-	SHALE, weathered, soit, onve tail to right gray				
		<u> </u>							-	13.8	916.9			
4	SS	1_	50/1"			6.4			-		910.9			
									15 -	** <u>LIMESTONE</u> , weathered, seamy to thin-bedded, buff to light gray				
	D.								-	16.0	914.7			
	PA								-	** SHALE , hard, gray				
									_	18.0	912.7			
		<u> </u>							-	18.6 **LIMESTONE, hard, gray	912.1			
										AUGER REFUSAL @ 18.6 FEET				
								-						
* Ca			trometer atification		Rock Stroresent 1		•	te bound	darv line	es between soil and rock types. In-situ the transition may be gradual.				
WA				SERVAT					, , , , , , ,	BORING STARTED 12-18-14				
<u>Z</u>		W.D.					٢	2-		BORING COMPLETED 12-18-14				
Ţ	Dry								for Cost	echnical and Materials Engineering RIG CME-55 DRILLER	MC			
				mpletio	on			our occurre	, IOI OCOL	ecitifical and Materials Engineering	IG1399			

BOREH	OLE INI	FORMA	ATION		Pa	age 2 d	of 2		L	.00	OF B	ORIN	IG I	NO.	B-12		
STATION			OFFSE	T				PRO	DJECT NAME	Pr	oposed K	(ansas	Ener	gy & Se	ervice Co	enter	
NORTHIN	IG		EAS	TING				SIT	E LOCATION		V 7th Str		l Van	Buren	Street		
DRLLING			eoSource	e, LLC				014	NED / ADOLUT		peka, Ka		. / TT	FIZ Aa	l.:44		
METHOD	4-incl	Augers	1	R A ı	uto	Ow	NER / ARCHITE	EGI	State of	Kansas	S / H.	IK Arc	nitects				
SAMPLE NO.	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	GRAPHIC LOG	DEPTH, Feet.			MATE	ERIAL [DESC	CRIPTIC	DN		
									d d	hara listur	classificat cteristics a bed samp rock types	and visu les. Co	ıal ob	servatio	n of		
* Calibrated					ength ir the appr		e bound	 dary line	es between soil	l and	rock types.	In-situ th	e trans	sition may	be gradua	l.	
WATER	LEVE	L OBS	ERVAT	TIONS	3							BORIN	G STA	RTED	12-1	8-14	
 	W.D.						SE		Sou	R	CE	BORING	G COM	1PLETED	12-1	8-14	
l -	A.B.					-			echnical and Mater			RIG		ME-55	DRILLER		МС
∥ Bacl	kfilled	@ Co	mpletio	on								APPRO	VED	JJZ	JOB#	D14	G1399

ВС	REH	OLE IN	FORMA	TION		Pa	ige 1 d	of 2			LOG OF B	ORING N	10.	B-13	
ST	ATION			OFFSE	T				PRO	DJECT NAME	Proposed K	ansas Energ	y & Se	ervice Ce	nter
NC	RTHIN	G		EAST	ΓING				SITE	E LOCATION	SW 7th Stre	eet and Van	Buren	Street	
DR	LLING	COMPA	NY G e	oSource	e, LLC					Topeka, Kansas					
ME	THOD	4-inc	h Flight	Augers	I	HAMMER	₹ A ı	uto	OW	OWNER / ARCHITECT State of Kansas / HTK Architects					
SAMPLE NO.	SAMPLE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	GRAPHIC LOG	DEPTH, Feet.			RIAL DESC			931.9
										As	sphaltic Concre		iace L	ic vation.	301.3
									-		rick Pavers	, (c (c)			
	PA								- - -		LL, lean to fat of trace gravel	clay, stiff, dar	k gray∫	brown,	
1	ST	9		2830	104	28.3	СН		- - 5 -						
	PA								- - - -	5.5 <u>F</u>	AT CLAY, very	stiff, gray bro	own		926.4
									-						
3	SS	18	12	*3500		23.6	СН		10 -	9.5					922.4
									10 -	<u>F</u>	AT CLAY, very	stiff, reddish	brown		
	PA								-	11.8					920.1
									- - -	4	SHALE, weather brown	ered, soft, oli	ve tan t	o gray	
4	SS	15	56/9"			20.7			-	14.5					917.4
									15 -	16.0	LIMESTONE, thin-bedded, lig	weathered, s ht gray	eamy to		915.9
	PA								-	**	SHALE, hard, g	gray			
									_	18.2					913.7
								TT	-		LIMESTONE,	hard, gray			913.7
										Al	UGER REFUSA	AL @ 18.7 F	EET		
* Cal			rometer			ength in	•								
18/4							oximat	e bound	dary line	es between s	oil and rock types. I				44
WA			L OBS	ERVAT	IONS)	-		-			BORING STAR		12-18	
		W.D.					L	jΕ			JRCE	BORING COMP		12-18	
	Dry		I @ C-	moletic	\n		Yo	ur Source	for Geote	echnical and Ma	terials Engineering	RIG CM	E-55	JOB#	MC
	Daci	viilled	. <i>W</i> C0	mpletic	ווע		l					AFFROVED	JJZ	JUB#	D14G1399


BOREHOLE INFORMATION	ION P	age 2 of 2	L	OG OF BORING NO.	B-13
STATION	OFFSET		PROJECT NAME	Proposed Kansas Energy & S	ervice Center
NORTHING	EASTING		SITE LOCATION	SW 7th Street and Van Burer	Street
	Source, LLC		OMMED / ADOLUTE	Topeka, Kansas	-1.244
METHOD 4-inch Flight A	ugers HAMME	R Auto	OWNER / ARCHITE	State of Kansas / HTK Ar	enitects
SAMPLE NO. SAMPLE TYPE RECOVERY STANDARD PENETRATION BLOWS/FT.	DRY DENSITY PCF MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL GRAPHIC LOG	DEPTH, Feet.	MATERIAL DESCRIPTI	ON
			cl di	ock classification is based on dril naracteristics and visual observati isturbed samples. Core samples is ther rock types.	on of
* Calibrated Penetrometer The stratification lin	** Rock Strength i nes represent the app		ary lines between soil	and rock types. In-situ the transition ma	y be gradual.
WATER LEVEL OBSE	RVATIONS			BORING STARTED	12-18-14
▽ Dry W.D.		GE	o Soul	BORING COMPLETED	12-18-14
▼ Dry A.B.			for Geotechnical and Mater	PIG CME 55	DRILLER MC
Backfilled @ Com	pletion			APPROVED JJZ	JOB# D14G1399


В	OREHO	OLE IN	IFORMA	ATION		Pa	age 1	of 1		LOG OF BORING NO. B-14	
ST	ATION			OFFSE	T				PRO	DJECT NAME Proposed Kansas Energy & Service Center	
NO	ORTHIN	G		EAS	ΓING				SIT	ELOCATION SW 7th Street and Van Buren Street	
DF	RLLING	COMPA	ANY G	eoSource	e, LLC					Topeka, Kansas	
ME	THOD	4-inc	h Flight	Augers		HAMMEI	R A	uto	OW	NER / ARCHITECT State of Kansas / HTK Architects	
SAMPLE NO.	SAMPLE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	3RAPHIC LOG	DEPTH, Feet.	MATERIAL DESCRIPTION	
S	S	<u>~</u>	N L M	_⊃ ∾ <u>_</u>		≥0	⊃s	O		Approx. Surface Elevation:	921.5
	PA								-	Asphaltic Concrete (5")	
1	ST	10		1450	109	21.8	CL		- -	FILL, lean to fat clay, medium stiff, light brown, trace fine sand	919.0
	PA								-	FILL , fat clay, medium stiff to stiff, reddish	
2	2 SS 18 5 *2000 18						СН		- - -	brown, dark brown and brown layers, trace gravel	
	PA								5		
3	SS	18	6	*2500		36.5	СН		10 -		
									-	11.3	910.2
	PA								-	** <u>LIMESTONE</u> , weathered, seamy	
									_	12.4 12.2 **SHALE, weathered, soft, tan	909.1 908.3
									13.2 **SHALE, weathered, soft, tall 13.7 **LIMESTONE, hard, gray	908.3	
										**Rock classification is based on drilling characteristics and visual observation of disturbed samples. Core samples may reveal other rock types.	
* Ca			trometer			ength ir		to hours	don, lin	po bothuson coil and rock tupos. In situ the transition was be gradual	
١٨/ ٨				SERVAT			oximat	e bound	uary line	es between soil and rock types. In-situ the transition may be gradual. BORING STARTED 12-19-14	
VVA	Dry			/LIVAI	IONS	,	-	_		BORING STARTED 12-19-14 BORING COMPLETED 12-19-14	
<u>_</u>	Dry						Ĺ	JE		DURGE CME 55 DRILLER	MC
<u> </u>			I @ C^	mpletio	nn .		Yo	our Source	for Geot	echnical and Macenais Engineering	NIC 31399
ll .	D ucr		. 🐷 👓	יייאייבנול	-11		II			JJZ ³³² D140	

В	OREHO	DLE IN	FORMA	TION		Pa	age 1	of 1		LOG OF BORING NO. B-15	
ST	ATION			OFFSE	T				PRO	DJECT NAME Proposed Kansas Energy & Service Center	
NO	ORTHIN	G		EAST	ΓING				SITI	ELOCATION SW 7th Street and Van Buren Street	
DF	RLLING	COMPA	NY G e	oSource	e, LLC					Topeka, Kansas	
M	ETHOD	4-inc	h Flight	Augers		HAMME	R A	uto	OW	NER / ARCHITECT State of Kansas / HTK Architects	
SAMPLE NO.	SAMPLE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	GRAPHIC LOG	DEPTH, Feet.	MATERIAL DESCRIPTION	20.2
0,	0,		07 E E	300 E		20	5 %			• •	20.2
	PA								-	Ţ	
1	1 SS 18 14 *1000 19.2						CL CH		- - -	FILL, lean to fat clay, soft, to medium stiff, dark gray brown, tan and brown mixed, with some gravel and miscellaneous construction rubble	
		1.4	55/011			27.4	CL		-		
2	SS	14	55/8"			27.4	СН		5 –	4.7	15.5
	PA								-	RUBBLE FILL, brick, cinders, limestone or concrete debris in a clay matrix	013.7
										AUGER REFUSAL @ 6.5 FEET	
* Ca			rometer			rength in					
WA				lines rep			roximat	te bound	dary line	es between soil and rock types. In-situ the transition may be gradual. BORING STARTED 12-18-14	
VV		feet \		LIVAI	IONS	•	_		_	201-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-	
<u> </u>	0.8								_	PIG CME-55 DRILLER N	MC
				mpletio	on		Yo	our Source	e ror Geot	echnical and Materials Engineering APPROVED JJZ JOB # D14G1	

В	OREHO	DLE IN	IFORMA	ATION		Pa	age 1	of 1		LOG OF BORING NO. B-16	
ST	ATION			OFFSE	T				PRO	DJECT NAME Proposed Kansas Energy & Service Center	
NC	ORTHIN	G		EAS ⁻	ΓING				SITE	ELOCATION SW 7th Street and Van Buren Street	
DF	RLLING	COMPA	ANY G	eoSourc	e, LLC					Topeka, Kansas	
ME	THOD	4-inc	h Flight	Augers	ا	HAMME	R A	uto	OW	NER / ARCHITECT State of Kansas / HTK Architects	
SAMPLE NO.	SAMPLE TYPE	RECOVERY	STANDARD PENETRATION BLOWS/FT.	UNCONFINED STRENGTH PSF	DRY DENSITY PCF	MOISTURE CONTENT, %	UNIFIED SOIL SYMBOL	3RAPHIC LOG	DEPTH, Feet.	MATERIAL DESCRIPTION	
0,		ш.	ОЛЕ Ш	J 00 IL		20	00			Approx. Surface Elevation: S Asphaltic Concrete (5")	929.0
	PA								-	Asphaluc Concrete (5')	
1	ST	8		5990	106	13.4	CL		- - -	FILL, lean clay, very stiff, light brown, trace fine sand	926.5
2 ST 13 4570 105 22.9						22.9	CL CH		- - -	FILL, lean to fat clay, very stiff, brown	
	PA								5 - - - -	FAT CLAY, very stiff, light brown to gray brown mottled rust and light gray	923.5
3	SS	18	8	*4500		20.6	СН		- - 10 –	10.0	919. <u>0</u>
* Cal	ibrated	Pene	trometer	** F	Rock Str	ength ir	n psi			BOTTOM OF BORING	
							oximat	te bound	dary line	es between soil and rock types. In-situ the transition may be gradual.	
				SERVA1	TIONS)		_		BORING STARTED 12-18-14	
<u>Ā</u>	Dry							3E		BORING COMPLETED 12-18-14	
Ţ	Dry	A.B.					Yo	our Source	e for Geot	echnical and Materials Engineering RIG CME-55 DRILLER	MC
	Back	filled	l @ Co	mpletio	on					APPROVED JJZ JOB# D14G	1399

UNIFIED SOIL CLASSIFICATION (ASTM D-2487-98) **GROUP** MATERIAL CRITERIA FOR ASSIGNING SOIL GROUP NAMES SOIL GROUP NAMES & LEGEND **TYPES** SYMBOL Cu>4 AND 1<Cc<3 WELL-GRADED GRAVEL GW **GRAVELS CLEAN GRAVELS** <5% FINES Cu>4 AND 1>Cc>3 GP POORLY-GRADED GRAVEL COARSE-GRAINED SOILS >50% RETAINED ON NO. 200 SIEVE >50% OF COARSE FRACTION RETAINED ON NO 4. SIEVE FINES CLASSIFY AS ML OR CL GM SILTY GRAVEL **GRAVELS WITH FINES** >12% FINES FINES CLASSIFY AS CL OR CH GC CLAYEY GRAVEL SANDS Cu>6 AND 1<Cc<3 SW WELL-GRADED SAND **CLEAN SANDS** <5% FINES POORLY-GRADED SAND SP Cu>6 AND 1>Cc>3 >50% OF COARSE FRACTION PASSES FINES CLASSIFY AS ML OR CL SILTY SAND SM SANDS AND FINES ON NO 4. SIEVE >12% FINES CLAYEY SAND FINES CLASSIFY AS CL OR CH PI>7 AND PLOTS>"A" LINE CL LEAN CLAY SILTS AND CLAYS FINE-GRAINED SOILS >50% PASSES NO. 200 SIEVE **INORGANIC** PI>4 AND PLOTS<"A" LINE ML SILT LIQUID LIMIT<50 **ORGANIC** ORGANIC CLAY OR SILT OL LL (oven dried)/LL (not dried)<0.75 СН **FAT CLAY** PI PLOTS >"A" LINE SILTS AND CLAYS **INORGANIC** PI PLOTS <"A" LINE MH **ELASTIC SILT** LIQUID LIMIT>50 **ORGANIC** LL (oven dried)/LL (not dried)<0.75 ОН ORGANIC CLAY OR SILT 11/11/ HIGHLY ORGANIC SOILS PRIMARILY ORGANIC MATTER, DARK IN COLOR, AND ORGANIC ODOR





BEDROCK PROPERTIES & DESCRIPTIONS

ROCK QUALIT	Y DESIGNATION	BEDDING CHA	RACTERISTICS
DESCRIPTION	RQD (%)	<u>TERM</u>	THICKNESS (inches)
Very Poor	0 - 25	Massive	> 60
Poor	25 - 50	Very Thick Bedded	d 36 - 60
Fair	50 - 75	Thick Bedded	12 - 36
Good	75 - 90	Medium Bedded	4 - 12
Excellent	90 -100	Thin Bedded	1 - 4
		Very Thin Bedded	0.4 - 1
DECREE OF W	EATHEDING	Laminated	< 0.4

Slightly Weathered - Slight decomposition of Parent material in joints and seams. Weathered - Well-developed and decomposed joints and seams Highly Weathered - Rock highly decomposed, may be extreemly broken.

BEDROCK DISCONTINUITIES

Bedding Planes Planes dividing the individual layers, beds or strata of rocks. Fractures in rock, generally more or less vertical to the bedding. Joints Seams Applies to bedding planes with an unspecified degree of weathering.

PENETRATION RESISTANCE (RECORDED AS BLOWS / 0.5 FT)												
SAND & 0	GRAVEL		SILT & CLAY									
RELATIVE DENSITY	BLOWS/FOOT*	CONSISTENCY	BLOWS/FOOT*	COMPRESSIVE STRENGTH (TSF)								
VERY LOOSE	0 - 4	VERY SOFT	0 - 2	0 - 0.25								
LOOSE	4 - 10	SOFT	2 - 4	0.25 - 0.50								
MEDIUM DENSE	10 - 30	MEDIUM STIFF	4 - 8	0.50 - 1.0								
DENSE	30 - 50	STIFF	8 - 15	1.0 - 2.0								
VERY DENSE	OVER 50	VERY STIFF	15 - 30	2.0 - 4.0								
		HARD	OVER 30	OVER 4.0								

NUMBER OF BLOWS OF 140 LB HAMMER FALLING 30 INCHES TO DRIVE A 2 INCH O.D. (1-3/8 INCH I.D.) SPLIT-BARREL SAMPLER THE LAST 12 INCHES OF AN 18-INCH DRIVE (ASTM-1586 STANDARD PENETRATION TEST).



General Notes and Terms

BORING LOG SYMBOLS

SURFACE MATERIALS

COHESIVE SOILS

LARGE GRANULAR SOILS



TOPSOIL



SILT



CLAYEY GRAVEL



FILL MATERIAL



CLAYEY SILT



SILTY GRAVEL



ASPHALTIC CONCRETE



LEAN CLAY



POORLY GRADED GRAVEL



CONCRETE



LEAN TO FAT CLAY



WELL GRADED GRAVEL




GRANULAR BASE





COBBLES & BOULDERS

GRANULAR SOILS





SHALE

BEDROCK UNITS



JOINT OR VOID

WEATHERED BEDROCK



SILTY SAND



FISSILE SHALE



WEATHERED SHALE



FINE SAND



SANDSTONE



WEATHERED SANDSTONE



POORLY GRADED SAND



LIMESTONE



WEATHERED LIMESTONE



WELL GRADED SAND





GRAVELLY SAND



DEPARTMENT OF ADMINISTRATION
OFFICE OF FACILITIES & PROCUREMENT MANAGEMENT
DESIGN & CONSTRUCTION
800 S.W. JACKSON, SUITE 700 TOPEKA, KANSAS 66612
PHONE: 785.296.8899 FAX: 785.296.3456

PROJECT #:
PROJECT TITLE
AGENCY NAME
BUILDING NUMBER(S)

BUILDING NUMBER(S)

BATE IINSERT DATEI. DRAWN BY IINSERT NAMEI

SHEET CONTENT
A-000000
SHEET NO.

SHEET NO.
ORIGINAL CONTRACT
DOCUMENTS

DEPARTMENT OF ADMINISTRATION

OFFICE OF FACILITIES & PROCUREMENT MANAGE

DESIGN & CONSTRUCTION

800 S.W. JACKSON, SUITE 700 TOPEKA, KANSAS 66612

PHONE: 785.296.8899 FAX: 785.296.3456

SHEET CONTENT

A - 000000

SHEET NO. ORIGINAL CONTRACT DOCUMENTS

Ф #

DEPARTMENT OF ADMINISTRATION
OFFICE OF FACILITIES & PROCUREMENT MANAG
DESIGN & CONSTRUCTION
800 S.W. JACKSON, SUITE 700 TOPEKA, KANSAS 66612
PHONE: 785.296.8899 FAX: 785.296.3456

DRAWN BY [INSERT NAME] PROJECT #:
PROJECT TITLE
AGENCY NAME
BUILDING NUMBER(S) DATE],

 \Box

A - 000000

SHEET CONTENT

ORIGINAL CONTRAC DOCUMENTS

SHEET NO.

